



WATER LICENCE INSPECTION FORM

☐ Original
☐ Follow-Up Report

Licensee	Licensee Representative
Hamlet of Chesterfield Inlet	Richard Vah Horne
Licence No. / Expiry	Representative's Title
3BM-CHE1523	Senior Administrative officer
Land / Other Authorizations	Land / Other Authorizations
Date of Inspection	Inspector
28/07/2015	Atuat Shouldice
Activities Inspected	
<input type="checkbox"/> Camp	<input type="checkbox"/> Drilling
<input type="checkbox"/> Roads/Hauling	<input type="checkbox"/> Mining
<input checked="" type="checkbox"/> Other: Water Discharge	<input type="checkbox"/> Construction
	<input type="checkbox"/> Reclamation
	<input checked="" type="checkbox"/> Fuel Storage
	<input checked="" type="checkbox"/> Other:Water use /Deposit of waste

Conditions:	A - Acceptable	C - Concern	U - Unacceptable	NA – Not Applicable	NI – Not Inspected
Water Use	Condition	Comment	Site Conditions	Condition	Comment
Intake/Screen	A		Water Management Structures	A	
Flow Measure. Device	A	1	Culverts / Bridges	A	
Source:	A		Drainage	A	
Water Use:	A		Erosion / Sediment	A	
Recirculation (y /n)	Y		Mitigation Measures	A	
			Reclamation Activities	A	
			Materials Storage	A	
Waste Disposal			Signage	A	
Waste Water	A				
Solid Waste	A		Monitoring		
Hazardous Waste	A		Sample Collection / Analysis	NI	
*The number in the comments field will correspond with specific comments provided below.					
Samples taken by Inspector:			Location(s): Chesterfield Inlet		
<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No					

SECTION 1	<input type="checkbox"/> Comments (s. __)	<input type="checkbox"/> Non-Compliance with Act or Licence (s. __)	<input type="checkbox"/> Action Required (s. __)
A compliance inspection was conducted July 28 th 2015 of Hamlet of Chesterfield Inlet.			
SECTION 2	<input checked="" type="checkbox"/> Comments (s. __)	<input type="checkbox"/> Non-Compliance with Act or Licence (s. __)	<input type="checkbox"/> Action Required (s. __)
A flow meter was installed during the filling on the Water Lagoon; issues with placement of the pump may have not given an accurate reading to find the total amount during recharge of lagoon.			
Inspector requested that all waste oil drums be palletized and capped in order to stop the spreading on contaminates.			
Two Sewage discharge point were inspected, only one is being used because of location and prevailing wind direction. No concerns noted.			
The landfill was inspected; Items in landfill have started to be segregated. Fencing falling in some areas. No concerns noted			
SECTION 3	<input type="checkbox"/> Comments (s. __)	<input type="checkbox"/> Non-Compliance with Act or Licence, (s. __)	<input checked="" type="checkbox"/> Action Required (s. __)
The Hamlet of Chesterfield Inlet have been following the yearly goals of the water licence working compliance group in relation to the use of water and deposit of waste.			
The inspector requests that the drums be Palletized and capped before the next municipal inspection of 2016.			

Licensee or Representative	Inspector's Name
	Atuat Shouldice
Signature	Signature
Date	Date
	03/03/16

Office Use Only: Follow-up report to be issued by Inspector ☐ Yes ☐ No