

Licensee

Hamlet of Kugluktuk

## WATER LICENCE INSPECTION FORM

Licensee Representative

Aaron Shaban

Original
Follow-Up Report

· · ·				Representative's Title						
					amlet Foreman					
Land / Other Authorization	ıs		La	and / Other Au	ithorizations					
Date of Inspection			In	spector						
16 July 2018				aba Pede	rsen					
Activities Inspected			_							
☐ Camp☐ Roads/Hauling	☐ Drilling ☐ Other:	•	Mining	Constru	ction  Municipal Water Lice	Reclamation	☐ Fuel Storage	e		
☐ Kodus/Hauling	Other.			⊠ Other. I	viumcipai water Lici	ense				
Conditions: A - A	Acceptabl	e	C - Concern U - Unac	ceptable	NA – Not A	pplicable	NI – Not In	spected		
Water Use	Condition	Comment	Site Conditions	Condition	Comment	Haz/Mat	Condition	Comment		
	Condition	Comment		Condition	Comment	Management	Condition	comment		
Intake/Screen			Water Management Structures			Storage	С	8		
Flow Measure.	Α	1	Culverts / Bridges			Spills	С	9		
Device										
Source:			Drainage	С	7	Spill Plan				
Water Use:	Α	1	Erosion / Sediment							
Recirculation ( y /n)			Mitigation Measures			Administrative				
			Reclamation Activities			Records	Α	1		
			Materials Storage			Reports	А			
Waste Disposal			Signage	С	3,4,5,6,7&10	Plans				
Waste Water	С	11				Notifications	А	2		
Solid Waste	Α		Monitoring			Other				
Hazardous Waste	С	8	Sample Collection /	Α						
			Analysis							
			•							
k	The num	ber in the	comments field will corre	spond with	specific comme	nts provided belov	v.	1		
Samples taken by Insp			Location(s):	<u>,                                      </u>		•				
Yes No										
SECTION 1	Comme	ente le	Non-Complian	nce with Act	t or Licence (s	)	tion Required	(s )		
SECTION 1 Comments (s) Non-Compliance with Act or Licence (s) Action Required (s) On July 16, 2018 I Inspected the Hamlet of Kugluktuk's Municipal Water License 3BM-KUG1520. I saw the Old Pump House and Raw										
Water Intake, the New Pump House and Raw Water Intake complete System, the Old Treatment Plant, the Mobile Emergency Pump										
Shed, the New Treatment Plant, the Back-Wash Reservoir, the Main Reservoir, the Valve Vault, the Metal Dump Expansion Project,										
the Garbage Dump, the Used Oil Burn Program, the Contaminated Soils Land Farm Area, the Sewage Lagoon, the Buttress Repair								pair		
Project and All Associated Sample Sites under the Water License.										
I was accompanied by	Shah Ala	ım and Za	ach from the GN CGS as w	ell as Aaron	Shaban and Ke	vin Klengenberg fr	om the Hamlet	t of		
Kugluktuk.										
SECTION 2	Commo	ents	Non-Compliar	nce with Act	t or Licence	Ac	tion Required			
1. The Hamlet has used 37,000 Cubic Meters of Water so far this year. 2. The Hamlet is using both the Old and New Water										
Systems simultaneously during the Test Period for the New System. 3. There was No Signage at Sample Station KUG-1A										
below the New Raw Water Intake Pump Shack (Photos 1 & 2), 4. There was no Signage at Sample Station KUG-1B in the Old										
Water Treatment Plant (Photo 3), 5. There was no Signage at Sample Station KUG-1C in the New Water Treatment Plant										
(Photo 5), 6. There was no Signage on the Emergency Pump Shed used as Sample Station KUG-1D (Photo 6), 7. The Hamlet										
(111000 5)) 0.	rnere wa	13 110 31611	466 on the Emergency . w.	inp Silea as			oto 6), 7. The H	lamiet		
		_	ump Expansion Project (Ph	-	•	•	-			
was in the m	iddle of a	Metal Du		noto 7), 8. T	here were still l	ots of Used Oil Dru	ıms and other	Debris		
was in the m inside the Co	iddle of a ntaminat	Metal Due de Soils L	ump Expansion Project (Ph	noto 7), 8. T bage Dump	here were still I (Photo 8), 9. Th	ots of Used Oil Dru e Sewage Lagoon	ıms and other Buttress Repai	Debris r		
was in the m inside the Co Project is cor	iddle of a ntaminat nplete, b	Metal Dued Soils Loud it it is still with the second secon	ump Expansion Project (Pl and Farm area of the Gar	noto 7), 8. T bage Dump (Photo 9), 1	here were still I (Photo 8), 9. Th 0. The Signage f	ots of Used Oil Dru e Sewage Lagoon or Sample Station	ums and other Buttress Repai KUG-3 inside t	Debris r he		
was in the m inside the Co Project is cor Sewage Lago	iddle of a Intaminat Inplete, b In was n	Metal Duted Soils Lout it is still ot at the	ump Expansion Project (Ph and Farm area of the Gar Il leaking at a slower rate (	noto 7), 8. T bage Dump (Photo 9), 1 to 10), 11. I	here were still I (Photo 8), 9. Th 0. The Signage f observed severa	ots of Used Oil Dru e Sewage Lagoon or Sample Station	ums and other Buttress Repai KUG-3 inside t	Debris r he		
was in the m inside the Co Project is cor Sewage Lago	iddle of a Intaminat Inplete, b In was n	Metal Dured Soils Lout it is still ot at the gallon D	ump Expansion Project (Phand Farm area of the Garll leaking at a slower rate (actual Sample Point (Phot	noto 7), 8. T bage Dump (Photo 9), 1 to 10), 11. I Debris (Phot	here were still I (Photo 8), 9. Th 0. The Signage f observed severa os 11 & 12).	ots of Used Oil Drue Sewage Lagoon or Sample Station al Items floating w	ums and other Buttress Repai KUG-3 inside t	Debris r he ge		
was in the m inside the Co Project is cor Sewage Lago Lagoon, inclu SECTION 3	iddle of a ntaminat nplete, b on was n iding a 45	Metal Dured Soils Lut it is still ot at the gallon Dents	ump Expansion Project (Phand Farm area of the Garll leaking at a slower rate (actual Sample Point (Photrum, 2 Logs and Various D	noto 7), 8. T bage Dump (Photo 9), 1 to 10), 11. I Debris (Photo nce with Act	here were still I (Photo 8), 9. Th 0. The Signage f observed severa os 11 & 12). t or Licence	ots of Used Oil Drue Sewage Lagoon or Sample Station al Items floating wi	ums and other Buttress Repai KUG-3 inside t ithin the Sewag	Debris r he ge		
was in the m inside the Co Project is cor Sewage Lago Lagoon, incluSECTION 3	iddle of a ntaminat mplete, be on was nedding a 45 Commons well wit	Metal Dured Soils Lut it is still ot at the gallon Dents	ump Expansion Project (Phand Farm area of the Garll leaking at a slower rate (actual Sample Point (Photrum, 2 Logs and Various Darbon Non-Compliar	noto 7), 8. T bage Dump (Photo 9), 1 to 10), 11. I o bebris (Photo ce with Act Cubic Meter	here were still I (Photo 8), 9. Th 0. The Signage f observed severa os 11 & 12). t or Licence	ots of Used Oil Drue Sewage Lagoon or Sample Station al Items floating with the Items and Items and Items and Items floating with the Items and It	ums and other Buttress Repai KUG-3 inside t ithin the Sewag ction Required	Debris r he ge the Old		
was in the m inside the Co Project is cor Sewage Lago Lagoon, inclu SECTION 3  1. The Hamlet i Water Syster	iddle of a ntaminat mplete, be on was neding a 45 Commons well with m stops b	Metal Dured Soils Lut it is still ot at the significant Durents thin their eing used	ump Expansion Project (Phand Farm area of the Garl leaking at a slower rate (actual Sample Point (Photrum, 2 Logs and Various Darbon Pontrum, 2 Logs and Various Darbon Project (Phand Park Pontrum)	noto 7), 8. The bage Dump (Photo 9), 1 to 10), 11. In the bebris (Photo ace with Act Cubic Meter be installed	here were still I (Photo 8), 9. Th 0. The Signage f observed severa os 11 & 12). t or Licence rs per year. 2. P at Sample Station	ots of Used Oil Drue Sewage Lagoon or Sample Station al Items floating with the Iron KUG-1A. 4. Pro	ums and other Buttress Repai KUG-3 inside t ithin the Sewag ction Required aspector when oer Signage mu	Debris r he ge the Old ust be		
was in the m inside the Co Project is cor Sewage Lago Lagoon, inclu SECTION 3  1. The Hamlet i Water Syster installed at S	iddle of a ntaminat mplete, be on was ned ing a 45 Commons well with m stops be ample Sta	Metal Dured Soils Lut it is still ot at the gallon Dents hin their eing used ation KUG	ump Expansion Project (Phand Farm area of the Garll leaking at a slower rate (actual Sample Point (Photrum, 2 Logs and Various Darbon Point Point (Photrum, 2 Logs and Various Darbon Point Point (Photrum, 2 Logs and Various Darbon Point Point Point (Photrum, 2 Logs and Various Darbon Point Poin	noto 7), 8. The bage Dump (Photo 9), 1 foo 10), 11. If the bedris (Photo ace with Act Cubic Meter be installed aust be installed	here were still I (Photo 8), 9. Th 0. The Signage f observed severa os 11 & 12). t or Licence rs per year. 2. P at Sample Station	e Sewage Lagoon or Sample Station al Items floating will lease advise the Iron KUG-1A. 4. Propagation KUG-1C. 6.	ums and other Buttress Repai KUG-3 inside t ithin the Sewag  ction Required aspector when per Signage mu	Debris r he ge the Old ust be e must		



relocated to a more suitable spot after the Hamlet is finished with the Metal Dump Expansion Project. The Hamlet must contact the Inspector when they are ready to select the new Sample location. 8. All Drums and other Debris must be removed from the Contaminated Soils Land Farm Area within the Garbage Dump to allow for proper usage of this facility. 9. The Hamlet and the GN must continue to monitor the leak under the Sewage Lagoon Buttress and figure out a permanent solution to this ongoing concern. 10. The Signage for Sample Station KUG-3 must be relocated to above the actual Sample Point. 11. All foreign Items floating in the Sewage Lagoon must be removed.

Licensee or Representative	Inspector's Name		
	Baba Pedersen		
Signature	Signature		
	Signed Original on File		
Date	Date		
	2019 Jan 18		

Office Use Only:	Follow-up report to be issued by Inspector	☐ Yes ☒ No	
cc.	CIRNAC, Manager Field operations, Iqaluit, <u>Justin.hack@canada.ca</u>		
	Nunavut Water Board, Manager of Licensing, Gjoa Haven, licensing@n	wb-oen.ca	
	Gov't of Nunavut, Municipal Engineer, Cambridge Bay, salam@	gov.nu.ca	



## PHOTO LOG



































