

Licensee

WATER LICENCE INSPECTION FORM

Licensee Representative

Original
Follow-Up Report

Same Continue Same Sam						
Date of Inspection 2019 July 30 Baba Pedersen Cardivilue Inspected Drilling Other: Mining Construction Reclamation Fuel Storage						
Date of Inspection						
Baba Pedersen						
Activities Inspected Roads/Haulling						
Camp						
Conditions: A - Acceptable C - Concern U - Unacceptable NA - Not Applicable NI - Not Inspected Water Use Site Conditions Site Conditions Condi						
Water Use Comments Site Condition Comments Haz/Mat Management Condition Comments Comments Haz/Mat Management Comments Comm						
Water Use						
Intake/Screen Water Management Structures C 48.5 Storage U 7 Flow Measure. Device A Culverts / Bridges Spills Source: Drainage Spill Plan Water Use: Erosion / Sediment Recirculation (y /n) Mitigation Measures C 6 Administrative Recirculation (y /n) Mitigation Measures C 6 Administrative Recirculation Materials Storage Records A Reports A Waste Disposal Signage C 1,28.3 Plans Waste Water C 48.5 Notifications Solid Waste A Monitoring Other Hazardous Waste C 8 Sample Collection / Analysis A Authorization Display C 9 *The number in the comments field will correspond with specific comments provided below. Samples taken by Inspected the Hamlet of Kugluktuk's Municipal Water License 3BM-KUG1520. I was accompanied by Isa Kalluk from the Hamlet of Kugluktuk and Shah Alam from the GN CGS. SECTION 1 Comments Non-Compliance with Act or Licence Action Required We saw 1. Signage for Sample Station KUG-1A (Photo 1), 2. The indoor Sample Station KUG-1C (Photo 2), 3. The Emergency Water Intake Pump Shack (Photo 3), at the Sewage Lagoon we saw 4. The ongoing Leak under the Buttress (Photo 4), 5. The extremely Low Level within the Lagoon (Photo 5), 6. Floating Debris and Wood inside the Lagoon (Photos 6 & 7), 7. The Contaminated Soil Land Farm Area (Photo 8), 8. The used Battery Pile in the Land Farm Area (also Photo 8), and 9. I asked to see a copy of this Water License 3BM-KUG1520. SECTION 2 Comments Non-Compliance with Act or Licence Action Required 1. The Signage for Sample Station KUG-1A must be moved to a more visible location closer to the actual Sample Point is 3. Signage to Identify the Sample Station KUG-1D must be attached to the outside of the green Emergency Water Intake Pump Shack. If/when this is ever used, the exact GPS Coordinates must be provided to the Inspector as to where it was						
Flow Measure. Device A Culverts / Bridges Spills Source: Drainage Spill Plan Water Use: Erosion / Sediment Recirculation (y / n) Mitigation Measures C 6 Administrative Recirculation Records A Records A Records A Materials Storage Signage C 1,2&3 Plans Waste Disposal Signage C 1,2&3 Plans Notifications Solid Waste A Monitoring Other Hazardous Waste C 8 Sample Collection / Analysis A Authorization Display C 9 *The number in the comments field will correspond with specific comments provided below. Samples taken by Inspector: Location(s): SECTION 1 Comments (S_ Non-Compliance with Act or Licence (S_) Action Required (S_ On July 30, 2019 I Inspected the Hamlet of Kugluktuk's Municipal Water License 3BM-KUG1520. I was accompanied by Isa Kalluk from the Hamlet of Kugluktuk's Municipal Water License 3BM-KUG1520. I was accompanied by Isa Kalluk from the Hamlet of Kugluktuk's Municipal Water License 3BM-KUG1520. I was accompanied by Isa Kalluk from the Hamlet of Kugluktuk's Municipal Water License 3BM-KUG1520. I was accompanied by Isa Kalluk from the Hamlet of Kugluktuk's Municipal Water License 3BM-KUG1520. I was accompanied by Isa Kalluk from the Hamlet of Kugluktuk's and Shah Alam from the GN CGS. SECTION 2 Comments Non-Compliance with Act or Licence Action Required We saw 1. Signage for Sample Station KUG-1A (Photo 1), 2. The indoor Sample Station KUG-1C (Photo 2), 3. The Emergency Water Intake Pump Shack (Photo 3), at the Sewage Lagoon we saw 4. The ongoing Leak under the Buttress (Photo 4), 5. The extremely Low Level within the Lagoon (Photos 6 & 7), 7. The Contaminated Soil Land Farm Area (Photo 8), 8. The used Battery Pile in the Land Farm Area (also Photo 8), and 9. I asked to see a copy of this Water License 3BM-KUG1520. SECTION 3 Comments Non-Compliance with Act or Licence Action Required 1. The Signage for Sample Station KUG-1A must be moved to a more visible location closer to the actual Sample Point is 3. Signage to Identify the Sample Station KUG-1D must be attached to the outside of the gr						
Source: Drainage Spill Plan						
Water Use: Recirculation (y /n) Mitigation Measures C 6 Administrative Reclamation Activities Records A Materials Storage Reports A Waste Disposal Waste Water C 4&5 Solid Waste Hazardous Waste C 8 Sample Collection / Analysis A Authorization Display C 9 *The number in the comments field will correspond with specific comments provided below. Samples taken by Inspector: Ves No Non-Compliance with Act or Licence Action Required (s_) On July 30, 2019 Inspected the Hamlet of Kugluktuk's Municipal Water License 3BM-KUG1520. I was accompanied by Isa Kalluk from the Hamlet of Kugluktuk and Shah Alam from the GN CGS. SECTION 1						
Recirculation (y /n)						
Reclamation Activities Records A Materials Storage Reports A Waste Disposal Signage C 1,283 Plans Waste Water C 4&5 Solid Waste A Monitoring Hazardous Waste C 8 Sample Collection / Analysis A Authorization Display C 9 *The number in the comments field will correspond with specific comments provided below. Samples taken by Inspector: Wes No Non-Compliance with Act or Licence (s_) Action Required (s_) On July 30, 2019 I Inspected the Hamlet of Kugluktuk's Municipal Water License 3BM-KUG1520. I was accompanied by Isa Kalluk from the Hamlet of Kugluktuk and Shah Alam from the GN CGS. Non-Compliance with Act or Licence Action Required We saw 1. Signage for Sample Station KUG-1A (Photo 1), 2. The indoor Sample Station KUG-1C (Photo 2), 3. The Emergency Water Intake Pump Shack (Photo 3), at the Sewage Lagoon we saw 4. The ongoing Leak under the Buttress (Photo 4), 5. The extremely Low Level within the Lagoon (Photo 5), 6. Floating Debris and Wood inside the Lagoon (Photos 6 & 7), 7. The Contaminated Soil Land Farm Area (Photo 8), 8. The used Battery Pile in the Land Farm Area (also Photo 8), and 9. I asked to see a copy of this Water License 3BM-KUG1520. SECTION 3						
Waste Water C 485 Notifications Solid Waste Water C 485 Notifications Solid Waste A Monitoring Other Hazardous Waste C 8 Sample Collection / Analysis A Authorization Display C 9 *The number in the comments field will correspond with specific comments provided below. Samples taken by Inspector: Location(s): SECTION 1 Comments (s) Non-Compliance with Act or Licence (s) Action Required (s) On July 30, 2019 I Inspected the Hamlet of Kugluktuk's Municipal Water License 3BM-KUG1520. I was accompanied by Isa Kalluk from the Hamlet of Kugluktuk and Shah Alam from the GN CGS. SECTION 2 Comments Non-Compliance with Act or Licence Action Required We saw 1. Signage for Sample Station KUG-1A (Photo 1), 2. The indoor Sample Station KUG-1C (Photo 2), 3. The Emergency Water Intake Pump Shack (Photo 3), at the Sewage Lagoon we saw 4. The ongoing Leak under the Buttress (Photo 4), 5. The extremely Low Level within the Lagoon (Photo 5), 6. Floating Debris and Wood inside the Lagoon (Photos 6 & 7), 7. The Contaminated Soil Land Farm Area (Photo 8), 8. The used Battery Pile in the Land Farm Area (also Photo 8), and 9. I asked to see a copy of this Water License 3BM-KUG1520. SECTION 3 Comments Non-Compliance with Act or Licence Action Required 1. The Signage for Sample Station KUG-1A must be moved to a more visible location closer to the actual Sample Point. 2. The Signage for Sample Station KUG-1C must be Permanent and easily readable that identifies exactly where the Sample Point is. 3. Signage to Identify the Sample Station KUG-1D must be attached to the outside of the green Emergency Water Intake Pump Shack. If/when this is ever used, the exact GPS Coordinates must be provided to the Inspector as to where it was						
Waste Water C 485 Notifications Solid Waste Water C 485 Notifications Solid Waste A Monitoring Other Hazardous Waste C 8 Sample Collection / Analysis A Authorization Display C 9 *The number in the comments field will correspond with specific comments provided below. Samples taken by Inspector: Location(s): SECTION 1 Comments (s) Non-Compliance with Act or Licence (s) Action Required (s) On July 30, 2019 I Inspected the Hamlet of Kugluktuk's Municipal Water License 3BM-KUG1520. I was accompanied by Isa Kalluk from the Hamlet of Kugluktuk and Shah Alam from the GN CGS. SECTION 2 Comments Non-Compliance with Act or Licence Action Required We saw 1. Signage for Sample Station KUG-1A (Photo 1), 2. The indoor Sample Station KUG-1C (Photo 2), 3. The Emergency Water Intake Pump Shack (Photo 3), at the Sewage Lagoon we saw 4. The ongoing Leak under the Buttress (Photo 4), 5. The extremely Low Level within the Lagoon (Photo 5), 6. Floating Debris and Wood inside the Lagoon (Photos 6 & 7), 7. The Contaminated Soil Land Farm Area (Photo 8), 8. The used Battery Pile in the Land Farm Area (also Photo 8), and 9. I asked to see a copy of this Water License 3BM-KUG1520. SECTION 3 Comments Non-Compliance with Act or Licence Action Required 1. The Signage for Sample Station KUG-1A must be moved to a more visible location closer to the actual Sample Point. 2. The Signage for Sample Station KUG-1C must be Permanent and easily readable that identifies exactly where the Sample Point is. 3. Signage to Identify the Sample Station KUG-1D must be attached to the outside of the green Emergency Water Intake Pump Shack. If/when this is ever used, the exact GPS Coordinates must be provided to the Inspector as to where it was						
Waste Water C 4&5						
*The number in the comments field will correspond with specific comments provided below. *The number in the comments field will correspond with specific comments provided below. Samples taken by Inspector: Yes No Non-Compliance with Act or Licence (s) Action Required (s) On July 30, 2019 I Inspected the Hamlet of Kugluktuk's Municipal Water License 3BM-KUG1520. I was accompanied by Isa Kalluk from the Hamlet of Kugluktuk and Shah Alam from the GN CGS. Section 2						
*The number in the comments field will correspond with specific comments provided below. *The number in the comments field will correspond with specific comments provided below. Samples taken by Inspector: Yes No Non-Compliance with Act or Licence (s) Action Required (s) On July 30, 2019 I Inspected the Hamlet of Kugluktuk's Municipal Water License 3BM-KUG1520. I was accompanied by Isa Kalluk from the Hamlet of Kugluktuk and Shah Alam from the GN CGS. Non-Compliance with Act or Licence Action Required						
*The number in the comments field will correspond with specific comments provided below. Samples taken by Inspector: Yes No Non-Compliance with Act or Licence (s Action Required (s) On July 30, 2019 Inspected the Hamlet of Kugluktuk's Municipal Water License 3BM-KUG1520. I was accompanied by Isa Kalluk from the Hamlet of Kugluktuk and Shah Alam from the GN CGS. Non-Compliance with Act or Licence						
Samples taken by Inspector: Yes No Non-Compliance with Act or Licence (s) Action Required (s) On July 30, 2019 I Inspected the Hamlet of Kugluktuk's Municipal Water License 3BM-KUG1520. I was accompanied by Isa Kalluk from the Hamlet of Kugluktuk and Shah Alam from the GN CGS. SECTION 2 Comments Non-Compliance with Act or Licence Action Required We saw 1. Signage for Sample Station KUG-1A (Photo 1), 2. The indoor Sample Station KUG-1C (Photo 2), 3. The Emergency Water Intake Pump Shack (Photo 3), at the Sewage Lagoon we saw 4. The ongoing Leak under the Buttress (Photo 4), 5. The extremely Low Level within the Lagoon (Photo 5), 6. Floating Debris and Wood inside the Lagoon (Photos 6 & 7), 7. The Contaminated Soil Land Farm Area (Photo 8), 8. The used Battery Pile in the Land Farm Area (also Photo 8), and 9. I asked to see a copy of this Water License 3BM-KUG1520. SECTION 3 Comments Non-Compliance with Act or Licence Action Required 1. The Signage for Sample Station KUG-1A must be moved to a more visible location closer to the actual Sample Point. 2. The Signage for Sample Station KUG-1C must be Permanent and easily readable that identifies exactly where the Sample Point is. 3. Signage to Identify the Sample Station KUG-1D must be attached to the outside of the green Emergency Water Intake Pump Shack. If/when this is ever used, the exact GPS Coordinates must be provided to the Inspector as to where it was						
Samples taken by Inspector: Yes No Non-Compliance with Act or Licence (s) Action Required (s) On July 30, 2019 I Inspected the Hamlet of Kugluktuk's Municipal Water License 3BM-KUG1520. I was accompanied by Isa Kalluk from the Hamlet of Kugluktuk and Shah Alam from the GN CGS. SECTION 2 Comments Non-Compliance with Act or Licence Action Required We saw 1. Signage for Sample Station KUG-1A (Photo 1), 2. The indoor Sample Station KUG-1C (Photo 2), 3. The Emergency Water Intake Pump Shack (Photo 3), at the Sewage Lagoon we saw 4. The ongoing Leak under the Buttress (Photo 4), 5. The extremely Low Level within the Lagoon (Photo 5), 6. Floating Debris and Wood inside the Lagoon (Photos 6 & 7), 7. The Contaminated Soil Land Farm Area (Photo 8), 8. The used Battery Pile in the Land Farm Area (also Photo 8), and 9. I asked to see a copy of this Water License 3BM-KUG1520. SECTION 3 Comments Non-Compliance with Act or Licence Action Required 1. The Signage for Sample Station KUG-1A must be moved to a more visible location closer to the actual Sample Point. 2. The Signage for Sample Station KUG-1C must be Permanent and easily readable that identifies exactly where the Sample Point is. 3. Signage to Identify the Sample Station KUG-1D must be attached to the outside of the green Emergency Water Intake Pump Shack. If/when this is ever used, the exact GPS Coordinates must be provided to the Inspector as to where it was						
SECTION 1						
SECTION 1						
On July 30, 2019 I Inspected the Hamlet of Kugluktuk's Municipal Water License 3BM-KUG1520. I was accompanied by Isa Kalluk from the Hamlet of Kugluktuk and Shah Alam from the GN CGS. SECTION 2 Comments Non-Compliance with Act or Licence Action Required We saw 1. Signage for Sample Station KUG-1A (Photo 1), 2. The indoor Sample Station KUG-1C (Photo 2), 3. The Emergency Water Intake Pump Shack (Photo 3), at the Sewage Lagoon we saw 4. The ongoing Leak under the Buttress (Photo 4), 5. The extremely Low Level within the Lagoon (Photo 5), 6. Floating Debris and Wood inside the Lagoon (Photos 6 & 7), 7. The Contaminated Soil Land Farm Area (Photo 8), 8. The used Battery Pile in the Land Farm Area (also Photo 8), and 9. I asked to see a copy of this Water License 3BM-KUG1520. SECTION 3 Comments Non-Compliance with Act or Licence Action Required 1. The Signage for Sample Station KUG-1A must be moved to a more visible location closer to the actual Sample Point. 2. The Signage for Sample Station KUG-1C must be Permanent and easily readable that identifies exactly where the Sample Point is. 3. Signage to Identify the Sample Station KUG-1D must be attached to the outside of the green Emergency Water Intake Pump Shack. If/when this is ever used, the exact GPS Coordinates must be provided to the Inspector as to where it was						
On July 30, 2019 I Inspected the Hamlet of Kugluktuk's Municipal Water License 3BM-KUG1520. I was accompanied by Isa Kalluk from the Hamlet of Kugluktuk and Shah Alam from the GN CGS. SECTION 2 Comments Non-Compliance with Act or Licence Action Required We saw 1. Signage for Sample Station KUG-1A (Photo 1), 2. The indoor Sample Station KUG-1C (Photo 2), 3. The Emergency Water Intake Pump Shack (Photo 3), at the Sewage Lagoon we saw 4. The ongoing Leak under the Buttress (Photo 4), 5. The extremely Low Level within the Lagoon (Photo 5), 6. Floating Debris and Wood inside the Lagoon (Photos 6 & 7), 7. The Contaminated Soil Land Farm Area (Photo 8), 8. The used Battery Pile in the Land Farm Area (also Photo 8), and 9. I asked to see a copy of this Water License 3BM-KUG1520. SECTION 3 Comments Non-Compliance with Act or Licence Action Required 1. The Signage for Sample Station KUG-1A must be moved to a more visible location closer to the actual Sample Point. 2. The Signage for Sample Station KUG-1C must be Permanent and easily readable that identifies exactly where the Sample Point is. 3. Signage to Identify the Sample Station KUG-1D must be attached to the outside of the green Emergency Water Intake Pump Shack. If/when this is ever used, the exact GPS Coordinates must be provided to the Inspector as to where it was						
From the Hamlet of Kugluktuk and Shah Alam from the GN CGS. SECTION 2 Comments Non-Compliance with Act or Licence Action Required We saw 1. Signage for Sample Station KUG-1A (Photo 1), 2. The indoor Sample Station KUG-1C (Photo 2), 3. The Emergency Water Intake Pump Shack (Photo 3), at the Sewage Lagoon we saw 4. The ongoing Leak under the Buttress (Photo 4), 5. The extremely Low Level within the Lagoon (Photo 5), 6. Floating Debris and Wood inside the Lagoon (Photos 6 & 7), 7. The Contaminated Soil Land Farm Area (Photo 8), 8. The used Battery Pile in the Land Farm Area (also Photo 8), and 9. I asked to see a copy of this Water License 3BM-KUG1520. SECTION 3 Comments Non-Compliance with Act or Licence Action Required 1. The Signage for Sample Station KUG-1A must be moved to a more visible location closer to the actual Sample Point. 2. The Signage for Sample Station KUG-1C must be Permanent and easily readable that identifies exactly where the Sample Point is. 3. Signage to Identify the Sample Station KUG-1D must be attached to the outside of the green Emergency Water Intake Pump Shack. If/when this is ever used, the exact GPS Coordinates must be provided to the Inspector as to where it was						
We saw 1. Signage for Sample Station KUG-1A (Photo 1), 2. The indoor Sample Station KUG-1C (Photo 2), 3. The Emergency Water Intake Pump Shack (Photo 3), at the Sewage Lagoon we saw 4. The ongoing Leak under the Buttress (Photo 4), 5. The extremely Low Level within the Lagoon (Photo 5), 6. Floating Debris and Wood inside the Lagoon (Photos 6 & 7), 7. The Contaminated Soil Land Farm Area (Photo 8), 8. The used Battery Pile in the Land Farm Area (also Photo 8), and 9. I asked to see a copy of this Water License 3BM-KUG1520. SECTION 3						
Intake Pump Shack (Photo 3), at the Sewage Lagoon we saw 4. The ongoing Leak under the Buttress (Photo 4), 5. The extremely Low Level within the Lagoon (Photo 5), 6. Floating Debris and Wood inside the Lagoon (Photos 6 & 7), 7. The Contaminated Soil Land Farm Area (Photo 8), 8. The used Battery Pile in the Land Farm Area (also Photo 8), and 9. I asked to see a copy of this Water License 3BM-KUG1520. SECTION 3						
Level within the Lagoon (Photo 5), 6. Floating Debris and Wood inside the Lagoon (Photos 6 & 7), 7. The Contaminated Soil Land Farm Area (Photo 8), 8. The used Battery Pile in the Land Farm Area (also Photo 8), and 9. I asked to see a copy of this Water License 3BM-KUG1520. SECTION 3						
Farm Area (Photo 8), 8. The used Battery Pile in the Land Farm Area (also Photo 8), and 9. I asked to see a copy of this Water License 3BM-KUG1520. SECTION 3 Comments Non-Compliance with Act or Licence Action Required 1. The Signage for Sample Station KUG-1A must be moved to a more visible location closer to the actual Sample Point. 2. The Signage for Sample Station KUG-1C must be Permanent and easily readable that identifies exactly where the Sample Point is. 3. Signage to Identify the Sample Station KUG-1D must be attached to the outside of the green Emergency Water Intake Pump Shack. If/when this is ever used, the exact GPS Coordinates must be provided to the Inspector as to where it was						
3BM-KUG1520. SECTION 3 Comments Non-Compliance with Act or Licence Action Required 1. The Signage for Sample Station KUG-1A must be moved to a more visible location closer to the actual Sample Point. 2. The Signage for Sample Station KUG-1C must be Permanent and easily readable that identifies exactly where the Sample Point is. 3. Signage to Identify the Sample Station KUG-1D must be attached to the outside of the green Emergency Water Intake Pump Shack. If/when this is ever used, the exact GPS Coordinates must be provided to the Inspector as to where it was						
1. The Signage for Sample Station KUG-1A must be moved to a more visible location closer to the actual Sample Point. 2. The Signage for Sample Station KUG-1C must be Permanent and easily readable that identifies exactly where the Sample Point is. 3. Signage to Identify the Sample Station KUG-1D must be attached to the outside of the green Emergency Water Intake Pump Shack. If/when this is ever used, the exact GPS Coordinates must be provided to the Inspector as to where it was						
 The Signage for Sample Station KUG-1A must be moved to a more visible location closer to the actual Sample Point. 2. The Signage for Sample Station KUG-1C must be Permanent and easily readable that identifies exactly where the Sample Point is. 3. Signage to Identify the Sample Station KUG-1D must be attached to the outside of the green Emergency Water Intake Pump Shack. If/when this is ever used, the exact GPS Coordinates must be provided to the Inspector as to where it was 						
Signage for Sample Station KUG-1C must be Permanent and easily readable that identifies exactly where the Sample Point is. 3. Signage to Identify the Sample Station KUG-1D must be attached to the outside of the green Emergency Water Intake Pump Shack. If/when this is ever used, the exact GPS Coordinates must be provided to the Inspector as to where it was						
is. 3. Signage to Identify the Sample Station KUG-1D must be attached to the outside of the green Emergency Water Intake Pump Shack. If/when this is ever used, the exact GPS Coordinates must be provided to the Inspector as to where it was						
Pump Shack. If/when this is ever used, the exact GPS Coordinates must be provided to the Inspector as to where it was						
located during use. 4. The Hamlet and the GN must work together to come up with a permanent solution to the ongoing						
leak in the lined Berm under the Buttress area on the North Side. 5. The very low level of fluid within the Lagoon BEFORE						
any Decant has taken place is an ongoing concern related to the Leakage. 6. The 2 piles of floating Debris and Wood Beams						
must be removed from the Lagoon to prevent damage to the Liner. 7. The Contaminated Soil Land Farm Area must be						
cleaned out of all items that should not be there. This area is ONLY for Contaminated Soil and nothing else. This has						
brought to the attention of the Hamlet by the Inspector numerous times and MUST be dealt with before the summer of						
brought to the attention of the Hamlet by the Inspector numerous times and MUST be dealt with before the summer of 2020 Inspection or the Inspector will have no choice but to pursue further Enforcement Action. 8. All used Batteries are to						
brought to the attention of the Hamlet by the Inspector numerous times and MUST be dealt with before the summer of 2020 Inspection or the Inspector will have no choice but to pursue further Enforcement Action. 8. All used Batteries are to be stored in Wooden Crates lined with Plastic Poly for safe keeping until they are able to be shipped south for proper						
brought to the attention of the Hamlet by the Inspector numerous times and MUST be dealt with before the summer of 2020 Inspection or the Inspector will have no choice but to pursue further Enforcement Action. 8. All used Batteries are to be stored in Wooden Crates lined with Plastic Poly for safe keeping until they are able to be shipped south for proper disposal. 9. Hard Copies of Water License 3BM-KUG1520 MUST be available to the key people responsible for ensuring all						
brought to the attention of the Hamlet by the Inspector numerous times and MUST be dealt with before the summer of 2020 Inspection or the Inspector will have no choice but to pursue further Enforcement Action. 8. All used Batteries are to be stored in Wooden Crates lined with Plastic Poly for safe keeping until they are able to be shipped south for proper						





Licensee or Representative	Inspector's Name
	Baba Pedersen
Signature Signature	
	Signed Original on File
Date	Date
	2019 Nov 29


Office Use Only:	Follow-up report to be issued by Inspector	☐ Yes ☑ No	
cc.	CIRNAC, Manager Field Operations, Iqaluit, justin.hack@canada.ca		
	Nunavut Water Board, Manager of Licensing, Gjoa Haven, <u>licensing@nwb-oen.ca</u>		
	Gov't of Nunavut, Municipal Engineer, Cambridge Bay, salam@gov	<u>/.nu.ca</u>	



PHOTO LOG









Description: The Signage for Sample Station KUG-1C needs to be Permanent, Very Visible and Easy to Read





Description: Signage for Sample Station KUG-1D needs to be attached to the outside of the Green Emergency Water Intake Pump Shack















