



Licensee or Representative Hamlet of Kugluktuk	Inspector's Name Isaiah James Bolt
Signature 	Signature
Date NOV 20 2024	Date

Office Use Only: Follow-up report to be issued by Inspector

☒ Yes ☐ No

PHOTO LOG

Date: Thursday, September 19, 2024	License Number: 3BM-KUG2030	Camera/Model: Olympus Tough TG-6	Inspector Isaiah James Bolt
Photo No. Photo #1	Lat/Long (DD.MM.SS.SS, NAD83) Click or tap here to enter text.		



Description:

Blue Arrow shows pooling area and sediment build up potentially caused by Sewage water that has not been able to clear the distance from the concrete block to the slope of the liner and is migrating along the bank into the pooling area. Yellow arrow shows erosion caused by this effect. The fence in the photo is also effected as this whole area is being washed out by the pooling water and migrating under the liner.