

Photo 7 CRS-2 crossing west aspect with installed culvert and upstream pond flow pattern; upstream water body is confirmed fish-bearing pond.



Photo 8 End of constructed access road with existing ATV trail near Km 2.9 of the proposed route; north aspect.



Photo 9 Muddy and rutted ATV trail along proposed access road route, near Km 3.0; southwest aspect.




Photo 10 Stream flow pattern upstream of CRS-3 with existing ATV trail and proposed access road route on the left side of the photo, note bedrock ridges on east and west; southeast aspect.

Page B-7 January 2009



Photo 11 East aspect of impacted stream banks at existing ATV trail stream crossing; site is also CRS-3 crossing of the proposed access road at Km 3.5; note numerous inuksuit present.



Photo 12 Confirmed fish-bearing lake and existing ATV trail near Km 4.0 of the proposed access road route; southeast aspect.

Page B-8




Photo 13 Stream flow pattern upstream of CRS-3 with existing ATV trail and proposed access road route on the left side of the photo; southeast aspect.



Photo 14 East aspect of impacted stream banks at existing ATV trail stream crossing; site is also CRS-3 crossing of the proposed access road at Km 3.5.

Page B-9 January 2009