

NUNAVUT SPILL REPORT

24 Hour Report Line 76-2 26-5
Phone/Fax: (867) 920-0130
Fax: (867) 873-8924

June 26/01

Hamlet of Pond Inlet

Crude oil



Possible hazards to environment,
fish or wild life

There were 45 gls. drums that were
put in metal waste area of the dump
and old trucks were dumped on top
of the drums which caused the
spill. The drums might not have been
properly closed, or crushed open
from ~~weight~~ weight of the trucks.

FOR SPILL LINE USE ONLY

DATE OF SPILL: 06/26/01

TIME OF SPILL: 14:00

LOCATION OF SPILL: Pond Inlet

TYPE OF SPILL: Crude Oil

AMOUNT OF SPILL: 45 gals.

CAUSE OF SPILL: Improperly closed drums

WIND DIRECTION: N

WIND SPEED: 10 km/h

WATER TEMPERATURE: 10°C

AIR TEMPERATURE: 10°C

SEA TEMPERATURE: 10°C

ICE TEMPERATURE: 10°C

ICE TYPE: None

ICE DIRECTION: None

ICE SPEED: None

ICE TYPE: None

ICE DIRECTION: None

ICE SPEED: None

ICE TYPE: None

ICE DIRECTION: None

ICE SPEED: None

ICE TYPE: None

ICE DIRECTION: None

ICE SPEED: None

ICE TYPE: None

ICE DIRECTION: None

ICE SPEED: None

ICE TYPE: None

ICE DIRECTION: None

ICE SPEED: None

ICE TYPE: None

ICE DIRECTION: None

ICE SPEED: None

Mona Katsak

Water & Sewer Clerk Hamlet of Pond Inlet

867 899 8934

INTERNAL	
PC	9/
LA	
OM	
TA	
BS	
ED	
CEO	
BRD	