



WATER LICENCE INSPECTION FORM

☒ Original

☐ Follow-Up Report

| | |
|--|-------------------------------|
| Licensee | Licensee Representative |
| Hamlet of Rankin Inlet | Darren Flynn |
| Licence No. / Expiry | Representative's Title |
| 3BM-RAN2025/ Dec 20,2025 | Senior Administrative Officer |
| Date of Inspection | Inspector |
| 6/24/2021 | Atuat SHOULDICE |
| Activities Inspected | |
| <div><input type="checkbox"/> Camp<input type="checkbox"/> Drilling<input type="checkbox"/> Mining<input type="checkbox"/> Construction<input type="checkbox"/> Reclamation<input type="checkbox"/> Fuel Storage</div> <div><input type="checkbox"/> Roads/Hauling<input checked="" type="checkbox"/> Other: Landfill<input type="checkbox"/> Other:</div> | |

| | | | |
|---|--|---|--|
| SECTION 1 | <input checked="" type="checkbox"/> Comments | <input type="checkbox"/> Non-Compliance with Act or Licence | <input type="checkbox"/> Action Required |
| <p>On June 24th , 2021 a water license Inspection was conducted of 3BM-RAN2025, issued to the Hamlet of Rankin Inlet, by the Crown Indigenous Relations and Northern Affairs Canada, Water Resource Officer Atuat Shouldice and Jakob Voisey. Darren Flynn (SAO) and Troy Aksalnik (Foremen) accompanied the Inspectors during inspection.</p> <p>Observations</p> <div><div>1. The 2020 annual report is available for review on the Nunavut Water Board FTP website.</div><div>2. The Landfill is equipped with signage.</div><div>3. The Hamlet is in the process of hiring a Landfill attendant to help organize and monitor the segregation of material coming in to Landfill. Hours of operation are posted for public and the gate is locked during evenings to ensure segregation is respected.</div><div>4. Some section of fence around the Landfill needs to be replaced. The fencing prevents windblown debris from being deposited to the land and ocean around the Landfill.</div><div>5. Battery and waste oil storage is disorganized after winter season and no attendant on site.</div></div> | | | |

| | | | |
|---|--|---|--|
| SECTION 2- | <input checked="" type="checkbox"/> Comments | <input type="checkbox"/> Non-Compliance with Act or Licence | <input type="checkbox"/> Action Required |
| <p>Summary:</p> <p>During the writing of this report the Hamlet hired a contractor to complete maintenance and upgrades to the landfill including lifting the exterior berm, sorting bulking materials/ hazardous waste and installing a new fence around the perimeter.</p> <p>A Landfill attendant was hired and is progressively maintaining site operations and storage of hazardous waste.</p> | | | |

| | |
|-------------------------------|----------------------|
| Inspector's Name | Representatives Name |
| Atuat Shouldice | Darren Flynn |
| Signature | |
| Sent Electronically | |
| Date | |
| October 25 th 2021 | |

Water Resource Officer, Nunavut Region
Crown Indigenous Relations and Northern Affairs Canada – CIRNAC
Atuat.Shouldice@RCAANC-CIRNAC.GC.CA
Office #: 867-645-2840



PHOTO LOG

| Date: | Authorization Number: | Camera/Model: | Inspector |
|----------------|-----------------------|---------------|---------------|
| June 24th 2021 | 3BM-RAN2025 | Samsung S9 | RMO Shouldice |

| Photo No. | Lat/Long (DD.MM.SS.SS, NAD83) |
|-----------|-------------------------------|
| Photo 1 | Marked on provided map. |

Description: Waste oil drums, waste garbage, since inspection has been cleaned up.



| PHOTO LOG | | | |
|--|-----------------------|-------------------------------|---------------|
| Date: | Authorization Number: | Camera/Model: | Inspector |
| June 24th 2021 | 3BM-RAN2025 | Samsung S9 | RMO Shouldice |
| Photo No. | | Lat/Long (DD.MM.SS.SS, NAD83) | |
| Photo 2 | | Marked on provided map. | |
| Description: balk storage area, since inspection the land fill attendant have been working on segregation. | | | |



| PHOTO LOG | | | |
|---|-----------------------|-------------------------------|---------------|
| Date: | Authorization Number: | Camera/Model: | Inspector |
| June 24 th 2021 | 3BM-RAN2025 | Samsung S9 | RMO Shouldice |
| Photo No. | | Lat/Long (DD.MM.SS.SS, NAD83) | |
| Photo 3 | | | |
| Description: winter collection of discarded batteries to be stored. | | | |

