



WATER LICENCE INSPECTION FORM

☒ Original

☐ Follow-Up Report

Licensee	Licensee Representative
Hamlet of Rankin Inlet	Darren Flynn
Licence No. / Expiry	Representative's Title
3BM-RAN2025/ Dec 20,2025	Senior Administrative Officer
Date of Inspection	Inspector
6/24/2021	Atuat SHOULDICE
Activities Inspected	
<div><input type="checkbox"/> Camp<input type="checkbox"/> Drilling<input type="checkbox"/> Mining<input type="checkbox"/> Construction<input type="checkbox"/> Reclamation<input type="checkbox"/> Fuel Storage</div> <div><input type="checkbox"/> Roads/Hauling<input checked="" type="checkbox"/> Other: Landfill<input type="checkbox"/> Other:</div>	

SECTION 1	<input checked="" type="checkbox"/> Comments	<input type="checkbox"/> Non-Compliance with Act or Licence	<input type="checkbox"/> Action Required
<p>On June 24th , 2021 a water license Inspection was conducted of 3BM-RAN2025, issued to the Hamlet of Rankin Inlet, by the Crown Indigenous Relations and Northern Affairs Canada, Water Resource Officer Atuat Shouldice and Jakob Voisey. Darren Flynn (SAO) and Troy Aksalnik (Foremen) accompanied the Inspectors during inspection.</p> <p>Observations</p> <div><div>1. The 2020 annual report is available for review on the Nunavut Water Board FTP website.</div><div>2. The Landfill is equipped with signage.</div><div>3. The Hamlet is in the process of hiring a Landfill attendant to help organize and monitor the segregation of material coming in to Landfill. Hours of operation are posted for public and the gate is locked during evenings to ensure segregation is respected.</div><div>4. Some section of fence around the Landfill needs to be replaced. The fencing prevents windblown debris from being deposited to the land and ocean around the Landfill.</div><div>5. Battery and waste oil storage is disorganized after winter season and no attendant on site.</div></div>			

SECTION 2-	<input checked="" type="checkbox"/> Comments	<input type="checkbox"/> Non-Compliance with Act or Licence	<input type="checkbox"/> Action Required
<p>Summary:</p> <p>During the writing of this report the Hamlet hired a contractor to complete maintenance and upgrades to the landfill including lifting the exterior berm, sorting bulking materials/ hazardous waste and installing a new fence around the perimeter.</p> <p>A Landfill attendant was hired and is progressively maintaining site operations and storage of hazardous waste.</p>			

Inspector's Name	Representatives Name
Atuat Shouldice	Darren Flynn
Signature	
Sent Electronically	
Date	
October 25 <sup>th</sup> 2021	

Water Resource Officer, Nunavut Region  
Crown Indigenous Relations and Northern Affairs Canada – CIRNAC  
Atuat.Shouldice@RCAANC-CIRNAC.GC.CA  
Office #: 867-645-2840



PHOTO LOG

Date:	Authorization Number:	Camera/Model:	Inspector
June 24th 2021	3BM-RAN2025	Samsung S9	RMO Shouldice

Photo No.	Lat/Long (DD.MM.SS.SS, NAD83)
Photo 1	Marked on provided map.

Description: Waste oil drums, waste garbage, since inspection has been cleaned up.





PHOTO LOG			
Date:	Authorization Number:	Camera/Model:	Inspector
June 24th 2021	3BM-RAN2025	Samsung S9	RMO Shouldice
Photo No.	Lat/Long (DD.MM.SS.SS, NAD83)		
Photo 2	Marked on provided map.		





PHOTO LOG			
Date:	Authorization Number:	Camera/Model:	Inspector
June 24 <sup>th</sup> 2021	3BM-RAN2025	Samsung S9	RMO Shouldice
Photo No.	Lat/Long (DD.MM.SS.SS, NAD83)		
Photo 3			
Description: winter collection of discarded batteries to be stored.			

