



WATER LICENCE INSPECTION FORM

☒ Original  
☐ Follow-Up Report

Licensee		Licensee Representative	
Hamlet of Taloyoak		Larry Banks	
Licence No. / Expiry		Representative's Title	
3BM-TAL-1419		Director of Public Works	
Land / Other Authorizations		Land / Other Authorizations	
Date of Inspection		Inspector	
7 July 2016		Baba Pedersen	
Activities Inspected			
<input type="checkbox"/> Camp	<input type="checkbox"/> Drilling	<input type="checkbox"/> Mining	<input type="checkbox"/> Construction
<input type="checkbox"/> Roads/Hauling	<input checked="" type="checkbox"/> Other: Municipal	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Fuel Storage

Conditions:		A - Acceptable	C - Concern	U - Unacceptable	NA – Not Applicable	NI – Not Inspected	
Water Use		Condition	Comment	Site Conditions		Condition	Comment
Intake/Screen	A			Water Management Structures			
Flow Measure. Device	U	1		Culverts / Bridges			
Source:				Drainage		A	
Water Use:	C	1		Erosion / Sediment			
Recirculation ( y /n)				Mitigation Measures			
				Reclamation Activities			
				Materials Storage		C	5
Waste Disposal				Signage		C	5
Waste Water	A						
Solid Waste	A			Monitoring			
Hazardous Waste	A			Sample Collection / Analysis		C	3 & 4
*The number in the comments field will correspond with specific comments provided below.							
Samples taken by Inspector:		Location(s): TAL 3, TAL 4 and TAL 6					
<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No							

SECTION 1	<input checked="" type="checkbox"/> Comments (s. __)	<input type="checkbox"/> Non-Compliance with Act or Licence (s. __)	<input type="checkbox"/> Action Required (s. __)
INAC Staff on this Inspection included Baba Pedersen, RMO/WRO, Erik Allain, Manager Field Operations and Jeremy Fraser, Summer Student. Shah Alam, GN Municipal Engineer for the Kitikmeot Region was also in attendance.			
SECTION 2	<input checked="" type="checkbox"/> Comments	<input type="checkbox"/> Non-Compliance with Act or Licence	<input type="checkbox"/> Action Required
Field Inspection Sites included the Water Intake Building (Photo 1), the Sewage Lagoon (Photo 3), the Garbage Dump and the Metal Dump. INAC Inspectors took Samples at Stations TAL 3 (photo 4), TAL 4 and TAL 6.			
SECTION 3	<input type="checkbox"/> Comments	<input type="checkbox"/> Non-Compliance with Act or Licence	<input checked="" type="checkbox"/> Action Required
1. The Hamlet uses the Fluid Manager Computer System and the Flow Meter had been sent out for Repairs. The Hamlet Staff were taking Manual Records (Photo 2) but were unable to provide Consumption Records as is required by the Water Licence. Staff MUST be able to provide Consumption Records to the Inspector on request. This needs to be rectified prior to next year's Inspection. 2. The Inspector strongly recommends the Hamlet build a Land Farm to properly handle Contaminated Soils. 3. Samples need to be taken by Hamlet Staff regularly and recorded as and when the Water Licence Stipulates. 4. The Dump Effluent Sample Location needs to be changed from Station TAL 5 to Station TAL 4 because the Station TAL 5 location is 100% dry and has no signs of any flow and there is sufficient flow and liquid to sample at Station TAL 4. 5. Signage needs to be posted in the Dump area to aid the public and Hamlet in properly segregating materials brought to the Dump as per the Water Licence. This needs to be installed prior to next year's Inspection.			

Licensee or Representative	Inspector's Name
	Baba Pedersen
Signature	Signature
	Signed Original on File
Date	Date
	17 October 2016


Office Use Only:	Follow-up report to be issued by Inspector	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
------------------	--	---

CC: licensing@nwb-oen.ca  
Erik Allain, Manager of Field Operations, INAC  
Shah Alam, Municipal Engineer, Gov't of Nunavut




PHOTO LOG

Date	Camera	Inspector	Authorization
7 July 2016		Baba Pedersen	3BM-TAL-1419
Photo Log # 6000		Location	
Photo 1		Water Intake Building	



Description: Outside view of Water Intake Building

Photo Log # 6005	Location
Photo 2	Water Intake Building



Description: Manual Records inside Water Intake Building DO NOT show Consumption Records and/or Amounts





Photo Log # 6015

Photo 3

Location

Sewage lagoon



Description: View of Sewage Lagoon and Truck Dumping Station

Photo Log # 6019

Photo 4

Location

TAL 3 Sample

Location



Description: INAC Inspectors taking samples at TAL 3 Sample Location