

Government of Nunavut

Environmental Assessment Screening under CEAA

Sewage Wetland Upgrade for the Hamlet of Whale Cove, Nunavut

Type of Document:

Appendix B: Site Photographs included with Final Report

Project Name:

Environmental Assessment Screening

Project Number:

OTT-00201369-A0

Prepared By:

exp

1595 Clark Boulevard
Brampton, ON L6T 4V1
Canada

T: 905.793.9800

F: 905.793.0641

www.exp.com

Date Submitted:

March 2013

Appendix B – Site Photographs



Photograph No. 1: Sewage Lagoon Inlet (East Berm)



Photograph No. 2: Sewage Lagoon Inlet Channel (East Berm)



Photograph No. 3: Sewage Deposit into Sewage Lagoon



Photograph No. 4: Base of Sewage Inlet Channel (East Berm)



Photograph No. 5: Typical Shoreline of Sewage Lagoon



Photograph No. 6: Fireweed Plants



Photograph No. 7: Evidence of Wildlife Browse



Photograph No. 8: Shoreline of Sewage Lagoon (South of Inlet)



Photograph No. 9: Typical Vegetation Present Throughout the Site



Photograph No. 10: Rock Willow Present Throughout the Site



Photograph No. 11: Shoreline of Sewage Lagoon made up of Rock Outcrops with Various Patches of Low-Lying Vegetation



Photograph No. 12: Typical Vegetation Present Throughout the Site



Photograph No. 13: West End of Sewage Lagoon; West Berm Visible (with Tall Grasses)



Photograph No. 14: Existing Outlet Berm (West Berm)



Photograph No. 15: View from the West Berm to the Downgradient Wetlands; Ocean in the Background (Looking West)



Photograph No. 16: Minor Berm Seepage (West Berm)



Photograph No. 17: Beginning of Wetlands (Adjacent to West Berm)



Photograph No. 18: Evidence of Wildlife Habitat Throughout the Wetlands



Photograph No. 19: Various Water Courses Throughout the Wetlands



**Photograph No. 20: Various Water Courses Throughout the Wetlands
Among Moss Beds**



Photograph No. 21: Arctic Squirrels Observed Throughout the Site



Photograph No. 22: Midway at the Wetlands; View Towards the Ocean



**Photograph No. 23: Wetlands Area Protected by Adjacent Rock Walls
(North and South of the Wetlands)**



Photograph No. 24: Downgradient Wetlands Area, Near Water Course



Photograph No. 25: Evidence of Wildlife



**Photograph No. 26: Downgradient Surface Water Sampling Point
(Facing East Toward Sewage Lagoon)**



Photograph No. 27: Least Sandpiper Observed Throughout the Site



Photograph No. 28: Outlet to the Ocean