

Date: July 13/12

ENVIRONMENTAL INSPECTION REPORT

Page 2

Permit/License#


TBL-AWL 1015 / Lease 58F/2-1-2

- Erosion along banks is occurring due to natural conditions → water intake will need to be moved to limit extra erosion in immediate vicinity (also safety concerns).
- Fuel storage → 2 berm units have not yet arrived from Yellowknife
 - ↳ Spill containment under main fuel tank and generator are good; but containment is needed for oils, lubricants and gas stored in maintenance + generator huts.
 - ↳ Fuel distribution lines are buried → monitoring required (recording monitoring).
- Water licence + lease records not kept on site (hard copy).
- Groundwater filtration system is located with high water mark, but no deposit occurs.
- DFO cabin located at N 74° 04.976' W 013° 49.967' (WAD83) ≠ Arctic watch
 - ↳ Arctic watch has cleaned the site up and DFO ^(research) stays during season but wastes are dealt with by lodge. Arctic watch set up this cabin as emergency cabin for Hunter/Trapper in Resolute, with fuel + food. RH
- Would like to see more records being kept on site, also fuel ^{spill} prevention + contingency plan as well as camp shut-down procedures.
- Overall site is clean + well kept → follow-up reporting required for fuel spill + secondary containment installation. (within next 30 days).


Representative's Signature


Inspector's Signature


RMO Initials


Representative's Title


District Mgr. Initials

Copy 1 - Inspector's File

Copy 2 - Field Rep.

Copy 3 - Permittee Head O.

Copy 4 - District