



## WATER LICENCE INSPECTION FORM

Original  
 Follow-Up Report

Licensee	Licensee Representative				
Canadian Arctic Holidays Ltd.	Richard Weber				
License No. / Expiry	Representative's Title				
7BL-ENN1828	Operator				
Land Authorization No. / Purpose / Expiry	Land Authorization Expiry				
--	May 9 <sup>th</sup> , 2018				
Date of Inspection	Inspector				
July 12 <sup>th</sup> , 2019	RMO C. Wilson				
Activities Inspected					
<input checked="" type="checkbox"/> Camp	<input type="checkbox"/> Drilling	<input type="checkbox"/> Mining	<input type="checkbox"/> Construction	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Fuel Storage
<input checked="" type="checkbox"/> Roads/Hauling	<input type="checkbox"/> Other:	<input type="checkbox"/> Other:			

**SECTION 1**     **Comments (s.1)**     **Non-Compliance with Act or Licence (s.1)**     **Action Required (s.1)**

On July 12<sup>th</sup>, 2019 Crown-Indigenous Relations and Northern Affairs Canada's Resource Management Officer, Christine Wilson completed a compliance inspection on Arctic Haven Lodge's water licence no.7BL-ENN1828.

*Preliminary notes*

- The water licence has been recently renewed on March 1<sup>st</sup>, 2018.
- The Licensee is allotted four (4) cubic metres per day for recreational purposes.
- The 2018 annual report is available for review on the Nunavut Water Board's FTP website.
- The annual report indicated that the Arctic Haven Lodge (lodge) used on average 3.7 cubic metres of water per day in 2018.

*Observations*

1. Freshwater is drawn on demand from Ennadai Lake and stored in tank at the lodge (photo 1).
2. The lodge used approximately 4.2 cubic meters for water the for month of July (photo 2)
3. Grey and black water is deposited into septic tanks. The sewage sludge is removed from the septic tanks annually and shipped out.
4. The freshwater intake is equipped with a screen (photo 3).
5. There is visible erosion on the trails that lead north to the floating boating dock (photo 4) and east from the Care-taker's cabin to the Lake (photo 5).
6. A temporary fuel storage container is located near the floating dock to refuel boats. In accordance with PART H, item 2, fuel must be stored at a minimum distance of 31 meters from the ordinary high water mark. All fuel containers and lines must have secondary containment and moved out of the 31 meter buffer zone when not in use (photo 6).
7. The pit that was used during the airstrip improvements needs to be graded flat with the surrounding topography (photo 7).

**SECTION 2**     **Comments (s.2)**     **Non-Compliance with Act or Licence (s.2)**     **Action Required (s.2)**

*Non-compliance or concerns related to the conditions of water licence 7BL-ENN1828:*

- Part I item 3, Failure to restore land to pre-existing contour to reduce erosion and permafrost degradation.

**SECTION 3**     **Comments (s.3)**     **Non-Compliance with Act or Licence, (s.3)**     **Action Required (s.3)**

The Licensee shall restore the pit noted in observation seven before the end of 2019 season and provide pictures to the inspector no later than November 30<sup>th</sup>, 2019.

The Lodge is well maintained, the inspector was pleased with the condition of the site in general.

Licensee or Representative	Inspector's Name
	C. Wilson
Signature	Signature
	Sent by e-mail
Date	Date
	July 12 <sup>th</sup> , 2019

Office Use Only:    Follow-up report to be issued by Inspector     Yes     No

**Attached:** Photo Log 7BL-ENN1828, - July 12<sup>th</sup>, 2019

cc.    Justin Hack, Manager Field Operations, CIRNAC  
Atuat Shouldice, Resource Management Officer, CIRNAC



Photo Log 7BL-ENN1828  
July 12<sup>th</sup>, 2019  
C. Wilson



**Photo Log # 1**

Photo

**Location (NAD 83 DD MM SS.SS)**

N60° 46' 04.07", W101° 41' 15.45"



**Description:**


Arctic Haven Lodge

**Photo Log # 2**

Photo

**Location (NAD 83 DD MM SS.SS)**

NA



**Description:**

Water Meter



**Photo Log # 3**

Photo

**Location (NAD 83 DD MM SS.SS)**

N60° 46' 2.84", W101° 41' 20.60"



**Description:**

Fresh water intake

**Photo Log # 4**

Photo

**Location (NAD 83 DD MM SS.SS)**

N60° 46' 0.80", W101° 41' 32.66"



**Description:**

North Trail to Boat Dock



Photo Log # 5

Photo

Location (NAD 83 DD MM SS.SS)

N60° 45' 57.74", W101° 41' 20.99"



Description:

Fresh Water intake

Photo Log # 6

Photo

Location (NAD 83 DD MM SS.SS)

N60° 46' 10.08", W101° 41' 45.73"



Description:

Fuel storage



Photo Log # 7

Photo

Location (NAD 83 DD MM SS.SS)

N60° 46' 5.5", W101° 41' 41.46"



**Description:**

Water transfer pit