



WATER LICENCE INSPECTION FORM

☒ Original
☐ Follow-Up Report

Licensee		Licensee Representative	
Hakongak Outfitting		N/A	
Licence No. / Expiry		Representative's Title	
7BL-HKO1015		-	
Land / Other Authorizations		Land / Other Authorizations	
Date of Inspection		Inspector	
18/07/2014		Eva Paul	
Activities Inspected			
<input checked="" type="checkbox"/> Camp	<input type="checkbox"/> Drilling	<input type="checkbox"/> Mining	<input type="checkbox"/> Construction
<input type="checkbox"/> Roads/Hauling	<input type="checkbox"/> Other:	<input type="checkbox"/> Other:	<input type="checkbox"/> Reclamation
<input checked="" type="checkbox"/> Fuel Storage			

Conditions:		A - Acceptable	C - Concern	U - Unacceptable	NA – Not Applicable	NI – Not Inspected					
Water Use		Condition	Comment	Site Conditions		Condition	Comment	Haz/Mat Management		Condition	Comment
Intake/Screen	NA			Water Management Structures		NA		Storage		A	
Flow Measure. Device	NA			Culverts / Bridges		NA		Spills		A	
Source:	NA			Drainage		U	2	Spill Plan		A	
Water Use:	NA			Erosion / Sediment		A					
Recirculation (y /n)	NA			Mitigation Measures		NA		Administrative			
				Reclamation Activities		NA		Records		NI	
				Materials Storage		A	3	Reports		U	4
Waste Disposal				Signage		NA		Plans		NI	
Waste Water	A							Notifications		NA	
Solid Waste	U	1		Monitoring		Other					
Hazardous Waste	A	1		Sample Collection / Analysis		NA					
*The number in the comments field will correspond with specific comments provided below.											
Samples taken by Inspector:			Location(s):								
<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No											

SECTION 1	<input checked="" type="checkbox"/> Comments (s.1)	<input checked="" type="checkbox"/> Non-Compliance with Act or Licence (s.2)	<input checked="" type="checkbox"/> Action Required (s.3)
A compliance inspection was conducted on July 18, 2014. The camp was not in use; it was all boarded up.			
1. The burn barrel contains fuel cans and naptha cans that have been burned. Other waste remains to be backhauled. Please note that as per your water licence application, you indicated that only paper will be incinerated in an open barrel and all other waste brought back to Cambridge Bay. No fuel was seen on-site.			
2. ATV use along the shore is causing rutting that could lead to sedimentation or impacts to surface drainage. Metal shed is constructed on the immediate banks of the river contrary to the licence.			
3. Quads were covered over with a tarp that has been frayed by the wind. The outhouse is tipped over.			
4. No annual reports are found on the NWB Public Registry.			
SECTION 2	<input type="checkbox"/> Comments	<input checked="" type="checkbox"/> Non-Compliance with Act or Licence	<input type="checkbox"/> Action Required
Part B Item 2. Failure to file annual reports.			
Part D Item 4. Open burning of non-approved waste.			
Part E Item 1. The licensee has erected a building on the immediate bank of the river contrary to this condition.			
Part E Item 2. ATV use on wet river bank is causing rutting.			
SECTION 3	<input type="checkbox"/> Comments	<input type="checkbox"/> Non-Compliance with Act or Licence	<input checked="" type="checkbox"/> Action Required
1. Remove all solid waste back to Cambridge Bay as soon as possible.			
2. Discontinue ATV use along shore during wet times. Licensee should travel on dry, hard ground and minimize activity within 31m of all water bodies.			
3. Metal shed and burn barrels must be moved to more than 30m from the high water mark of the river.			
4. Annual reports are required whether or not the camp is active in a given year. Please submit reports for past years and 2014 by March 31, 2015. Please include a report on the work done to remediate the items identified above.			

Licensee or Representative	Inspector's Name
-	Eva Paul
Signature	Signature
-	Sent electronically
Date	Date
-	28/11/2014

APPENDICES:	<input checked="" type="checkbox"/> Inspection Photos	<input type="checkbox"/> Sample Results	<input type="checkbox"/> Other: _____
-------------	---	---	---------------------------------------



Photos of July 18 2014 Inspection



Figure 1. Mr. Hakongak's outfitting camp from the air. Large metal shed constructed, and other materials are stored, below the high water mark.



Figure 2. Contents of burn barrel.



Figure 3. Contents of waste barrel.




Figure 4. Rutting caused by ATV use.

CC: Phyllis Beaulieu, Manager of Licensing, NWB
 Erik Allain, Manager of Field Operations, AANDC