



Inspection Report

License #: 3BC-CAM0919

Inspector: A.Keim

CIDMS # 384948

Client	National Defence Canada Nasittuq Corp.		
Mailing Address	Maj. A. Cameron – R&C 3-4 North Warning System Office c/o National Defence Headquarters 101 Colonel By Drive Ottawa, ON. K1A 0K2	Mr. Scott Charland Nasittuq Corp. Suite 100, 170 Laurier Ave W Ottawa, ON K1P 5V5	
Inspection site location	Cam-Main Cambridge Bay LRR		
Contact name	A. Cameron	Title	O.I.C
Last inspection date	Unknown	July 25,2008	
Inspection start date	August 25, 2009		
Region	Baffin		



INAC, Nunavut District
Box 100
Building 918
Iqaluit, NU, X0A 0H0

January 15, 2010

Maj. A. Cameron – R&C 3-4
North Warning System Office
c/o National Defence Headquarters
101 Colonel By Drive
Ottawa, ON. K1A 0K2

Submitted Via E-Mail
Our File: 3BC-CAM0919
Your File: _____
CIDM # 384948

Mr. Scott Charland
Nasittuq Corp.
Suite 100, 170 Laurier Avenue West
Ottawa, ON K1P 5V5
E-mail: scott.charland@nasittuq.com

RE: Water Licence Inspection August 25, 2009

The following inspection report is generated on the information collected during a compliance inspection carried out on the Cam-Main Cambridge Bay Long Range Radar site and facilities. The inspection was conducted to determine compliance with the terms and conditions of the Water License (3BC-CAM0409) issued to National Defence Canada (DND) by the Nunavut Water Board (NWB).

The report references the applicable parts of the Water License (3BC-CAM0409) and the findings observed under each of those parts. During the writing of this report a compliance review was undertaken of the documents, plans and manuals filed by the Licensee and located on the Nunavut Water Board's FTP site.

The Inspector thanks Ms. Barb Thomson and Ms. Mitzi Wall, both of Nasittuq Corporation for their assistance, time and advice during the inspection. The Inspector also thanks Mr. Kim Kalen, National Defence Canada for acting as the licensee's representative during the Inspection.

* It is noted that the current Water License (3BC-CAM0919) was issued on September 10th, 2009 following the Inspection. The new License addresses a number of the inconsistencies identified by the Licensee and the Inspector.

Issues noted in previous Inspections;

- Secondary Containment for fuel transfer areas is required.
- Secondary Containment required at Airport hanger.

During the period of the 2009 inspection the following issues were identified by the Inspector;

- Implementation of a testing procedure for water collected within Fuel Storage secondary containment prior to discharge.
- Battery storage requires secondary containment.

Non-Compliance: Issues identified during the August 25th, 2009 inspection and/or review of relevant material

Issues where there is a known or anticipated threat to human health.

- None noted

Issues where there is a known or anticipated environmental impairment;

- None

Issues where there is a known or suspected violation of a requirement of the Water License;

- None

The licensee is working on achieving compliance.



Indian and Northern
Affairs Canada

Affaires indiennes
et du Nord Canada

A. Keim

Inspector's Name

Inspector's Signature

Cc:

Peter Kusugak - Manager Field Operations Section- Indian and Northern Affairs Canada
Phyllis Beaulieu – Manager licensing – Nunavut Water Board



























