



APPENDIX D1 CULVERTS ALONG AWPR PHOTOGRAPHIC LOG



Photograph D1-17: R-03 km 10+580

Date: September 7, 2017

Photo Number: 069

Description: View of the culvert inlet. In good condition.



Photograph D1-18: R-03 km 10+580

Date: September 7, 2017

Photo Number: 070

Description: View of the culvert outlet. In good condition.



APPENDIX D1

CULVERTS ALONG AWPR PHOTOGRAPHIC LOG



Photograph D1-19: R-04 km 12+050

Date: September 7, 2017

Photo Number: 067

Description: View of the culvert inlet. In good condition.



Photograph D1-20: R-04 km 12+050

Date: September 7, 2017

Photo Number: 068

Description: View of the culvert outlet. In good condition.



APPENDIX D1 CULVERTS ALONG AWPR PHOTOGRAPHIC LOG



Photograph D1-21: PC-13 km 12+745

Date: September 7, 2017

Photo Number: 065

Description: View of the culvert inlet. In good condition.



Photograph D1-22: PC-13 km 12+745

Date: September 7, 2017

Photo Number: 066

Description: View of the culvert outlet. In good condition.



APPENDIX D1 CULVERTS ALONG AWPR PHOTOGRAPHIC LOG



Photograph D1-23: PC-2 km 13+405

Date: September 7, 2017

Photo Number: 061

Description: View of the culvert inlet. In good condition.



Photograph D1-24: PC-2 km 13+405

Date: September 7, 2017

Photo Number: 062

Description: View of the culvert outlet. In good condition.



APPENDIX D1 CULVERTS ALONG AWPR PHOTOGRAPHIC LOG



Photograph D1-25: PC-3 km 13+685

Date: September 7, 2017

Photo Number: 059

Description: View of the culvert inlet. In good condition.



Photograph D1-26: PC-3 km 13+685

Date: September 7, 2017

Photo Number: 060

Description: View of the culvert outlet. In good condition.



APPENDIX D1 CULVERTS ALONG AWPR PHOTOGRAPHIC LOG



Photograph D1-27: unnamed km 13+950

Date: September 7, 2017

Photo Number: 057

Description: View of the culvert inlet. In good condition.



Photograph D1-28: unnamed km 13+950

Date: September 7, 2017

Photo Number: 058

Description: View of the culvert outlet. The outlet is in good condition.



APPENDIX D1 CULVERTS ALONG AWPR PHOTOGRAPHIC LOG



Photograph D1-29: PC-4 km 14+910

Date: September 7, 2017

Photo Number: 055

Description: View of the culvert inlet. In good condition.



Photograph D1-30: PC-4 km 14+910

Date: September 7, 2017

Photo Number: 056

Description: View of the culvert outlet. In good condition. Large boulders around the outlet.



APPENDIX D1 CULVERTS ALONG AWPR PHOTOGRAPHIC LOG



Photograph D1-31: R-05A km 15+745

Date: September 7, 2017

Photo Number: 053

Description: View of the culvert inlet. In good condition.



Photograph D1-32: R-05A km 15+745

Date: September 7, 2017

Photo Number: 054

Description: View of the culvert outlet. In good condition.



APPENDIX D1 CULVERTS ALONG AWPR PHOTOGRAPHIC LOG



Photograph D1-33: PC-5 km 18+280

Date: September 7, 2017

Photo Number: 047

Description: View of the culvert inlet. In good condition.



Photograph D1-34: PC-5 km 18+280

Date: September 7, 2017

Photo Number: 048

Description: View of the culvert outlet. In good condition.



APPENDIX D1 CULVERTS ALONG AWPR PHOTOGRAPHIC LOG



Photograph D1-35: PC-6 km 18+900

Date: September 7, 2017

Photo Number: 045

Description: View of culvert inlet. In good condition.



Photograph D1-36: PC-6 km 18+900

Date: September 7, 2017

Photo Number: 046

Description: View of culvert outlet. In good condition.



APPENDIX D1 CULVERTS ALONG AWPR PHOTOGRAPHIC LOG



Photograph D1-37: PC-7A km 20+240

Date: September 7, 2017

Photo Number: 043

Description: View of culverts inlet. In general good condition.



Photograph D1-38: PC-7A km 20+240

Date: September 7, 2017

Photo Number: 044

Description: View of culverts outlet. In good general condition.



APPENDIX D1 CULVERTS ALONG AWPR PHOTOGRAPHIC LOG



Photograph D1-39: PC-7 km 20+250

Date: September 7, 2017

Photo Number: 041

Description: View of the culvert inlet. In good condition.



Photograph D1-40: PC-7 km 20+250

Date: September 7, 2017

Photo Number: 042

Description: View of the culvert outlet. In good condition.



APPENDIX D1 CULVERTS ALONG AWPR PHOTOGRAPHIC LOG



Photograph D1-41: R-07 km 25+900

Date: September 7, 2017

Photo Number: 033

Description: View of the culvert inlet. In good condition.



Photograph D1-42: R-07 km 25+900

Date: September 7, 2017

Photo Number: 034

Description: View of the culvert outlet. In good condition.



APPENDIX D1 CULVERTS ALONG AWPR PHOTOGRAPHIC LOG



Photograph D1-43: PC-8 km 29+420

Date: September 7, 2017

Photo Number: 031

Description: View of the culvert inlet. In good condition.



Photograph D1-44: PC-8 km 29+420

Date: September 7, 2017

Photo Number: 032

Description: View of the culvert outlet. In good condition.