



APPENDIX D2

BRIDGES ALONG AWPR PHOTOGRAPHIC LOG



Photograph D2-3 Bridges 1 – R02 km 8+750

Date: September 7, 2017

Photo Number: 079

Description: Looking at the north abutment from upstream.



Photograph D2-4 Bridges 1 – R02 km 8+750

Date: September 7, 2017

Photo Number: 080

Description: Looking at the south abutment from upstream.



APPENDIX D2

BRIDGES ALONG AWPR PHOTOGRAPHIC LOG



Photograph D2-5 Bridges 2 – R05 km 17+600

Date: September 7, 2017

Photo Number: 051

Description: Looking at the north abutment from downstream.



Photograph D2-6 Bridges 2 – R05 km 17+600

Date: September 7, 2017

Photo Number: 052

Description: Looking at the south abutment from downstream. Minor damage to the bin wall.



APPENDIX D2

BRIDGES ALONG AWPR PHOTOGRAPHIC LOG



Photograph D2-7 Bridges 2 – R05 km 17+600

Date: September 7, 2017

Photo Number: 049

Description: Looking at the north abutment from upstream.



Photograph D2-8 Bridges 2 – R05 km 17+600

Date: September 7, 2017

Photo Number: 050

Description: Looking at the south abutment from upstream. Minor damage to the bin wall.



APPENDIX D2

BRIDGES ALONG AWPR PHOTOGRAPHIC LOG



Photograph D2-9 Bridges 3 – R06 km 23+100

Date: September 7, 2017

Photo Number: 037

Description: Looking at the north abutment from upstream.



Photograph D2-10 Bridges 3 – R06 km 23+100

Date: September 7, 2017

Photo Number: 038

Description: Looking at the south abutment from upstream.



APPENDIX D2

BRIDGES ALONG AWPR PHOTOGRAPHIC LOG



Photograph D2-11 Bridges 3 – R06 km 23+100

Date: September 7, 2017

Photo Number: 039

Description: Looking at the north abutment from downstream.



Photograph D2-12 Bridges 3 – R06 km 23+100

Date: September 7, 2017

Photo Number: 040

Description: Looking at the south abutment from downstream.



APPENDIX D2

BRIDGES ALONG AWPR PHOTOGRAPHIC LOG



Photograph D2-13 Bridges 4 – R09 km 48+500

Date: September 7, 2017

Photo Number: 008

Description: Looking at the south abutment from downstream.



Photograph D2-14 Bridges 4 – R09 km 48+500

Date: September 7, 2017

Photo Number: 009

Description: Looking at the north abutment from downstream.



APPENDIX D2

BRIDGES ALONG AWPR PHOTOGRAPHIC LOG



Photograph D2-15 Bridges 4 – R09 km 48+500

Date: September 7, 2017

Photo Number: 006

Description: Looking at the north abutment from upstream.



Photograph D2-16 Bridges 4 – R09 km 48+500

Date: September 7, 2017

Photo Number: 007

Description: Looking at the south abutment from upstream.



APPENDIX D2

BRIDGES ALONG AWPR PHOTOGRAPHIC LOG



Photograph D2-17 Bridges 5 – R13 km 62+060

Date: September 8, 2017

Photo Number: 138

Description: Looking at the bridge from the downstream side.



Photograph D2-18 Bridges 5 – R13 km 62+060

Date: September 8, 2017

Photo Number: 139

Description: Looking at the bridge from the upstream side.



APPENDIX D2 BRIDGES ALONG AWPR PHOTOGRAPHIC LOG



Photograph D2-19 Bridges 6 – R15 km 69+200

Date: September 8, 2017

Photo Number: 150

Description: Looking at the south abutment from downstream. Damage to the bin wall likely caused during snow removal activities. Bridge is tipping toward the west side on the abutment.



Photograph D2-20 Bridges 6 – R15 km 69+200

Date: September 8, 2017

Photo Number: 151

Description: Looking at the north abutment from downstream. Damage to the bin wall likely caused during snow removal activities. Bridge is tipping toward the west side on the abutment.



APPENDIX D2

BRIDGES ALONG AWPR PHOTOGRAPHIC LOG



Photograph D2-21 Bridges 6 – R15 km 69+200

Date: September 8, 2017

Photo Number: 149

Description: Looking at the north abutment from upstream. Damage to the bin wall likely caused during snow removal activities. Bridge is tipping toward the west side on the abutment.



Photograph D2-22 Bridges 6 – R15 km 69+200

Date: September 8, 2017

Photo Number: 148

Description: Looking at the south abutment from upstream. Damage to the bin wall likely caused during snow removal activities. Bridge is tipping toward the west side on the abutment.



APPENDIX D2 BRIDGES ALONG AWPR PHOTOGRAPHIC LOG



Photograph D2-23 Bridges 7 – R16 km 73+800

Date: September 8, 2017

Photo Number: 156

Description: Looking at the bridge from the downstream side.



Photograph D2-24 Bridges 7 – R16 km 73+800

Date: September 8, 2017

Photo Number: 157

Description: Looking at the bridge from the upstream side.



APPENDIX D2

BRIDGES ALONG AWPR PHOTOGRAPHIC LOG



Photograph D2-25 Bridges 8 – R18 km 79+500

Date: September 8, 2017

Photo Number: 161

Description: Looking at the bridge from the upstream side.



Photograph D2-26 Bridges 8 – R18 km 79+500

Date: September 8, 2017

Photo Number: 160

Description: Looking at the bridge from the downstream side.



APPENDIX D2 BRIDGES ALONG AWPR PHOTOGRAPHIC LOG



Photograph D2-27 Bridges 9 – R19 km 83+150

Date: September 8, 2017

Photo Number: 169

Description: Looking at the bridge from the upstream side.



Photograph D2-28 Bridges 9 – R19 km 83+150

Date: September 8, 2017

Photo Number: 168

Description: Looking at the bridge from the downstream side.



APPENDIX E

Amaruq Road Photographic Log



APPENDIX E1

Culverts along Amaruq Road Photographic Log



APPENDIX E1

CULVERTS ALONG AMARUQ ROAD PHOTOGRAPHIC LOG



Photograph E1-1: Culvert #39 km 9+193

Date: September 11, 2017

Photo Number: 500

Description: View of culvert inlet, damaged in the middle.



Photograph E1-2: Culvert #39 km 9+193

Date: September 11, 2017

Photo Number: 499

Description: View of culvert outlet, damaged in the middle.



APPENDIX E1

CULVERTS ALONG AMARUQ ROAD PHOTOGRAPHIC LOG



Photograph E1-3: Culvert #60 km 12+775

Date: September 11, 2017

Photo Number: 487

Description: View of culvert outlet, in good condition.



Photograph E1-4: Culvert #86 km 20+740

Date: September 11, 2017

Photo Number: 475

Description: View of culvert outlet, buried.



APPENDIX E1

CULVERTS ALONG AMARUQ ROAD PHOTOGRAPHIC LOG



Photograph E1-5: Culvert #115 km 26+865

Date: September 11, 2017

Photo Number: 460

Description: View of culvert outlet, partially buried.



Photograph E1-6: Culvert #167 km 41+843

Date: September 10, 2017

Photo Number: 418

Description: View of culvert inlet, water is flowing underneath.



APPENDIX E1

CULVERTS ALONG AMARUQ ROAD PHOTOGRAPHIC LOG



Photograph E1-7: Culvert #167 km 41+843

Date: September 10, 2017

Photo Number: 419

Description: View of culvert outlet, in good condition.



Photograph E1-8: Culvert #203 km 48+800

Date: September 10, 2017

Photo Number: 395

Description: View of culvert outlet, partially buried.