



## APPENDIX E2 BRIDGES ALONG AMARUQ ROAD PHOTOGRAPHIC LOG



Photograph E2-33 Bridges 9 – km 44+800

Date: September 10, 2017

Photo Number: 408

Description: Looking at the north abutment from upstream.



Photograph E2-34 Bridges 9 – km 44+800

Date: September 10, 2017

Photo Number: 407

Description: Looking at the north abutment from downstream.



## APPENDIX E2 BRIDGES ALONG AMARUQ ROAD PHOTOGRAPHIC LOG



Photograph E2-35 Bridges 9 – km 44+800

**Date:** September 10, 2017

**Photo Number:** 405

**Description:** Looking at the south abutment from upstream.



Photograph E2-36 Bridges 9 – km 44+800

**Date:** September 10, 2017

**Photo Number:** 406

**Description:** Looking at the south abutment from downstream.



---

2017 ANNUAL GEOTECHNICAL INSPECTION  
MEADOWBANK GOLD MINE, NUNAVUT

---

## APPENDIX F

### Quarries and Eskers



---

2017 ANNUAL GEOTECHNICAL INSPECTION  
MEADOWBANK GOLD MINE, NUNAVUT

---

## APPENDIX F1

### Quarries along the AWPR Photographic Log



## APPENDIX F1 QUARRIES PHOTOGRAPHIC LOG



*Photograph F1-1: Quarry 1 – km 5+200*

**Date:** September 7, 2017

**Photo Number:** 084

**Description:** View of south walls.



*Photograph F1-2: Quarry 1 – km 5+200*

**Date:** September 7, 2017

**Photo Number:** 083

**Description:** View of south and east walls.



## APPENDIX F1 QUARRIES PHOTOGRAPHIC LOG



*Photograph F1-3: Quarry 2 – km 13+250*

**Date:** September 7, 2017

**Photo Number:** 063

**Description:** View of north and west walls.



*Photograph F1-4: Quarry 2 – km 13+250*

**Date:** September 7, 2017

**Photo Number:** 064

**Description:** View of north and east walls.



---

## APPENDIX F1 QUARRIES PHOTOGRAPHIC LOG

---



*Photograph F1-5: Quarry 3 – km 23+700*

**Date:** September 7, 2017

**Photo Number:** 035

**Description:** View of east wall.



*Photograph F1-6: Quarry 3 – km 23+700*

**Date:** September 7, 2017

**Photo Number:** 036

**Description:** View of west wall. Presence of loose rock along steep wall.



---

## APPENDIX F1 QUARRIES PHOTOGRAPHIC LOG

---



*Photograph F1-7: Quarry 4 – km 31+300*

**Date:** September 7, 2017

**Photo Number:** 029

**Description:** View of the east and south walls of Quarry 4. The quarry is flooded.



*Photograph F1-8: Quarry 4 – km 31+300*

**Date:** September 7, 2017

**Photo Number:** 030

**Description:** View of the west and south walls of Quarry 4. The quarry is flooded.



---

## APPENDIX F1 QUARRIES PHOTOGRAPHIC LOG

---



*Photograph F1-9: Quarry 5 – km 34+650*

**Date:** September 7, 2017

**Photo Number:** 028

**Description:** View of north and east walls.



*Photograph F1-10: Quarry 5 – km 34+650*

**Date:** September 7, 2017

**Photo Number:** 027

**Description:** View of north and west walls.



---

## APPENDIX F1 QUARRIES PHOTOGRAPHIC LOG

---



*Photograph F1-11: Quarry 6 – km 36+470*

**Date:** September 7, 2017

**Photo Number:** 023

**Description:** View of south and west walls.



*Photograph F1-12: Quarry 6 – km 36+470*

**Date:** September 7, 2017

**Photo Number:** 022

**Description:** View of south and east walls.



---

## APPENDIX F1 QUARRIES PHOTOGRAPHIC LOG

---



*Photograph F1-13: Quarry 7 – km 39+800*

**Date:** September 7, 2017

**Photo Number:** 017

**Description:** View of west wall. Presence of loose blocks.



*Photograph F1-14: Quarry 7 – km 39+800*

**Date:** September 7, 2017

**Photo Number:** 016

**Description:** View of north wall. Loose blocks were removed.



---

## APPENDIX F1 QUARRIES PHOTOGRAPHIC LOG

---



*Photograph F1-15: Quarry 8 – km 42+950*

**Date:** September 7, 2017

**Photo Number:** 012

**Description:** View of south wall. Presence of loose blocks.



*Photograph F1-16: Quarry 8 – km 42+950*

**Date:** September 7, 2017

**Photo Number:** 013

**Description:** View of west wall.



## APPENDIX F1 QUARRIES PHOTOGRAPHIC LOG



*Photograph F1-17: Quarry 9 – km 44+600*

**Date:** September 7, 2017

**Photo Number:** 010

**Description:** View of west and south walls. Presence of loose blocks at the base of the wall.



*Photograph F1-18: Quarry 9 – km 44+600*

**Date:** September 7, 2017

**Photo Number:** 011

**Description:** View of north and east walls. View of a pile of loose material.



---

## APPENDIX F1 QUARRIES PHOTOGRAPHIC LOG

---



*Photograph F1-19: Quarry 10 – km 48+900*

**Date:** September 7, 2017

**Photo Number:** 004

**Description:** View of the west wall. Presence of unstable blocks.



*Photograph F1-20: Quarry 10 – km 48+900*

**Date:** September 7, 2017

**Photo Number:** 005

**Description:** Overview of the quarry looking north at the east and north walls.



---

## APPENDIX F1 QUARRIES PHOTOGRAPHIC LOG

---



*Photograph F1-21: Quarry 11 – km 53+500*

**Date:** September 7, 2017

**Photo Number:** 002

**Description:** Overview of Quarry 11 looking at the west and north walls.



*Photograph F1-22: Quarry 11 – km 53+500*

**Date:** September 7, 2017

**Photo Number:** 003

**Description:** Overview of Quarry 11 looking at the north and east walls.



---

## APPENDIX F1 QUARRIES PHOTOGRAPHIC LOG

---



*Photograph F1-23: Quarry 12 – km 58+300*

**Date:** September 8, 2017

**Photo Number:** 137

**Description:** View of the south and east walls.



*Photograph F1-24: Quarry 12 – km 58+300*

**Date:** September 8, 2017

**Photo Number:** 136

**Description:** View of the west wall.



---

## APPENDIX F1 QUARRIES PHOTOGRAPHIC LOG

---



*Photograph F1-25: Quarry 13 – km 62+350*

**Date:** September 8, 2017

**Photo Number:** 140

**Description:** View of the west and north walls.



*Photograph F1-26: Quarry 13 – km 62+350*

**Date:** September 8, 2017

**Photo Number:** 141

**Description:** Looking at the south and east walls.



---

## APPENDIX F1 QUARRIES PHOTOGRAPHIC LOG

---



*Photograph F1-27: Quarry 14 – km 65+700*

**Date:** September 8, 2017

**Photo Number:** 142

**Description:** View of west and south walls. Quarry flooded.



*Photograph F1-28: Quarry 14 – km 65+700*

**Date:** September 8, 2017

**Photo Number:** 143

**Description:** View of north and west walls. Quarry flooded.



---

## APPENDIX F1 QUARRIES PHOTOGRAPHIC LOG

---



*Photograph F1-29: Quarry 15 – km 67+600*

**Date:** September 8, 2017

**Photo Number:** 144

**Description:** View of the south and west walls.



*Photograph F1-30: Quarry 15 – km 67+600*

**Date:** September 8, 2017

**Photo Number:** 145

**Description:** View of the north and west walls. Accumulation of water inside the quarry.



---

## APPENDIX F1 QUARRIES PHOTOGRAPHIC LOG

---



*Photograph F1-31: Quarry 16 – km 70+400*

**Date:** September 8, 2017

**Photo Number:** 152

**Description:** View of the south and west walls. Presence of loose rocks on steep wall.



*Photograph F1-32: Quarry 16 – km 70+400*

**Date:** September 8, 2017

**Photo Number:** 153

**Description:** View of the east wall. Presence of loose rocks on steep wall.



---

## APPENDIX F1 QUARRIES PHOTOGRAPHIC LOG

---



*Photograph F1-33: Quarry 17 – km 72+800*

**Date:** September 8, 2017

**Photo Number:** 155

**Description:** Looking at the north and west walls.



*Photograph F1-34: Quarry 17 – km 72+800*

**Date:** September 8, 2017

**Photo Number:** 154

**Description:** Looking at the south wall.