



## APPENDIX F1 QUARRIES PHOTOGRAPHIC LOG



*Photograph F1-35: Quarry 18 – km 80+200*

**Date:** September 8, 2017

**Photo Number:** 162

**Description:** View of the south wall.



*Photograph F1-36: Quarry 18 – km 80+200*

**Date:** September 8, 2017

**Photo Number:** 163

**Description:** Looking at the north and west walls.



## APPENDIX F1 QUARRIES PHOTOGRAPHIC LOG



*Photograph F1-37: Quarry 19 – km 84+300*

**Date:** September 8, 2017

**Photo Number:** 170

**Description:** Looking at the north and west walls.



*Photograph F1-38: Quarry 19 – km 84+300*

**Date:** September 8, 2017

**Photo Number:** 171

**Description:** Looking at the north and east walls.



---

## APPENDIX F1 QUARRIES PHOTOGRAPHIC LOG

---



*Photograph F1-39: Quarry 20 – km 89+550*

**Date:** September 8, 2017

**Photo Number:** 176

**Description:** Looking at the north and west walls.



*Photograph F1-40: Quarry 20 – km 89+550*

**Date:** September 8, 2017

**Photo Number:** 177

**Description:** Looking at the north and east wall.



---

## APPENDIX F1 QUARRIES PHOTOGRAPHIC LOG

---



*Photograph F1-41: Quarry 21 – km 93+400*

**Date:** September 8, 2017

**Photo Number:** 178

**Description:** Looking at the south and east walls.



*Photograph F1-42: Quarry 21 – km 93+400*

**Date:** September 8, 2017

**Photo Number:** 179

**Description:** Looking at the north and west walls.



## APPENDIX F1 QUARRIES PHOTOGRAPHIC LOG



Photograph F1-43: Quarry 22 – km 99+200

Date: September 8, 2017

Photo Number: 184

Description: View of the south and west walls.



Photograph F1-44: Quarry 22 – km 99+200

Date: September 8, 2017

Photo Number: 185

Description: Looking at the north and west walls.



---

## APPENDIX F1 QUARRIES PHOTOGRAPHIC LOG

---



*Photograph F1-45: Quarry 23 (Airstrip Quarry)*

**Date:** September 8, 2017

**Photo Number:** 193

**Description:** Looking at the north wall.



*Photograph F1-46: Quarry 23 (Airstrip Quarry)*

**Date:** September 8, 2017

**Photo Number:** 194

**Description:** Looking at the south wall.



## APPENDIX F1 QUARRIES PHOTOGRAPHIC LOG



*Photograph F1-47: Quarry 23 (Airstrip Quarry)*

**Date:** September 8, 2017

**Photo Number:** 197

**Description:** Looking at the north wall. Presence of loose rocks along steep wall.



*Photograph F1-48: Quarry 23 (Airstrip Quarry)*

**Date:** September 8, 2017

**Photo Number:** 196

**Description:** Looking at the north and east walls.



---

## APPENDIX F1 QUARRIES PHOTOGRAPHIC LOG

---



*Photograph F1-49: Quarry 23 (Airstrip Quarry)*

**Date:** September 8, 2017

**Photo Number:** 195

**Description:** Looking at the south and east walls.

[https://golderassociates.sharepoint.com/sites/16104g/preparation\\_of\\_deliverables/rev0/annexes\\_inspection\\_2017/appendix\\_f - quarries/f1 - quarries photographic log 2017.docx](https://golderassociates.sharepoint.com/sites/16104g/preparation_of_deliverables/rev0/annexes_inspection_2017/appendix_f - quarries/f1 - quarries photographic log 2017.docx)



---

2017 ANNUAL GEOTECHNICAL INSPECTION  
MEADOWBANK GOLD MINE, NUNAVUT

---

## APPENDIX F2

### Quarries and Eskers along Amaruq Road Photographic Log



## APPENDIX F2 ESKERS AND QUARRIES ALONG AMARUQ ROAD PHOTOGRAPHIC LOG



*Photograph F2-1 Eskers and Quarries 1 – km 15+000*

**Date:** September 11, 2017

**Photo Number:** 481

**Description:** View of esker #1. Loose rock is present on the steep wall.



*Photograph F2-2 Eskers and Quarries 1 – km 15+000*

**Date:** September 11, 2017

**Photo Number:** 482

**Description:** View of esker #1. Loose rock is present on the steep wall.



## APPENDIX F2 ESKERS AND QUARRIES ALONG AMARUQ ROAD PHOTOGRAPHIC LOG



*Photograph F2-3 Eskers and Quarries 2 – km 25+000*

**Date:** September 11, 2017

**Photo Number:** 465

**Description:** View of esker #2. General good condition but some steep walls and loose rocks.



*Photograph F2-4 Eskers and Quarries 2 – km 25+000*

**Date:** September 11, 2017

**Photo Number:** 466

**Description:** View of esker #2. General good condition but some steep walls and loose rocks.



## APPENDIX F2 ESKERS AND QUARRIES ALONG AMARUQ ROAD PHOTOGRAPHIC LOG



Photograph F2-5 Eskers and Quarries 3 – km 35+000

**Date:** September 10, 2017

**Photo Number:** 426

**Description:** View of the rock quarry at km 35. Unstable walls subject to rockfalls.



Photograph F2-6 Eskers and Quarries 3 – km 35+000

**Date:** September 10, 2017

**Photo Number:** 427

**Description:** View of the rock quarry at km 35. Unstable walls subject to rockfalls.



## APPENDIX F2 ESKERS AND QUARRIES ALONG AMARUQ ROAD PHOTOGRAPHIC LOG



*Photograph F2-7 Eskers and Quarries 3 – km 35+000*

**Date:** September 10, 2017

**Photo Number:** 428

**Description:** View of the rock quarry at km 35. Unstable walls subject to rockfalls.



*Photograph F2-8 Eskers and Quarries 4 – km 46+000*

**Date:** September 10, 2017

**Photo Number:** 401

**Description:** View of esker #3. The 2-m high steep soil slopes are unstable.



## APPENDIX F2 ESKERS AND QUARRIES ALONG AMARUQ ROAD PHOTOGRAPHIC LOG



*Photograph F2-9 Eskers and Quarries 4 – km 46+000*

**Date:** September 10, 2017

**Photo Number:** 402

**Description:** View of esker #3. The 2-m high steep soil slopes are unstable.



*Photograph F2-10 Eskers and Quarries 4 – km 46+000*

**Date:** September 10, 2017

**Photo Number:** 403

**Description:** View of esker #3. The 2-m high steep soil slopes are unstable.



## APPENDIX F2 ESKERS AND QUARRIES ALONG AMARUQ ROAD PHOTOGRAPHIC LOG



*Photograph F2-11 Eskers and Quarries 4 – km 46+000*

**Date:** September 10, 2017

**Photo Number:** 404

**Description:** View of esker #3. The 2-m high steep soil slopes are unstable.



*Photograph F2-12 Eskers and Quarries 5 – km 52+000*

**Date:** September 10, 2017

**Photo Number:** 388

**Description:** View of the rock quarry at km 52. In good conditions with loose blocks on the north wall.



## APPENDIX F2 ESKERS AND QUARRIES ALONG AMARUQ ROAD PHOTOGRAPHIC LOG



*Photograph F2-13 Eskers and Quarries 5 – km 52+000*

**Date:** September 10, 2017

**Photo Number:** 389

**Description:** View of the rock quarry at km 52. In good conditions with loose blocks on the north wall.



*Photograph F2-14 Eskers and Quarries 6 – km 62+000*

**Date:** September 10, 2017

**Photo Number:** 375

**Description:** View of esker #6C (north borrow pit). The 2-m high steep soil slopes are unstable.



## APPENDIX F2 ESKERS AND QUARRIES ALONG AMARUQ ROAD PHOTOGRAPHIC LOG



*Photograph F2-15 Eskers and Quarries 6 – km 62+000*

**Date:** September 10, 2017

**Photo Number:** 376

**Description:** View of esker #6C (north borrow pit). The 2-m high steep soil slopes are unstable.



*Photograph F2-16 Eskers and Quarries 6 – km 62+000*

**Date:** September 10, 2017

**Photo Number:** 377

**Description:** View of esker #6B. In good condition.



---

## APPENDIX F2 ESKERS AND QUARRIES ALONG AMARUQ ROAD PHOTOGRAPHIC LOG

---



*Photograph F2-17 Eskers and Quarries 6 – km 62+000*

**Date:** September 10, 2017

**Photo Number:** 378

**Description:** View of eskers #6A and #6D. In good condition.



---

**2017 ANNUAL GEOTECHNICAL INSPECTION  
MEADOWBANK GOLD MINE, NUNAVUT**

---

## **APPENDIX G**

### **Bulk Fuel Facilities**




---

2017 ANNUAL GEOTECHNICAL INSPECTION  
MEADOWBANK GOLD MINE, NUNAVUT

---

## APPENDIX G1

### Baker Lake Tank Farm Photographic Log



## NOTE

---

GRID REFERENCE: NAD 83, UTM ZONE 14.

## REFERENCE

BASE PLAN PROVIDED BY AEM LTD. IN  
"PORTAGE\_GOOSE\_VAULT\_END2018\_LOM2013\_V4D-WITH  
LABEL.dwg RECEIVED OCTOBER 7, 2013

---

CONSULTANT

AGNICO EAGLE



XXXX-MM-DD

---

BRBRABER M. Habersetzer

---

DESIGN S. Betnesky

REVIEW M. Hüberl et al.

---

APPROVED

---

**TITLE E**

## TITLE

## TANK FARM BAKER LAKE

---

**PROJECT No.**

---

PHAS

Rev

---

**FIGURE**

5 mm IF THIS MEASUREMENT DOES NOT MATCH WHAT IS SHOWN, THE SHEET SIZE HAS BEEN MODIFIED FROM: ANSI A



## APPENDIX G1 BAKER LAKE TANK FARM PHOTOGRAPHIC LOG



*Photograph G1-1 Baker Lake Tank Farm*

**Date:** September 7, 2017

**Photo Number:** 098

**Description:** From the south side of Tank 1, looking southeast at Tanks 1, 2, 3, and 4. Presence of water ponding.



*Photograph G1-2 Baker Lake Tank Farm*

**Date:** September 7, 2017

**Photo Number:** 097

**Description:** Looking at the southwestern corner of Tank 1.