



---

## APPENDIX H2

### DIVERSION DITCH AND ITS EROSION AND SEDIMENT PROTECTION STRUCTURE PHOTOGRAPHIC LOG

---



*Photograph H2-7 Diversion Ditch and its Sediment and Erosion Protection Structure*

**Date:** September 8, 2017

**Photo Number:** 243

**Description:** From the northern diversion ditch looking southeast.



*Photograph H2-8 Diversion Ditch and its Sediment and Erosion Protection Structure*

**Date:** September 8, 2017

**Photo Number:** 244

**Description:** From the northern diversion ditch looking west.



---

## APPENDIX H2

### DIVERSION DITCH AND ITS EROSION AND SEDIMENT PROTECTION STRUCTURE PHOTOGRAPHIC LOG

---



*Photograph H2-9 Diversion Ditch and its Sediment and Erosion Protection Structure*

**Date:** September 8, 2017

**Photo Number:** 245

**Description:** From the northern diversion ditch looking east.



*Photograph H2-10 Diversion Ditch and its Sediment and Erosion Protection Structure*

**Date:** September 8, 2017

**Photo Number:** 246

**Description:** From the northern diversion ditch looking west.



---

## APPENDIX H2

### DIVERSION DITCH AND ITS EROSION AND SEDIMENT PROTECTION STRUCTURE PHOTOGRAPHIC LOG

---



*Photograph H2-11 Diversion Ditch and its Sediment and Erosion Protection Structure*

**Date:** September 8, 2017

**Photo Number:** 247

**Description:** From 637281E/7216790N, looking north. View of the western diversion ditch.



*Photograph H2-12 Diversion Ditch and its Sediment and Erosion Protection Structure*

**Date:** September 8, 2017

**Photo Number:** 248

**Description:** From 637281E/7216790N, looking south at the western diversion ditch.



---

## APPENDIX H2

### DIVERSION DITCH AND ITS EROSION AND SEDIMENT PROTECTION STRUCTURE PHOTOGRAPHIC LOG

---



*Photograph H2-13 Diversion Ditch and its Sediment and Erosion Protection Structure*

**Date:** September 8, 2017

**Photo Number:** 249

**Description:** From 637251E/7216171N, looking north at the western diversion ditch.



*Photograph H2-14 Diversion Ditch and its Sediment and Erosion Protection Structure*

**Date:** September 8, 2017

**Photo Number:** 250

**Description:** From 637251E/7216171N, looking west at the western diversion ditch and its retention basin.



---

**APPENDIX H2**  
**DIVERSION DITCH AND ITS EROSION AND SEDIMENT PROTECTION**  
**STRUCTURE PHOTOGRAPHIC LOG**

---



*Photograph H2-15 Diversion Ditch and its Sediment and Erosion Protection Structure*

**Date:** September 8, 2017

**Photo Number:** 251

**Description:** From 637074E/7216157N, looking east at the western diversion ditch.



*Photograph H2-16 Diversion Ditch and its Sediment and Erosion Protection Structure*

**Date:** September 8, 2017

**Photo Number:** 252

**Description:** From 637074E/7216157N, looking west at the western diversion ditch.



---

## APPENDIX H2

### DIVERSION DITCH AND ITS EROSION AND SEDIMENT PROTECTION STRUCTURE PHOTOGRAPHIC LOG

---



*Photograph H2-17 Diversion Ditch and its Sediment and Erosion Protection Structure*

**Date:** September 8, 2017

**Photo Number:** 253

**Description:** From 0+000, looking southwest at the western diversion ditch.

c:\users\mhabersetze\golder associates\1784282, aem geotech inspection meadowbank - preparation of deliverables\rev0\annexes inspection 2017\appendix h - other facilities\h2 - diversion ditch\h2-diversion ditch photo log 2017.docx



---

**2017 ANNUAL GEOTECHNICAL INSPECTION  
MEADOWBANK GOLD MINE, NUNAVUT**

---

## **APPENDIX H3**

### **RSF Till Plug Photographic Log**



## APPENDIX H3 RSF TILL PLUG PHOTOGRAPHIC LOG



*Photograph H3-1 RSF Till Plug*

**Date:** September 8, 2017

**Photo Number:** 238

**Description:** From the south side of NP2 Lake (north of the diversion ditch) looking west at the RSF till plug.



*Photograph H3-2 RSF Till Plug*

**Date:** September 8, 2017

**Photo Number:** 235

**Description:** From the south side of NP2 Lake (south of the diversion ditch) looking west at the RSF till plug.



## APPENDIX H3 RSF TILL PLUG PHOTOGRAPHIC LOG



*Photograph H3-3 RSF Till Plug*

**Date:** September 8, 2017

**Photo Number:** 236

**Description:** From the south side of NP2 Lake (south of the diversion ditch) looking southeast at the RSF till plug.



*Photograph H3-4 RSF Till Plug*

**Date:** September 8, 2017

**Photo Number:** 237

**Description:** From the south side of NP2 Lake (south of the diversion ditch) looking northwest at the RSF till plug.



---

## APPENDIX H3

### RSF TILL PLUG PHOTOGRAPHIC LOG

---

<https://golderassociates.sharepoint.com/sites/16104g/preparation of deliverables/rev0/annexes inspection 2017/appendix h - other facilities/h3- rsf till plug/h3 - rsf till plug photo log 2017.docx>



---

**2017 ANNUAL GEOTECHNICAL INSPECTION  
MEADOWBANK GOLD MINE, NUNAVUT**

---

## **APPENDIX H4**

### **Diffusers Photographic Log**



---

## APPENDIX H4 DIFFUSERS PHOTOGRAPHIC LOG

---



*Photograph H4-1 Diffusers – Vault Diffuser*

**Date:** September 8, 2017

**Photo Number:** 216

**Description:** Looking at the Diffuser at Vault. In good condition.

[https://golderassociates.sharepoint.com/sites/16104g/preparation\\_of\\_deliverables/rev0/annexes\\_inspection\\_2017/appendix\\_h - other facilities/h4 - diffusers/h4-diffusers\\_photo\\_log\\_2017.docx](https://golderassociates.sharepoint.com/sites/16104g/preparation_of_deliverables/rev0/annexes_inspection_2017/appendix_h - other facilities/h4 - diffusers/h4-diffusers_photo_log_2017.docx)



---

2017 ANNUAL GEOTECHNICAL INSPECTION  
MEADOWBANK GOLD MINE, NUNAVUT

---

## APPENDIX H5

### Landfill Photographic Log



## APPENDIX H5 LANDFILL PHOTOGRAPHIC LOG



*Photograph H5-1 Landfill*

**Date:** September 8, 2017

**Photo Number:** 265

**Description:** From 638857E/7215767N, looking north at the landfill.



*Photograph H5-2 Landfill*

**Date:** September 8, 2017

**Photo Number:** 266

**Description:** From 638857E/7215767N, looking northwest at the landfill.



---

**2017 ANNUAL GEOTECHNICAL INSPECTION  
MEADOWBANK GOLD MINE, NUNAVUT**

---

## **APPENDIX H6**

### **Contaminated Soil Storage and Bioremedial Landfarm Facility Photographic Log**



---

**APPENDIX H6**  
**CONTAMINATED SOIL STORAGE AND BIOREMEDIATION LANDFARM FACILITY**  
**PHOTOGRAPHIC LOG**

---



*Photograph H6-1 Contaminated Soil Storage and Bioremedial Landfarm Facility*

**Date:** September 8, 2017

**Photo Number:** 256

**Description:** Looking southwest at the Contaminated Soil Storage and Bioremedial Landfarm Facility located within the South Cell of the TSF.



*Photograph H6-2 Contaminated Soil Storage and Bioremedial Landfarm Facility*

**Date:** September 8, 2017

**Photo Number:** 255

**Description:** From the WTP, looking northeast at the Contaminated Soil Storage and Bioremedial Landfarm Facility located within the South Cell of the TSF.



## APPENDIX H6 CONTAMINATED SOIL STORAGE AND BIOREMEDIAL LANDFARM FACILITY PHOTOGRAPHIC LOG



*Photograph H6-3 Contaminated Soil Storage and Bioremedial Landfarm Facility*

**Date:** September 8, 2017

**Photo Number:** 263

**Description:** From the northeast extremity of the South Cell, looking northwest at the new Contaminated Soil Storage and Bioremedial Landfarm Facility located within the South Cell of the TSF, north of Central Dike.



*Photograph H6-4 Contaminated Soil Storage and Bioremedial Landfarm Facility*

**Date:** September 8, 2017

**Photo Number:** 264

**Description:** From the northeast extremity of the South Cell, looking west at the new Contaminated Soil Storage and Bioremedial Landfarm Facility located within the South Cell of the TSF, north of Central Dike.



---

**2017 ANNUAL GEOTECHNICAL INSPECTION  
MEADOWBANK GOLD MINE, NUNAVUT**

---

## **APPENDIX H7**

### **Stormwater Pond Photographic Log**



---

## APPENDIX H7 STORMWATER POND PHOTOGRAPHIC LOG

---



*Photograph H7-1 Stormwater Pond*

**Date:** September 8, 2017

**Photo Number:** 204

**Description:** From the northern side of the pond, looking west at Stormwater Pond and crusher ramp.



*Photograph H7-2 Stormwater Pond*

**Date:** September 8, 2017

**Photo Number:** 205

**Description:** From the northern side of the pond, looking south at Stormwater Pond and the crusher ramp.



---

## APPENDIX H7 STORMWATER POND PHOTOGRAPHIC LOG

---



*Photograph H7-3 Stormwater Pond*

**Date:** September 8, 2017

**Photo Number:** 206

**Description:** From the northern side of the pond, looking southeast at Stormwater Pond.

<https://golderassociates.sharepoint.com/sites/16104g/preparation of deliverables/rev0/annexes inspection 2017/appendix h - other facilities/h7 - stormwater pond/h7 stormwater pond photo log 2017.docx>



---

**2017 ANNUAL GEOTECHNICAL INSPECTION  
MEADOWBANK GOLD MINE, NUNAVUT**

---

## **APPENDIX H8**

### **Airstrip Photographic Log**



---

## APPENDIX H8 AIRSTRIPE PHOTOGRAPHIC LOG

---



*Photograph H8-1 Airstrip*

**Date:** September 8, 2017

**Photo Number:** 257

**Description:** Looking west at the extremity of the airstrip located within Third Portage Lake.



*Photograph H8-2 Airstrip*

**Date:** September 8, 2017

**Photo Number:** 258

**Description:** From the extremity of the airstrip located within Third Portage Lake, looking southeast.



---

## APPENDIX H8

### AIRSTrip PHOTOGRAPHIC LOG

---



*Photograph H8-3 Airstrip*

**Date:** September 8, 2017

**Photo Number:** 262

**Description:** From the northeast side of the airstrip looking northwest.



*Photograph H8-4 Airstrip*

**Date:** September 8, 2017

**Photo Number:** 261

**Description:** From the northeast side of the airstrip looking southeast.



## APPENDIX H8 AIRSTrip PHOTOGRAPHIC LOG



*Photograph H8-5 Airstrip*

**Date:** September 8, 2017

**Photo Number:** 208

**Description:** From the southeast side of the airstrip looking northwest.



*Photograph H8-6 Airstrip*

**Date:** September 8, 2017

**Photo Number:** 207

**Description:** From the southeast side of the airstrip looking east.

At Golder Associates we strive to be the most respected global company providing consulting, design, and construction services in earth, environment, and related areas of energy. Employee owned since our formation in 1960, our focus, unique culture and operating environment offer opportunities and the freedom to excel, which attracts the leading specialists in our fields. Golder professionals take the time to build an understanding of client needs and of the specific environments in which they operate. We continue to expand our technical capabilities and have experienced steady growth with employees who operate from offices located throughout Africa, Asia, Australasia, Europe, North America, and South America.

Africa	+ 27 11 254 4800
Asia	+ 86 21 6258 5522
Australasia	+ 61 3 8862 3500
Europe	+ 356 21 42 30 20
North America	+ 1 800 275 3281
South America	+ 55 21 3095 9500

[solutions@golder.com](mailto:solutions@golder.com)  
[www.golder.com](http://www.golder.com)

**Golder Associés Ltée**  
**7250, rue du Mile End, 3e étage**  
**Montréal (Québec) H2R 3A4**  
**Canada**  
**T: +1 (514) 383 0990**