

NWB Annual Report

Year being reported: 2011 ▼

License No: 8BW-CLY1216

Issued Date: February 28, 2012

Expiry Date: March 1, 2016

Project Name: Clyde River Road Construction Project

Licensee: Qikiqtaaluk Corporation

Mailing Address: PO-Box 1228
Iqaluit, Nu
X0A 0H0

Name of Company filing Annual Report (if different from Name of Licensee please clarify relationship between the two entities, if applicable):

Qikiqtaaluk Environmental Inc.

Relationship: Consultant & owned 51% by Qikiqtaaluk Corporation

General Background Information on the Project (*optional):

Licence Requirements: the licensee must provide the following information in accordance with

Part B

▼ Item 1

▼

A summary report of water use and waste disposal activities, including, but not limited to: methods of obtaining water; sewage and greywater management; drill waste management; solid and hazardous waste management.

Water Source(s):

No water was used during the reporting period

Water Quantity:

	Quantity Allowable Domestic (cu.m)
	Actual Quantity Used Domestic (cu.m)
	Quantity Allowable Drilling (cu.m)
	Total Quantity Used Drilling (cu.m)

Waste Management and/or Disposal

- Solid Waste Disposal
- Sewage
- Drill Waste
- Greywater
- Hazardous
- Other:

Additional Details:

damaged or crushed culverts were disposed of at the municipal landfill, un
damaged removed culverts were donated to the municipality

A list of unauthorized discharges and a summary of follow-up actions taken.

Spill No.: N/A (as reported to the Spill Hot-line)

Date of Spill: Date of Notification to an Inspector: Additional Details: (impacts to water, mitigation measures, short/long term monitoring, etc)
Revisions to the Spill Contingency PlanNo Spill Contingency Plan (SCP) submitted or approved Additional Details:
Revisions to the Abandonment and Restoration PlanAR plan submitted and approved - no revision required or proposed Additional Details:
Progressive Reclamation Work Undertaken

Additional Details (i.e., work completed and future works proposed)

Remediation work was undertaken on the road. Report is attached
Results of the Monitoring Program including:**The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where sources of water are utilized;**Select Additional Details:
No monitoring was done
The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where wastes associated with the licence are deposited;Details described below Additional Details:
Damaged or crushed culverts were disposed of at the municipal landfill.
Coordinates for the municipal landfill are 70° 28' 12.8" 68° 36' 50.4"

Results of any additional sampling and/or analysis that was requested by an Inspector

No additional sampling requested by an Inspector or the Board

Additional Details: (date of request, analysis of results, data attached, etc)

Any other details on water use or waste disposal requested by the Board by November 1 of the year being reported.

No additional sampling requested by an Inspector or the Board

Additional Details: (Attached or provided below)

Any responses or follow-up actions on inspection/compliance reports

Select

Additional Details: (Dates of Report, Follow-up by the Licensee)

Any additional comments or information for the Board to consider

The abandonment and restoration plan was implemented. The road was monitored for signs of sedimentation into fish bearing waters during this period and any issues were addressed.

Date Submitted:

April 30, 2015

Submitted/Prepared by:

Greg Johnson

Contact Information:

Tel: 514-940-3332

Fax: 514-940-3435

email: gjohnson@qenv.ca