

## Appendix B      Waterbody Crossing Photographs

Appendix B: Waterbody Crossing Photographs

**Photo 1**

**West aspect of constructed CRS-1 crossing at Km 0 of the access road, marine Tariuraq Inlet on the left side of photo and the freshwater lake on the right side; no culverts installed.**

**Photo 2**

**South aspect from the constructed CRS-1 crossing; marine Tariuraq Inlet in background.**

Appendix B: Waterbody Crossing Photographs

---



**Photo 3** North aspect from constructed CRS-1 crossing; the freshwater lake in background.



**Photo 4** Substrate and large riprap on south shore of CRS-1 crossing, the marine Tariuraq Inlet in background; south aspect.

**Photo 5**

**Substrate and large riprap of north shore of CRS-1 crossing, the freshwater lake on right side of photo; west aspect.**

**Photo 6**

**South aspect from the freshwater lake with CRS-1 crossing and Tariuraq Inlet in background.**

Appendix B: Waterbody Crossing Photographs

---



**Photo 7** CRS-2 crossing at Km 1.8 of the access road, north aspect with installed culvert and downstream flow pattern.



**Photo 8** CRS-2 crossing west aspect with installed culvert and upstream pond flow pattern.