

WATER LICENCE INSPECTION FORM

☒ Original

☐ Follow-Up Report

Licensee	Licensee Representative
University of Exeter	Thomas Brody
Licence No. / Expiry	Representative's Title
8WLC-FDI1415	Researcher
Land / Other Authorizations	Land / Other Authorizations
N2014N0006	
Date of Inspection	Inspector
July 5, 2022	Joseph Monteith
Activities Inspected	
<input checked="" type="checkbox"/> Camp	<input type="checkbox"/> Drilling
<input type="checkbox"/> Roads/Hauling	<input type="checkbox"/> Mining
	<input type="checkbox"/> Construction
	<input checked="" type="checkbox"/> Reclamation
	<input type="checkbox"/> Fuel Storage
	<input type="checkbox"/> Other:

Conditions:	A- Acceptable	U-Unacceptable	C-Concern	NI-Not Inspected	NA- Not applicable
PART:	Condition		Observation No.*		
A: SCOPE, DEFINITIONS AND ENFORCEMENT					
B: GENERAL CONDITIONS					
C: CONDITIONS APPLYING TO SECURITY					
D: CONDITIONS APPLYING TO WATER USE	A		1		
E: CONDITIONS APPLYING TO WASTE DISPOSAL AND MANAGEMENT	A		2-4		
F: CONDITIONS APPLYING TO MODIFICATIONS					
G: CONDITIONS APPLYING TO CONSTRUCTION					
H: CONDITIONS APPLYING TO EMERGENCY RESPONSE AND CONTINGENCY PLANNING					
I: CONDITIONS APPLYING TO ABANDONMENT, RECLAMATION AND CLOSURE PLANNING	A		5		
J: CONDITIONS APPLYING TO MONITORING					
SCHEDULES					
*The item number corresponds with specific conditions within the licence and the observation number corresponds with specific comments provided below.					
Samples taken by Inspector:		Location(s): N66° 49' 10.1" W63° 52' 59.3			
<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No					

Background			
A water license application was submitted on			
Inspector Statement			
On July 5, 2022, a Water License inspection was conducted by Water Resource Officer(WRO) Joseph Monteith at the site where 8WLC-FDI1415 was located in Schei Peninsula, Axel Heiberg Island,NU.			
Water Use			
1. No signs of water use, or disturbance			
Waste			
2. No signs of sump pit			
3. No signs of solid wastes			
4. No signs of spills			
Reclamation			
5. No signs of structures, equipment or spills.			
SECTION 1	<input checked="" type="checkbox"/> Comments	<input type="checkbox"/> Non-Compliance with Act or Licence	<input type="checkbox"/> Action Required
Site appears to have been reclaimed to near pristine conditions. I recommend Closure of the water license 8WLC-FDI1415			
SECTION 2	<input type="checkbox"/> Comments	<input checked="" type="checkbox"/> Non-Compliance with Act or Licence	<input type="checkbox"/> Action Required

Licensee or Representative	Inspector's Name
Thomas Brodey	Joseph Monteith
Signature	Signature
Date	Date
	November 18, 2022

CC: Licensing Department, NWB
Jeremy Fraser, Manager of Field Operation

PHOTO LOG


Date	Camera	Inspector
July 5, 2022	Samsung Galaxy S9	Joseph Monteith
Photo Log #1	Location	
Photo 1	Schei Peninsula, Qikiqtani Region, Nunavut	
<div></div>		
Description: Basemap routes, tracks and points. General proximity of observed culvert		



Photo Log #

Location

Photo 2

N66° 49' 10.1" W63° 52' 59.3




Description: Campsite was located at the top right hand side of the lake.

Photo Log #

Location

Photo 3

N66° 49' 10.1" W63° 52' 59.3



Description: No signs of structures, equipment or spills in the general vicinity of the camp site.



Photo Log #

Location

Photo 4

N66° 49' 10.1" W63° 52' 59.3



Description: No signs of structures, equipment or spills in the general vicinity of the camp site.