



WATER LICENCE INSPECTION FORM

☐ Original
☐ Follow-Up Report

Licensee	Licensee Representative
GEOLOGICAL SURVEY OF CANADA	N/A
Licence No. / Expiry	Representative's Title
8WLC-GEM1819	
Land / Other Authorizations	Land / Other Authorizations
N2018N0004	
Date of Inspection	Inspector
July 10, 2018	Jonathan Mesher
Activities Inspected	
<input checked="" type="checkbox"/> Camp	<input type="checkbox"/> Drilling
<input type="checkbox"/> Roads/Hauling	<input type="checkbox"/> Mining
	<input type="checkbox"/> Construction
	<input type="checkbox"/> Reclamation
	<input type="checkbox"/> Fuel Storage
	<input type="checkbox"/> Other:

Conditions:	A- Acceptable	U-Unacceptable	C-Concern	NI-Not Inspected	NA- Not applicable
PART:	Item No. *	Condition	Observation No. *		
A: SCOPE, DEFINITIONS AND ENFORCEMENT		A			
B: GENERAL CONDITIONS		A			
C: CONDITIONS APPLYING TO SECURITY		A			
D: CONDITIONS APPLYING TO WATER USE		A			
E: CONDITIONS APPLYING TO WASTE DISPOSAL AND MANAGEMENT		C			
F: CONDITIONS APPLYING TO MODIFICATIONS		A			
G: CONDITIONS APPLYING TO CONSTRUCTION		A			
H: CONDITIONS APPLYING TO EMERGENCY RESPONSE AND CONTINGENCY PLANNING		A			
I: CONDITIONS APPLYING TO ABANDONMENT, RECLAMATION AND CLOSURE PLANNING		A			
J: CONDITIONS APPLYING TO MONITORING		A			
SCHEDULES		A			
*The item number corresponds with specific conditions within the licence and the observation number corresponds with specific comments provided below.					
Samples taken by Inspector:	Location(s):				
<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No					

SECTION 1	<input checked="" type="checkbox"/> Comments (s. __)	<input type="checkbox"/> Non-Compliance with Act or Licence (s. __)	<input type="checkbox"/> Action Required (s. __)
A Inspection was conducted of the Water Licence 8WLC-GEM1819 by Jonathan Mesher and Joseph Monteith Of CIRNAC on July 10, 2018.			
At the time of this inspection the Licensee was not on site due to weather delays, the only sign of activity on site was the storage of approximately 129 barrels of fuel within a berm.			
<ul style="list-style-type: none">The secondary containment was in poor condition at the time of the inspection, it is recommended that if the licensee plans to leave fuel on site that a more robust secondary containment be used. Without the ability to do required maintenance or inspect the pop-up berms regularly they often fail to contain water or fuel.			
SECTION 2	<input type="checkbox"/> Comments	<input type="checkbox"/> Non-Compliance with Act or Licence	<input type="checkbox"/> Action Required
Click here to enter text.			
SECTION 3	<input type="checkbox"/> Comments	<input type="checkbox"/> Non-Compliance with Act or Licence	<input type="checkbox"/> Action Required
Click here to enter text.			

Licensee or Representative	Inspector's Name
GEOLOGICAL SURVEY OF CANADA	Jonathan Mesher
Signature	Signature
Date	Date



August 10, 2018

Office Use Only: Follow-up report to be issued by Inspector

☐ Yes ☐ No

CC: Licensing Department, NWB
Erik Allain, Manager of Field Operations,



Fuel storage at 8WLC-GEM1819