

INSPECTION FORM

Original	
Follow-Up	Report

Action Required

Licensee				Licensee Repre	Sentativ	-				
Mars Society			srupert@marssociety.org							
Licence No. / Expiry				Representative	e's Title					
8WLC-LHA1718										
Land / Other Authorizations										
N2012N0018, 58H	1 7-2									
Date of Inspection				Inspector						
30 June 2017	0 June 2017 Justin HACK									
Activities Inspected	_			_						
	Drilling Other: Cam	מו	☐ Mining ☐ Construc ☐ Other:			ion Reclamation		☐ Fuel Storage		
<u>-</u>		-		_						
	ceptable	C	C - Concern	U - Unacceptab			Not Applicable		Not Insp	ected
Water Use	Condition	Comment	Site Condition	ns	Condit ion	Comme nt	Haz/Mat Manager	nent	Condition	Comment
Intake/Screen			Water Manag	ement Structures			Storage		Α	
Flow Measure. Device			Culverts / Brid	dges			Spills			
Source:			Drainage		А		Spill Plan			
Water Use:			Erosion / Sedi	ment	Α					
Recirculation (y /n)			Mitigation Me	easures			Administrative			
			Reclamation A	Activities			Records			
			Materials Stor	rage	Α		Reports			
Waste Disposal			Signage				Plans			
Waste Water							Notifications			
Solid Waste			Monitoring				Other			
Hazardous Waste			Sample Collec	ction / Analysis						
*The number in the comments field will correspond with specific comments provided below.										
Samples taken by Inspector:			Location(s): Qikiqtani Region, Nunavut							
Yes No										

SECTION 1 Background

Nunavut Water Authorization without a Licence 8WLC-LHA1718 was issued to Mars Society to authorize the use of 1m³ of water and the deposit of waste in support of scientific research and related activities at the Flashline Mars Arctic Research Station Project, located near the Haughton Crater on Devon Island, Nunavut. The coordinates for this activity are N75 25.882 and W89 49.408 and occur within the Eastern Devon Island Watershed Management Area.

Non-Compliance with Act or Licence

Inspector's Statement

Comments

On June 30, 2017 a water licence was conducted at this project to inspect all uses of water and deposits of waste. At the time of the inspection, I was informed that the scheduled activity on the site was delayed due to weather and during the inspection there was no activity on site.

Water Use

No water was being used. No water related infrastructure was apparent to inspect.

Waste Disposal

No sewage was being discharged on site. There was evidence on site that all waste was being contained in barrels. Secondary containment

Land Use

There were no concerns noted with the operation of this project in relation to Land Use Permit N2012N0018 and Lease #58H7-2. Both INAC Permits are in good standing.

	Indigenous and
T	Northern Affairs Canada

Inspector's Name	
Justin Hack	
Signature	
Justin Jank	
Date	
September 22, 2017	



Figure #1: Overview of camp



Figure #2: 5 Barrels of Fuel in secondary containment.