APPENDIX A

PHOTOGRAPHS

PART

OF

CLOSURE PLAN FOR

TAILINGS CONTAINMENT AREA

Prepared for

Kinross Gold Corporation

LUPIN OPERATION

LIST OF PHOTOS

Photo 1. Lupin tailings containment area, 2001 1
Photo 2. Looking north toward plant; Cell 5 in foreground and Cell 2 to the right 2
Photo 3. Cells 2 and 1 adjacent to Pond 1 in foreground..... 2
Photo 4. Looking southwest with Cell 3 bounded by Dams K & L and J Dam in lower left 3
Photo 5. Looking east with N Dam to the right and M Dam to the left..... 3
Photo 6. Dam 1a looking north..... 4
Photo 7. Dam 2 looking south..... 4
Photo 8. Dam 4 looking northeast, TCA on left 5
Photo 9. Dam 3D, looking west, Cell 1 to the right (not visible) 5
Photo 10, K Dam, looking northeast; Pond 2 to the left..... 6
Photo 11. M Dam, looking east with Pond 2 to the right..... 6
Photo 12. Tailings being covered with esker..... 7
Photo 13. Test pit excavations, September 2004..... 7
Photo 14. Test pit 1-1 in Cell 1, located at new pipe 7 installation 7
Photo 15. Test pit 1-2, in Cell 1, located at Pipe 1 location. Pipe removed and place in Cell 3..... 7
Photo 16. Test Pit 1-3 at test pad, south, excavation for pipe repositioning..... 8
Photo 17. Test Pit 1-3 at test pad, south, new pipe being backfilled 8
Photo 18. Test pit 1a-1 in Cell 1a; note coarser esker and wet base..... 8
Photo 19. Test pit 2-1 in northern section of Cell 2 with older tailings,; minor oxidation at tailings surface 8
Photo 20. Test Pit 2-2 in southern area of Cell 2..... 9
Photo 21. Test pit 2-3, in southern area of Cell 2, closer to mid point of cell..... 9
Photo 22. Test pit 3-1 in Cell 3. Minor oxidation of tailings. This part of cell was covered only weeks earlier. 9
Photo 23.Test pit 3b-1 in Cell 3b. 9

Photo 1. Lupin tailings containment area, 2001

Photo 2. Looking north toward plant; Cell 5 in foreground and Cell 2 to the right

Photo 3. Cells 2 and 1 adjacent to Pond 1 in foreground

Photo 4. Looking southwest with Cell 3 bounded by Dams K & L and J Dam in lower left

Photo 5. Looking east with N Dam to the right and M Dam to the left

Photo 6. Dam 1a looking north

Photo 7. Dam 2 looking south

Photo 8. Dam 4 looking northeast, TCA on left

Photo 9. Dam 3D, looking west, Cell 1 to the right (not visible)

Photo 10, K Dam, looking northeast; Pond 2 to the left

Photo 11. M Dam, looking east with Pond 2 to the right

Photo 12. Tailings being covered with esker

Photo 13. Test pit excavations, September 2004

Photo 14. Test pit 1-1 in Cell 1, located at new pipe 7 installation

Photo 15. Test pit 1-2, in Cell 1, located at Pipe 1 location. Pipe removed and place in Cell 3

Photo 16. Test Pit 1-3 at test pad, south, excavation for pipe repositioning

Photo 17. Test Pit 1-3 at test pad, south, new pipe being backfilled

Photo 18. Test pit 1a-1 in Cell 1a; note coarser esker and wet base

Photo 19. Test pit 2-1 in northern section of Cell 2 with older tailings,; minor oxidation at tailings surface

Photo 20. Test Pit 2-2 in southern area of Cell 2

Photo 21. Test pit 2-3, in southern area of Cell 2, closer to mid point of cell

Photo 22. Test pit 3-1 in Cell 3. Minor oxidation of tailings. This part of cell was covered only weeks earlier.

Photo 23.Test pit 3b-1 in Cell 3b.