WATER LICENCE INSPECTION FORM

☒ Original
☐ Follow-Up Report

Licensee	Licensee Representative
Geological Survey of Canada	Dr. Mary Sanborn-Barrie
Licence No. / Expiry	**Representative's Title**
8WLC-GBS1819	
Land / Other Authorizations	**Land / Other Authorizations**
Date of Inspection	**Inspector**
June 27, 2026	Joseph Monteith

Activities Inspected

☐ Camp ☐ Drilling ☐ Mining ☐ Construction ☐ Reclamation ☐ Fuel Storage
☐ Roads/Hauling ☐ Other: ☐ Other:

Conditions: **A- Acceptable** **U-Unacceptable** **C-Concern** **NI-Not Inspected** **NA- Not applicable**

PART:	Condition	Observation No.*
A: SCOPE, DEFINITIONS AND ENFORCEMENT		
B: GENERAL CONDITIONS	A	1
C: CONDITIONS APPLYING TO SECURITY		
D: CONDITIONS APPLYING TO WATER USE	A	2
E: CONDITIONS APPLYING TO WASTE DISPOSAL AND MANAGEMENT		3
F: CONDITIONS APPLYING TO MODIFICATIONS		
G: CONDITIONS APPLYING TO CONSTRUCTION		
H: CONDITIONS APPLYING TO EMERGENCY RESPONSE AND CONTINGENCY PLANNING		
I: CONDITIONS APPLYING TO ABANDONMENT, RECLAMATION AND CLOSURE PLANNING	A	4
J: CONDITIONS APPLYING TO MONITORING		
SCHEDULES		

**The item number corresponds with specific conditions within the licence and the observation number corresponds with specific comments provided below.*

Samples taken by Inspector:	Location(s): N72° 43' 43.8" W94° 19' 08.6"
☐ Yes ☒ No	

Background

Inspector Statement

On June 27, 2026 Resource Management Officer Joseph Monteith had conducted a site inspection of 8WLC-GBS1819 at Creswell Bay, Somerset Island, Qikqitani Region, Nunavut.

Inspection

General Condition

1. On May 24, 2019 an annual report was uploaded to the Nunavut Water Board website

https://public.nwb-oen.ca/registry/8%20MISCELLANEOUS/8WL/8WLC%20-%20Camp/8WLC-GBS1819%20Sanborn-Barrie/3%20TECH/1%20GENERAL%20(B)/2%20ANNUAL%20RPT/

Water Use

2. The licensee was authorized to withdraw 5 cubic metres per day

Waste Disposal Management

3. Grey Water Sump Pitt was excavated, and the overburden removed was placed back over the sump pitt.

Reclamation

4. The site has been reclaimed to the satisfaction of the inspector.

SECTION 1 ☒ **Comments** ☐ **Non-Compliance with Act or Licence** ☒ **Action Required**

Site appears to have been brought back to near pristine condition. I recommend final closure of the water license.

SECTION 2	☐ Comments	☒ Non-Compliance with Act or Licence	☐ Action Required

Licensee or Representative	Inspector's Name
	Joseph Monteith
Signature	**Signature**
Date	**Date**
	October 22, 2026

CC: Licensing Department, NWB
Jeremy Fraser, Manager of Field Operation

PHOTO LOG

Date	Camera	Inspector
June 27, 2026	Samsung Galaxy S12	Joseph Monteith
Photo Log #1		**Location**
Photo 1		N72° 43' 43.8" W94° 19' 08.6"



Description: site of camp was on the banks of the river on the right hand side. No signs of camp infrastructure and equipment.

Photo Log	Location
Photo 2	N72° 43' 43.8" W94° 19' 08.6"



Description: site of camp was banks of the river on the right hand side. No signs of camp infrastructure and equipment.