WATER LICENCE INSPECTION FORM

☒ Original
☐ Follow-Up Report

Licensee	Licensee Representative
Defense Research & Development Canada – Atlantic Research Centre	Patrick Sangster
Licence No. / Expiry	**Representative's Title**
8WLC-NWT2223	Environment, Health and Safety Officer
Land / Other Authorizations	**Land / Other Authorizations**
Date of Inspection	**Inspector**
Click here to enter text.	Joseph Monteith

Activities Inspected

☒ Camp ☐ Drilling ☐ Mining ☐ Construction ☐ Reclamation ☒ Fuel Storage
☐ Roads/Hauling ☐ Other: ☐ Other:

Conditions: **A- Acceptable** **U-Unacceptable** **C-Concern** **NI-Not Inspected** **NA- Not applicable**

PART:	Condition	Observation No.*
A: SCOPE, DEFINITIONS AND ENFORCEMENT		
B: GENERAL CONDITIONS	A	1
C: CONDITIONS APPLYING TO SECURITY		
D: CONDITIONS APPLYING TO WATER USE	A	2
E: CONDITIONS APPLYING TO WASTE DISPOSAL AND MANAGEMENT	A	3
F: CONDITIONS APPLYING TO MODIFICATIONS		
G: CONDITIONS APPLYING TO CONSTRUCTION		
H: CONDITIONS APPLYING TO EMERGENCY RESPONSE AND CONTINGENCY PLANNING	A	4
I: CONDITIONS APPLYING TO ABANDONMENT, RECLAMATION AND CLOSURE PLANNING		
J: CONDITIONS APPLYING TO MONITORING		
SCHEDULES		

**The item number corresponds with specific conditions within the licence and the observation number corresponds with specific comments provided below.*

Samples taken by Inspector:	Location(s): N74° 39' 37.3" W91° 17' 50.9"
☐ Yes ☒ No	

Background

Inspector Statement

On June 30, 2026 a Water License Inspection was conducted by Water Resource Officer, Joseph Monteith at Gascoyne Inlet(photo 1 &2), by Aerial Survey.

Inspection

General Condition

1. An annual report was submitted to the Nunavut Water Board for 2024.

https://public.nwb-oen.ca/registry/8%20MISCELLANEOUS/8WL/8WLC%20-%20Camp/8WLC-NWT2425/3%20TECH/1%20GENERAL%20(B)/2%20ANNUAL%20RPT/2024/250310%208WLC-NWT2324%20DRDC%20-%202024%20NWB%20Annual%20Report-IMLE.pdf

Water Use

2. Water Use is Authorized, location of the water withdrawal (photo 3).

Waste Disposal Management

3. Sewage Waste is backhauled to Resolute Bay, NU. An incinerator was observed in past inspections on site.

Spill Contingency

4. Secondary Containment was observed on site, with unknown storage within the secondary containment. A spill kit was observed next to it.

SECTION 1 ☒ **Comments** ☐ **Non-Compliance with Act or Licence** ☒ **Action Required**

No concerns

SECTION 2	☐ Comments	☒ Non-Compliance with Act or Licence	☐ Action Required

Licensee or Representative	Inspector's Name
	Joseph Monteith
Signature	**Signature**
Date	**Date**
	October 23, 2026

CC: Licensing Department, NWB
Jeremy Fraser, Manager of Field Operation

PHOTO LOG

Date	Camera	Inspector
Photo Log #1		**Location**
Photo 1		N74° 39' 37.3" W91° 17' 50.9"



Description: 15 structures, very minimal signs of windblown debris.

Photo Log	Location
Photo 2	N74° 39' 37.3" W91° 17' 50.9"



Description: 15 structures, very minimal signs of windblown debris.

Photo Log	Location
Photo 3	N74° 41' 02.4" W91° 19' 46.6"



Description: Location of water withdrawal. No signs of equipment used to withdrawal water.

Photo Log	Location
Photo 4	N74° 39' 37.3" W91° 17' 50.9"



Description: Observed a section of their camp which may contain fuel in secondary containment, and a spill kit next to it in the yellow drum.