From: Melissa Joy
To: Susan (RTX) Ball
Cc: John Craig; Phyllis Beaulieu
Subject: RE: 2BE-ARN Water Licence Inspection Report
Date: Thursday, October 11, 2012 12:31:08 PM

Hi Susan,

Thank you for the update and for removing the metal; weather looked a bit rough from your photo -hope everyone was ok.
So far, we have been unable to locate a copy of the (full) closure plan via our end of things. Were you able to locate one from your records?

Melissa

>>> "Ball, Susan (RTX)" <Susan.Ball@riotinto.com> 10/11/2012 12:55 PM >>>

Melissa

Just an FYI, that we have removed the metal from lake at the old Arnaq site (see attached). Turned out that it was a piece of metal transition strip for flooring. The metal has now been removed from site.

Were you able to locate a copy of the closure plan submitted via the AANDC Lands Division?

Regards,

Susan Ball
Land Manager

Rio Tinto
354-200 Granville Street, Vancouver, BC, V6C 1S4, Canada

T: 1.604.696.3449 F: 1.604.696.3401 M: 1.604.764.2375

From: Melissa Joy [mailto:Melissa.Joy@aandc-aadnc.gc.ca]
Sent: Friday, April 13, 2012 12:21 PM
To: Hodgkinson, Gary (RTX); Ball, Susan (RTX)
Cc: John Craig; Phyllis Beaulieu
Subject: RE: 2BE-ARN Water Licence Inspection Report

Susan,

I have had the opportunity to review your correspondence and submissions sent on Apr 4/12.

1. You asked for clarification on requirements for a "final closure report". While this is a term primarily applied to the closure requirements under the land use permit, in your water licence, this requirement is identified under Part B, item 2(iv) and Part H, item 3, where changes in operations (such as final closure and reclamation activities) are to be reported and submitted with the Annual Report. This usually occurs as a submission of a final closure plan/report as per an approved Abandonment and Restoration (A&R) plan. Occasionally, this information is simply included in a detailed Annual Report.

Approved Plans become part of the licence and the terms are to be carried out by the Licensee (the terms and conditions of the licence prevail where any conflicts occur), such as the details/status of items to be documented as listed under Kennecott's "Final Abandonment and Restoration Plan" and Addendum.

Therefore, if Kennecott submitted a "final closure report" or plan that did not cover these details, then they did not meet the requirements under the water licence. I have requested a copy of a plan submitted via the AANDC Lands Division -and can forward you a copy for your records once received. I will provide you with additional comments at that time.

What I look for are the documented completion regarding the details of removal and reclamation (i.e.: as per the terms and conditions of the water licence), such as sumps, latrine sites, waste inventories and waste manifests confirming proper disposal for hazardous wastes. As well, coordinates listings (camp/drill sites/fuel caches and laydown areas) and photographs of sites -preferably showing both before and after the cleanup.

2. Addendums to the A&R Plan and Spill Contingency Plan have been received -thank you. These have been forwarded to the NWB.

3. Unfortunately we do not have additional information regarding the metal debris, other than the photos submitted to you with the inspection report. GPS coordinates were taken at N67* 42' 35.7" and W91* 36' 19.4" ± 20m (taken from helo while hovering over site). Unfortunately I don't have further record regarding elevation as I had maxed out waypoint capacity on the gps at the time. I have attached several uncropped photos of the debris to assist you in identifying a workable scale (ie. distance from shoreline).

Please let me know if you have any questions regarding this information; I look forward to touching base with you once the Final Plan is received.

Best regards,
Melissa

Melissa Joy, B. Env Sc.
Water Resource Officer
Aboriginal Affairs & Northern Development Canada
P.O. Box 100, Iqaluit, NU, X0A 0H0
PH: (867) 975-4288
FAX: (867) 979-6445
email: melissa.joy@aandc.gc.ca

This transmission is confidential. Any unauthorized disclosure, distribution, or other use is strictly prohibited. If you have received this message in error, please contact sender immediately and delete this transmission and any attachments.
>>> "Ball, Susan (RTX)" <Susan.Ball@riotinto.com> 4/4/2012 3:39 PM >>>

Melissa

Attached is our response to your recent letter.

Regards,

Susan Ball
Land Manager

Rio Tinto
354-200 Granville Street, Vancouver, BC, V6C 1S4, Canada

T: 1.604.696.3449 F: 1.604.696.3401 M: 1.604.764.2375

From: Melissa Joy [mailto:Melissa.Joy@aandc-aadnc.gc.ca]
Sent: Monday, March 12, 2012 1:59 PM
To: Ball, Susan (RTX)
Cc: Phyllis Beaulieu; garry.hodgkinson@riotinto.com
Subject: 2BE-ARN Water Licence Inspection Report

Dear Ms. Ball,

Attached, please find the 2010 Inspection Report findings for the Arnak Property under water licence 2BE-ARN0507 (Kennecott Canada Exploration). There are several outstanding issues that need to be resolved before this licence can be closed; a response is expected within 30 days on receipt of this report (as per the inspection report).

A hard copy is also being sent to your office via registered mail. If you have any questions or concerns, please feel free to contact me.

Sincerely,
Melissa Joy

Melissa Joy, B. Env Sc.
Water Resource Officer
Aboriginal Affairs & Northern Development Canada
P.O. Box 100, Iqaluit, NU, X0A 0H0
PH: (867) 975-4288
FAX: (867) 979-6445
email: melissa.joy@aandc.gc.ca

This transmission is confidential. Any unauthorized disclosure,
distribution, or other use is strictly prohibited. If you have received
this message in error, please contact sender immediately and delete this
transmission and any attachments.

Avis:
Ce message et toute pièce jointe sont la propriété de Rio Tinto et sont destinés seulement aux personnes ou à l'entité à qui le message est adressé. Si vous avez reçu ce message par erreur, veuillez le détruire et en aviser l'expéditeur par courriel. Si vous n'êtes pas le destinataire du message, vous n'êtes pas autorisé à utiliser, à copier ou à divulguer le contenu du message ou ses pièces jointes en tout ou en partie.

Notice:
This message and any attachments are the property of Rio Tinto and are intended solely for the named recipients or entity to whom this message is addressed. If you have received this message in error please inform the sender via e-mail and destroy the message. If you are not the intended recipient you are not allowed to use, copy or disclose the contents or attachments in whole or in part.

Avis:
Ce message et toute pièce jointe sont la propriété de Rio Tinto et sont destinés seulement aux personnes ou à l'entité à qui le message est adressé. Si vous avez reçu ce message par erreur, veuillez le détruire et en aviser l'expéditeur par courriel. Si vous n'êtes pas le destinataire du message, vous n'êtes pas autorisé à utiliser, à copier ou à divulguer le contenu du message ou ses pièces jointes en tout ou en partie.

Notice:
This message and any attachments are the property of Rio Tinto and are intended solely for the named recipients or entity to whom this message is addressed. If you have received this message in error please inform the sender via e-mail and destroy the message. If you are not the intended recipient you are not allowed to use, copy or disclose the contents or attachments in whole or in part.