From:	Eva Paul
To:	Graham Gill
Cc:	Andrew Keim; Baba Pedersen; Christine Wilson; Phyllis Beaulieu <licensing@nunavutwaterboard.org; Rod Brown
Subject:	RE: 2BE-PEL0813 Inspection Form August 17, 2012 and associated photos
Date:	Wednesday, August 29, 2012 1:24:52 PM
Attachments:	IQALUIT-#568292-v1-2BE-PEL0813_RESPONSE_TO_AUGUST_23_E-MAIL_FROM_MR__GILL.pdf

Hello Mr. Gill,

Please find attached a letter of response to your e-mail of August 23, 2012. Please feel free to call and discuss any items of concern from this or your recent inspection.

Regards,

Eva Paul
Water Resources Officer | Agent des ressources hydriques
Aboriginal Affairs and Northern Development Canada | Affaires autochtones et Développement du Nord Canada
Nunavut Regional Office | Bureau régional du Nunavut
Building 918, PO Box 100 | Édifice 918, CP 100
Iqaluit, NU X0A 0H0

Phone | Tél. : 867-975-4548
Cell | Mobile: 867-222-6490
Fax | Téléc. : 867-975-6445
Eva.Paul@aandc-aadnc.gc.ca

>>> Graham Gill <G.Gill@diamondsnorth.com> 8/23/2012 5:57 PM >>>

Hi Eva and Rod; We will be having crews cleanup other sites near mid-September so not sure if we will get all work you outlined done this year but will definitely try to start with the salt, oils and filled berms

This all depends on crew and helicopter availability and of course weather

Below are some my comments regarding the pictures sent.

Figure 1 shows 5 pails. These contain rock and/or soil, not oil

Figure 2.We will try have these removed and/ or covered and off the ground.

Figure 3 These are sealed drums and left for this type of cleanup

Figure 4. we can store this in one the shacks put the oils in side

Figure 5. Again these are sealed and were lft there for this type of cleanup. When I talked with Baba Pederson last year he made mention that berms were not mandatory but that one container of equal or greater volume should be present

Figure 6 Berms of water will be dealt with using rain drains which we have on site

Figure 7 As above

Figure 8. Hose can be roved an drum stored properly out of the weather

Figure 9. See item 6 Hose can be roved.

Figure 10. See item 6

Figure 11. Oils of grease cab stored in one of the shed for now or removed to town

Figure 12. As above.

Figure 13. This door will be secured

Figure 14.I'm not sure why this is a problem if the door is more firmly secured. These could be removed to town and given to the Hamlet perhaps.

Figure 15. As above

Figure 16. Can be roved town for disposal

Figure 17. As above.

Figure 18 and 19. Wood could be moved to the camp airstrip and flown out later.

Figure 20. Ashes to be screened my magnets, raked as well as barrel imprints..Waste to be removed.

Figure 21 and 22. See Item 20

Figure 23. See Item 20

Figure 24. See item 20.

Thanks.

Graham

From: Eva Paul [mailto:Eva.Paul@aandc-aadnc.gc.ca]
Sent: August-17-12 7:59 AM
To: Graham Gill; Graham Gill
Cc: Andrew Keim; Phyllis Beaulieu <licensing@nunavutwaterboard.org
Subject: 2BE-PEL0813 Inspection Form August 17, 2012 and associated photos

Hello Mr. Gill,

I recently was present at your site on August 11, 2012. Please find attached the report of my inspection. Please note that the items I identified for Amaruq and Tunerq camps must be completed by September 30, 2012. There are further administrative deadlines that are outlined in the report.

Please feel free to contact me to discuss any matters that require clarification.

Thank you,

Eva Paul
Water Resources Officer | Agent des ressources hydriques
Aboriginal Affairs and Northern Development Canada | Affaires autochtones et Développement du Nord Canada
Nunavut Regional Office | Bureau régional du Nunavut
Building 918, PO Box 100 | Édifice 918, CP 100
Iqaluit, NU X0A 0H0

Phone | Tél. : 867-975-4548
Cell | Mobile: 867-222-6490
Fax | Téléc. : 867-975-6445
Eva.Paul@aandc-aadnc.gc.ca