WATER LICENCE INSPECTION FORM

☒ Original
☐ Follow-Up Report

Licensee	Licensee Representative
Alex Vilela	Flexure Minerals Ltd.
Licence No. / Expiry	**Representative's Title**
2WLC-PRP2425	
Land / Other Authorizations	**Land / Other Authorizations**
Date of Inspection	**Inspector**
July 23, 2026	Joseph Monteith

Activities Inspected

☒ Camp ☐ Drilling ☐ Mining ☐ Construction ☐ Reclamation ☐ Fuel Storage
☐ Roads/Hauling ☐ Other: ☐ Other:

Conditions: **A- Acceptable** **U-Unacceptable** **C-Concern** **NI-Not Inspected** **NA- Not applicable**

PART:	Condition	Observation No.*
A: SCOPE, DEFINITIONS AND ENFORCEMENT		
B: GENERAL CONDITIONS		
C: CONDITIONS APPLYING TO SECURITY		
D: CONDITIONS APPLYING TO WATER USE	a	1
E: CONDITIONS APPLYING TO WASTE DISPOSAL AND MANAGEMENT	a	2-4
F: CONDITIONS APPLYING TO MODIFICATIONS		
G: CONDITIONS APPLYING TO CONSTRUCTION		
H: CONDITIONS APPLYING TO EMERGENCY RESPONSE AND CONTINGENCY PLANNING		
I: CONDITIONS APPLYING TO ABANDONMENT, RECLAMATION AND CLOSURE PLANNING	a	5
J: CONDITIONS APPLYING TO MONITORING		
SCHEDULES		

**The item number corresponds with specific conditions within the licence and the observation number corresponds with specific comments provided below.*

Samples taken by Inspector:	Location(s):
☐ Yes ☒ No	

Background

Alexandre Jones Vilela Da Silva (Alex Vilela) c/o Flexure Minerals Ltd. was authorized for the use of water and deposit of waste during mineral exploration including non invasive geophysical survey, prospecting, sampling, and geological sampling at the Prescott Project, located within the Kitikmeot and Qikiqtani Regions, Nunavut and within Eastern Prince of Wales Island Watershed

Inspector Statement

On July 23, 2026 a water license inspection was conducted by Water Resource Officer (WRO)Joseph Monteith at the sites of 2WLC-PRP2425.

Water Use

1. No signs of water use, or disturbances.

Waste

2. No signs of sump pit
3. No signs of solid wastes
4. No signs of spills

Reclamation

5. No signs of structures, equipment or spills.

SECTION 1 ☒ Comments ☐ Non-Compliance with Act or Licence ☒ Action Required

Site appears to have been reclaimed to near pristine conditions. I recommend closure of the water license 2WLC-PRE2425

SECTION 2 ☐ Comments ☒ Non-Compliance with Act or Licence ☐ Action Required

Licensee or Representative	Inspector's Name
Alex Vilela	Joseph Monteith
Signature	**Signature**
Date	**Date**
	September 29, 2026

CC: Licensing Department, NWB
Jeremy Fraser, Manager of Field Operation

PHOTO LOG

Date	Camera	Inspector
July 23, 2026	Galaxy S9	Joseph Monteith
Photo Log #1		**Location**
Photo 1		N73°23”27’, W97°09”54’



Description: Site 1 Prince of Whales Island, Peel Sound

Photo Log	Location
Photo 2	N67° 56' 05.8" W64° 54' 14.8"



Description: Site 2 Prescott Island

Photo Log	Location
Photo 2	N67° 56' 05.8" W64° 54' 14.8"



Description: Site 3 Somerset Island, Ashton Bay