From: David Hohnstein
To: "Westwell, Bill"
Cc: "Roy, Bhabesh"; "Lam, Bu"; "Phyllis Beaulieu"
Subject: RE: Cape Dorset Lagoon
Date: Friday, June 08, 2012 12:07:32 PM
Attachments: 120222 3BM-CAP0810 Multi Year Municipal Compliance Summary-IMLE.pdf
120222 3BM-CAP0810 Non-Compliance Cover Letter-IMLE.pdf
110911 3BM-CAP0810 Water Use Inspection Report Form-IMLE.pdf

Hi Bill,
Dionne had indicated you'd given her a quick call this morning about Dorset and Taloyoak. What I can offer on Dorset is the following:

1) Licence expired March 1, 2010; Renewal is required (and any amendment that may be needed, ie thermistor installation); a revised renewal application submitted July 2011, pending additional information;
2) Part B, Item 6 requires the installation to 20-25m (this was agreed upon by the geotechnical engineer of record and the licensee at the time of the public hearing on the renewal application 2008), additional information would need to be provided with the current renewal application on file, to amend this condition or accept the depths as installed;
3) Latest outstanding concerns (with respect to the application) were I believe provided in a letter of September 14, 2011; additional concerns may have been identified in the compliance letter of AANDC's of February 22, 2012 (attached).
4) I believe the latest AANDC inspection report has still indicated that the new 2007 sewage lagoon continues to release contained runoff water through the berms, not sure if that is still the case, however there is a requirement under Part H. Item 25 for AANDC to provide the Board with confirmation of satisfaction of conditions prior to commissioning of the facility.

Please have a review of the above and attached and we can set up some time next week to discuss plans moving forward.

Regards,
Dave

From: Westwell, Bill [mailto:BWestwell@GOV.NU.CA]
Sent: Thursday, June 07, 2012 9:18 AM
To: dts@nunavutwaterboard.org
Cc: Roy, Bhabesh; Lam, Bu
Subject: Cape Dorset Lagoon

Dave,

Would you be able to provide us with some time so Bhabesh and I can call with progress on the Cape Dorset sewage lagoon?

1. If we may amend the licence to allow the thermistors to remain at 18.8 m, or was there a

reason they needed to be 20-25 m deep?

2. If there are any outstanding concerns that the NWB has with Cape Dorset?
3. Share our plan moving forward.

Thanks
Bill

Bill Westwell
Senior Manager Municipal Planning
Department of Community & Government Services
PO Box 1000
Station 700
Iqaluit Nunavut
X0A 0H0
867 975 5461