



---

## Cambridge Bay Soil Treatment Facility - Soil with high pH - 1BR-CST1723

---

**Sergey Kuflevskiy** <sergey.kuflevskiy@nwb-oen.ca>

To: koliver@kblenv.com

Cc: Richard Dwyer <richard.dwyer@nwb-oen.ca>

Tue, May 11, 2021 at 4:18 PM

Hi Katie,

Richard just forwarded your email to me.

To answer your question, the Licence only regulates the pH of the effluent under Part D, Item 7. So, I do not see any issues with using additional method of treatment, as long as you meet all other requirements of the Licence.

By the way, where is the 8.0 number coming from? If this is the limit of the receiving facility, and you need to treat the soil more in order to achieve the desired pH, I do not see any issues on our end.

I would recommend updating the Operations and Maintenance Plan to incorporate wood vinegar into Section 3b and attach the MSDS sheet to it as well. Please send the updated Plan to me and copy Richard Dwyer.

Let me know if you have any questions,

