

File No.: 1BR-FTA1217/TR/E2

December 1, 2014

Michael Molinski Transport Canada 3rd Floor – 344 Edmonton Street Winnipeg, MB R3C 0P6

Email: michael.molinski@tc.gc.ca

Subject: Licence No. 1BR-FTA1217 "Cambridge Bay Airport – Firefighter Training

and Apron Areas Remediation Project" Kitikmeot Region, Nunavut; Transport Canada; Submission of Landfarm Operation and Maintenance

Plan

Dear Mr. Molinski.

The Nunavut Water Board ("NWB" or "Board") has reviewed the "Cambridge Bay, Nunavut Airport Apron/ Fire Training Area Landfarm Operation and Maintenance Plan" dated May 29, 2014 that was submitted to the Board as per a requirement of Part E, Item 2 of the Licence.

The Licensee is advised that the submitted document does not provide the information that was required per Part E, Item 2 of the Licensee. <u>The Licensee is requested to revise the Plan and re-submit it within the 2014 Annual Report, taking into consideration the requirements outlined in Part E, Item 2 of the Licence.</u>

In addition, the Board has noticed that information provided within the S. 1.1 Sampling Program and S. 1.4 Monitoring Well Sampling is different from the sampling details provided within the Operations and Maintenance Plan, dated March 2012 that was originally approved by the Board.

The original proposed sampling program consisted of twelve composite soil samples and a sample from each of eight monitoring wells instead of eight composite soil and three monitoring wells sampling discussed in recent document. The NWB would like clarifications on this matter as well.

Should you have any questions, please feel free to contact the undersigned at (867) 360-6338 Ext. 35 or karen.kharatyan@nwb-oen.ca, at your earliest convenience.

Yours truly,

Karén Kharatyan Technical Advisor

cc: Public Registry