

# **Application for Water Licence Cancellation**

Document Date: April 2013

Application Submission Date: 03/09/2015

Month/Day/Year

P.O. BOX 119 GJOA HAVEN, NUNAVUT XOB 1J0

Tel: (867) 360-6338 FAX: (867) 360-6369

### DOCUMENT MANAGEMENT

Original Document Date: April 2010

#### **DOCUMENT AMENDMENTS**

	Description	Date
(1)	Updated for public distribution as separate document	June 2010
	from NWB Guide 7	
(2)	Updated NWB logos and reformatted table to allow rows	May 2011
	to break across page	
(3)	New NWB logo and change to Block 9	April 2013
(4)		
(5)		
(6)		
(7)		
(8)		
(9)		
(10)		



P.O. Box 119

TEL: (867) 360-6338

FAX: (867) 360-6369

معهد ۱۳۵۸ ۱۳۹۹ م GJOA HAVEN, NU X0B 1J0 NUNAVUT WATER BOARD NUNAVUT IMALIRIYIN KATIMAYIT OFFICE DES EAUX DU NUNAVUT

#### **APPLICATION FOR WATER LICENCE CANCELLATION**

1. LICENCE NO: 1BR-IAD0606	2.	EXPIRY DATE: 2006/12/31		
3. NAME AND MAILING ADDRESS OF LICENSEE	4.	ADDRESS OF CORPORATE OFFICE IN CANADA (if applicable)		
Government of Nunavut Department of Economic Development & Transportation P.O. Box 560 Rankin Inlet, NU P.O. Box 100, Stn 720, Iqaluit, NU, X0A-0H0  Phone: 867 975-7771 Fax: 867 979-6985 e-mail: jhawkins@gov.nu.ca	Fax:			
5. DECLARATION:				
I, on behalf of				
The Department of Economic Development & Transportation, Government of Nunavut  hereby make application to cancel the above-noted water use licence effective				
_April 1, 2015 (insert proposed date of cancellation)				
Date of most recent water licence inspection: (attach copy of inspection report, if available)  Signature of Licensee: Date:		ber 2006		
6. CANCELLATION FEE:				
Application fee of \$30.00 CDN (payable to the Receiver General for Canada)				

7. REASON – Provide written reason for cancellation request: Work was completed in 2006 per the design provided. All sediment removed from the channel was deposited as detailed in Attachment A. No contamination was detected in the sediment at the time of placement. A sample result (TP 250) from testing undertaken in 2014 is included.			
The embankments of the channel were reconstructed, and all culvert invert embankments were reinforced with rip-rap materials. Water flow through the drainage channel and culverts is no longer impeded or subject to seasonal ice blockages. Flooding of airport apron surfaces has not occurred since the work was undertaken.			
8. ABANDONMENT MEASURES The following measures have been taken to address the final abandonment conditions required by the licence: (explain, with drawings, how abandonment conditions of the licence have been met; how stream channels have been rehabilitated; how tailings have been re-contoured; how instream structures have been removed; and how waste materials have been disposed of. Enclose pictures if available.			
Waste material (sediment) was placed in two locations detailed in Attachment A.			
9. <b>CERTIFICATE OF COMPLETION</b> : Application for Licence Cancellation must be accompanied by either of the following:			
<ul><li>Application for Certificate of Completion enclosed; or</li><li>Certificate of Closure enclosed.</li></ul>			
The applicant is advised to consult with Aboriginal Affairs and Northern Development Canada egarding provision of the requested certificate.			

## Attachment A



Figure 1

