# **Appendix 5** Resolution Island INAC Land Officer Inspection Report (November 2009)



Qikiqtani Region P.O Box 2200 Igaluit, NU X0A 0H0

Indian & Northern Affairs Contaminated Sites PO Box 100 Igaluit Nu OHO AOX

Attn: Natalie Plato & Kevin Mckenna

November 16, 2009

# RE: Contaminated Site Inspection. LUP N2003X0038. Resolution & Radio Islands

On. September 5<sup>th</sup> 2009 I conducted a field inspection at the above mentioned locations.

A copy of the Inspection report is attached. After reading the report please sign and return a signed photocopy to my office. If you have any comments or suggestions please feel free to attach them to the copy of this report.

I apologize for the delay in forwarding this report to you.

# Issues Identified during the inspection:

Campsite: (Resolution Island).

This was part of the DEW Line radar system years ago.

The majority of the buildings were removed over a lengthy period (4-5 years) however, there are still buildings and their remnants on site which are being damaged by the weather. One of the smaller radar dishes was blown over this past winter (2008/2009) and if there is to be no further clean-up, the other dishes and some of the buildings yet remaining that could be forcibly re-located to other parts of the island.

## (Radio Island)

The only two items observable were a small cabin (no door) and a metal observation tower. No other amounts of garbage were seen. If the cabin is to be of any use (survival) then it should be either fixed up or torn down.

Fuel Storage: There is an appreciable amount of aviation fuel stored at Resolution Island for use over the next few years. No recent leakage was noted.

Water: Not Applicable



Waste: As stated earlier, there is an accumulation of garbage that should be cleaned up and removed

**Drilling activities:** Not applicable.

<u>Comments:</u> As seen in some of the photos attached there is a series of berms on Resolution Island. I'm not certain why they exist but they don't seem to be doing any harm.

If there are to be yearly inspections then a wildlife monitor should be present as we did sight a polar bear in the vicinity.

Please do not hesitate to contact me should you have any questions or comments.

Sincerely,

Kevin L Robertson

Resource Management Officer

Qikiqtani Region

PO Box 100. Iqaluit. Nu


X0A 0H0

Tel: (867) 975-4296 Fax: (867) 979-6445


Kevin.robertson@inac.gc.ca

cc: Land Administrator, INAC

CIDM # 366688.















District Mgr. Initials

ENVIRONMENTAL INSPECTION REPORT								
Permittee: (complete name and address) Contaminated Site. Indian + Anhem								
RATORIA POBOK 100 DORUNT DU XOA OHO								
Permit Expiry Date Last Previous Inspection								
Land Use Permit No. //2003 X 00 3 8.								
Quarrying Permit No.			3 X 00 3 8.		ary 31,2009.			
Cont	ractor: NATALIE	1730		Subcontractor: 975-4731				
Location(s) Inspected: Remaining Building + Radon Site, Land fill site								
with action monings BHF-5.								
Current Stage of Operation: Sheet Louis Inspections by Contaminat &								
Site & Field Operations.								
Program Modifications Approved:								
Program modifications Approved.								
Condition of Operation "A" - Acceptable "U" - Unacceptable "N/A" - Not Applicable								
	Operating Condition	N.		Aspect In	spected			
			1.44					
A	Location as Permitted		'A'			crique	al	application
В	Timing as Permitted		'A'	No act	inties	2 4	-	
-	Equipment as Approved			m - hau			ppl	cut in
D	Methods & Techniques		muni	toning c	ontine	1		
E	Facilities		NIA	21		u ·		
	Erosion Chamicala Masta	1	Not Kna	m, will	ray une	They are	speci	Cears -
G	Chemicals, Waste			un , re	yere m	are gust	COL	cins
H	Wildlife & Fisheries Habitat		NIA	Some K	Var Dear	Sighting	D.K	econded
_	Ecological Resource		NA		4 0		-	
K	Fuel Storage		Some 9	untit	of fe	al cach	acl.	as required.
L	Brush Disposal		N/A	100		Earl	1	
M	Matters Not Inconsistent		NIA				-	
N	Water Engineering		NIA	0.3	34- 3	1000	-	and the same of th
0	Water Supply		NIA	1		10		airin Aldas,
Р	Restoration		Unkne	our what	4.	nned for	rem	acres sough
Q	Quarrying Methods		cloud	permi	G.			
R	Sections 12 to 19 T.L.U.R.		NIA	Soma k	milderge	to sen	ain	1
S								
T VIV								
Surveillance Network Program Any Sampling will be conducted by Contaminated Siters								
Explanatory Remarks (attach page 2, if required) \ accompanies Keyin Mc Kenna on inefection								
or Sept 5/2009. He was to regripe dute from equipment of								
one location (4 boxes) I was required to visul reniency bloop								
To & general state of the nain camp / buildings, Page 2 attached of Yes 10								
N. O. J.								
Representative's Signature Inspector's Signature								
			0	KIR				
RMO Initials								
						1977		

Copy 1 - Inspector's File Copy 2 - Field Rep. Copy 3 - Permittee Head O. Copy 4 - District

Representative's Title

.

Date Sast 5, 2009.

Permit No. M2003×0038

Explanation and Remarks (Continued) Explications et remarques (suite)

Land Use Inspector - Inspectour de l'utilisation des terres

Note: This form is to be used as necessary in conjunction with the Land Use Inspection Report Territorial Land Use Regulations, IAND 52-221 (10-72).

Au besoin, annexer la présente feuille au rapport d'inspection de l'utilisation des terres, Règlements sur l'utilisation des terres territoriales, MAINC 52-221 (10-72).