

WATER LICENCE INSPECTION FORM

☑ Original☑ Follow-Up Report

Licensee	Licensee Repre	Licensee Representative										
Qikiqta	aaluk Environ	ımental I	lnc.			Oliver SIMARD						
Licence N	Representative	Representative's Title										
1BR-T	Project N	Project Manager										
Land / Ot	her Authorizations				Land / Other A	and / Other Authorizations						
												
Date of In	spection				Inspector	nspector						
July 16, 2019 Jonathan MESHER												
Activities	Inspected											
☐ Camp ☐ Drilling ☐ Mining ☐ Moads/Hauling ☐ Other: Landfarm					☐ Constru ☐ Other:	Construction Reclamate			☐ Fuel Storage			
Noaus	/ Hauling	Other. La	ilulalili		☐ Other.							
Condition	ons: A - A	cceptable	C	- Concern	U - Unacceptab	le	NA –	Not Applicable	NI -	- Not Ins	ected	
Water l	Jse	Condition	Comment	Site Conditions		Condit	Comme	Haz/Mat Manag	ement	Condition	Comment	
Intake/S	Screen	NA		Water Manager	ment Structures	ion A	nt	Storage		Α		
-	easure. Device	A		Water Management Structures Culverts / Bridges		NI		Spills		NA NA		
Source:		NA NA		· •		NI		Spill Plan		A		
Water U				Drainage Fresion / Sediment				Spili Fiaii		A		
		NA		Erosion / Sediment		NI		Administration				
Recircui	lation (y /n)	NA		Mitigation Measures		NI		Administrative				
				Reclamation Ac		NA		Records		NI		
				Materials Storag	ge	Α		Reports		NI		
	Disposal			Signage		Α		Plans		С		
Waste \	Nater	Α						Notifications		Α		
Solid W	aste	Α		Monitoring				Other				
Hazardo	ous Waste	Α		Sample Collection	on / Analysis	NI		Follow-up from		NI		
								previous inspecti	ion			
*The number in the comments field will correspond with specific comments provided below.												
Samples taken by Inspector: Location(s):												
☐ Yes ☐ No												
SECTION 1 Comments Non-Compliance with Act or Licence Action Required												
Comments Non-compliance with Act of Electice Action Required												
<u>Background</u>												
On August 20, 2014 the Nunavut Water Board issued a type "B" Water Licence 1BR-THI1419 to Qikiqtaaluk												
Environmental Inc. (QE) to allow for the disposal of waste during the operation of a commercial Hydrocarbon Impacted												
Water Treatment Facility located within the City of Igaluit, Nunavut.												
,,												
Inspection												
On June 16, 2019 an inspection was conducted by Jonathan MESHER a Water Resource Officer (WRO) of Crown-												
Indigenous Relations and Northern Affairs Canada (CIRNAC) and accompanied by Oliver Simard of Qikiataaluk Environmental.												
Environmental.												
1. The original soil treatment cell appears to be operating as intended; the soil appears to be laid out in a way to												
	increase aera	ation. (se	e photo #	1 for the referr	ed to containm	ent ce	II)					
2.												
	construction has not been approved by the NWB. The licensee has submitted an amendment to the NIRB (file #											
	15XH051) and to the NPC (file # 149195) and are waiting for the conformity determination prior to submitting											
	an amendment application to the NWB. (see photo #2 for the recently completed soil treatment facility)											
3. The licensee has also upgraded their water treatment facility to increase the rate of treatment from 10 Litres a								res a				
	minute to 30) Litres a r	minute.									
_	Nia		ا ا ا	alla a con 1999	af ala e le		L •					
4.	No concerns	were not	ea about	tne condition	of the berm wa	iis or th	ne stor	age or waste.				
SECTIO	ON 2	Commo	ents	⊠ Non-	Compliance wi	th Act	or Lice	nce 🔀 A	ction R	equired		





The Following is a list of Non-compliance with the water licence 1BR-THI1722;

- The Licensee is out of compliance with the Terms of the licence listed below because; they have constructed structures to hold waste prior to obtaining approval from the NWB.
 - I. Part G, Item 1
 - II. Part F, Item 1


Inspector's Name	
Jonathan MESHER	
Signature	
Date	
July 24 , 2019	

Water Resource Officer, Nunavut Region

Crown Indigenous Relations and Northern Affairs Canada – CIRNAC

Jonathan.mesher@canada.ca

Office #: 867-975-4296 Fax: 867 979-6445







Relations Couronne-Autochtones et Affaires du Nord Canada

Sony Cyber-shot

Photo Log Photo 2



J.Mesher

1BR-NUN



