

27 August, 2015

BY E-MAIL

Eva Paul
Water Resources Officer
Aboriginal Affairs and Northern Development Canada
Nunavut Regional Office
Building 969, PO Box 2200
Iqaluit, NU X0A 0H0

Re: July 16 2015 Report of Inspection for License 2BE-KIK0608

Dear Ms. Paul,

We acknowledge receipt of the water license inspection report for the drilling site referenced in License 2BE-KIK0608. We are as concerned as you are about the fuel drums and other materials that have been left at the site and the apparent lack of compliance with the terms of the license.

Staff turnover, handover of responsibilities and confusion surrounding the transfer of the mining lease to Rhonda Corp. in 2008 & 2009 are somewhat to blame for the clean-up not happening but we are still looking into aspects of the events that caused this site to be left in this state.

If we find we are liable for the site we will send the confirmation of when the materials removal work will be undertaken by the stipulated date of Sept 30th 2015.

Yours truly,

Jonas Schuett ECOHS Coordinator De Beers Canada Inc. - Exploration Cell: (519) 781-7128

Cc: Chris Wallace, DBCI Business Support and Assurance Manager Chris Redhead, DBCI Safety, Health and Environment Coordinator