NWB Annual I	Report	Year being reported: 2011 ▼				
License No: 2	2BE-MSX0712	Issued Date: May 16, 2007 Expiry Date: December 31, 2012				
Į.	Project Name: M	uskox Project				
l	Licensee: Silvermet Inc.					
r		8 King Street East, Suite 1700 Toronto ON M5C 1B5				
Name of Company filing Annual Report (if different from Name of Licensee please clarify relationship between the two entities, if applicable):						
General Back	ground Information o	n the Project (*optional):				
	Activity in 2011 was lin	mited to cleaning up the camp site				
Licence Requirements: the licensee must provide the following information in accodance with  Part B   Item 2						
A summary report of water use and waste disposal activities, including, but not limited to: methods of obtaining water; sewage and greywater management; drill waste management; solid and hazardous waste management.						
	Water Quantity: ir n	Silvermet camp and drilling locations - no water use in 2010  ncluded below Quantity Allowable Domestic (cu.m)  Actual Quantity Used Domestic (cu.m)  Quantity Allowable Drilling (cu.m)  Total Quantity Used Drilling (cu.m)				
	Waste Management an Solid Waste Dispo Sewage Drill Waste Greywater Hazardous Other: Additional Details: No waste disposal occ	osal				

A list of unauthorized discharges and a summary of follow-up actions taken.

	Spill No.: None (as reported to the Spill Hot-line)  Date of Spill: Date of Notification to an Inspector:
	Additional Details: (impacts to water, mitigation measures, short/long term monitoring, etc)
Revisions to	the Spill Contingency Plan
	N/A - not applicable
	Additional Details:
Revisions to	the Abandonment and Restoration Plan
	No Abandonment and Restoration (AR) Plan submitted or approved
4	Additional Details:
Progressive	Reclamation Work Undertaken
rogressive	Additional Details (i.e., work completed and future works proposed)
	During April 2011, Kikiak Contracting Ltd. (Kugluktuk) had a crew clean up the camp site of fuel drums, tents and equipment as much as was possible. Fuel drums and wood were removed from site and transported to the Mouse Lake camp operated by Hornby Bay Exploration Ltd. in the Dismal Lakes area. Tents and other equipment were removed from site and transported to Kikiak's yard in Kugluktuk. Hornby Bay was to have a team of its personnel clean the camp site once the snow had left. However, this did not take place so alternative clean up plans were put in place during 2012.
Results of th	e Monitoring Program including:
	The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where sources of water are utilized;
	Details described below
	Additional Details:
	Camn - N 66 degrees 59' 9 7" and W 114 degrees 53' 51 4"

The GPS Co-ordinates (in degrees, minutes and seconds of latitude and lo each location where wastes associated with the licence are deposited;	ngitud
Details described below	~
Additional Details:	
Camp - N 66 degrees 59' 9.7" and W 114 degrees 53' 51.4"	
Results of any additional sampling and/or analysis that was requested by a	an Ins
No additional sampling requested by an Inspector or the Board	•
Additional Details: (date of request, analysis of results, data attached, etc)	
etails on water use or weste disposal requested by the Board by November	1 of th
etails on water use or waste disposal requested by the Board by November ted.	i or ti
No additional sampling requested by an Inspector or the Board	~
	~
No additional sampling requested by an Inspector or the Board	<b>V</b>
No additional sampling requested by an Inspector or the Board  Additional Details: (Attached or provided below)	<b>V</b>
No additional sampling requested by an Inspector or the Board  Additional Details: (Attached or provided below)  ses or follow-up actions on inspection/compliance reports	
No additional sampling requested by an Inspector or the Board  Additional Details: (Attached or provided below)  ses or follow-up actions on inspection/compliance reports  Inspection Report received by the Licensee (Date):	t uel
Additional Details: (Attached or provided below)  ses or follow-up actions on inspection/compliance reports Inspection Report received by the Licensee (Date):  Additional Details: (Dates of Report, Follow-up by the Licensee)  A July 11, 2011 flyover inspection took place by INAC and an inspection report was received by Silvermet on March 14, 2012. The report identified that one for cache still remained and debris remained at the camp site. Silvermet addressee	t uel

Date Submitted:	June 2	24, 2014		
Submitted/Prepared by:	Rein Le	in Lehari		
Contact Information:	Tel:	416-203-8336		
	Fax:	416-368-5146		
	email:	rlehari@silvermet.ca		