

WATER LICENCE INSPECTION FORM

☑ Original☐ Follow-Up Report

Licensee	Licensee Representative							
Natalia Rybczynski, Ph.D. None Present								
Canadian Museum of Nature								
Research/ Paleobiology								
	PO Box 3443 STN "D"							
Ottawa ON K1P 6P4, Canada								
phone: (613) 566-246								
fax: (613) 364-4027								
nrybczynski@mus-na	ature.ca							
Licence No. / Expiry		Re	epresentati	ive's Title	1			
3BC-LEP1010 ex								
	Land / Other Authorizations Land / Other Authorizations							
Date of Inspection		In	spector					
07/07/2014		А	.Keim					
Activities Inspected								
☐ Camp	Drilling	☐ Mining	Cons		Reclamation	☐ Fuel Stora	ge	
☐ Roads/Hauling	Otner: wa	ter Discharge	Othe	r:				
Conditions: A - A	cceptable	C - Concern U - U	naccepta	able	NA - Not Applicable	NI – Not In	spected	
Water Use	Condition	Comment Site Conditions		Condition	Comment Haz/Mat Manage		•	
Intake/Screen	NA	Water Management Stru	ıctures	NA	Storage	С	2	
Flow Measure. Device	NA NA	Culverts / Bridges		NA	Spills	NA NA		
Source:	INA	· ·		NA	•	NA NA		
	NIA .	Drainage			Spill Plan	INA		
Water Use:	NA	Erosion / Sediment		NA				
Recirculation (y /n)	N	Mitigation Measures		NA	Administrative			
		Reclamation Activities		NA	Records	NI		
		Materials Storage		NA	Reports	С	1,2	
Waste Disposal		Signage		NA	Plans	Α		
Waste Water	NA				Notifications		3	
Solid Waste	NA	Monitoring			Other			
Hazardous Waste	NA	Sample Collection / Ar	nalysis	NA				
		•						
*	The number	r in the comments field will corre	spond w	ith spec	cific comments provided belo			
Samples taken by Inspe		Location(s):						
	ctor.	Location(s).						
Yes No								
_								
	Commen	· — ·				tion Required		
		d 2 sites listed in the 2010 Appli						
		1010 Project. Upon arrival at the						
evidence of occupation or disturbance could be seen. No persons, structures or activities could be seen in the area. The sites were								
both found in what appeared to be their natural state with no evidence of disturbance.								
On July 6 th the Inspector attended the areas around the sites listed in the application submitted to the Nunavut Water Board. A								
review of the Nunavut Water Board web site (FTP site) cannot locate an Annual Report for the above noted file. As such the								
Inspector cannot confirm the locations as listed in the application as those actually visited by the proponent or whether or not any type of camp or overnight facilities were erected at these or other locations								
type of camp or overni	gnt facilitie	es were erected at these or other	location	IS				
SECTION 2	Commen	nts (s) Non-Compli	ance wit	h Act o	r Licence (s)	tion Required	(s)	
During the period of th	e Inspectio	on 4 drums of aviation fuel and tw	vo drum:	s of hea	ating fuel were found on the	beach side are	ea where	
the strip for the site is located. These drums were found not in secondary containment. It is not clear why these drums were not								
removed from the camp. The Licensee is required to confirm with PCSP that drums associated with this project were all removed								
from camp and to have	· e that inforr	mation included in the above no	ted Annu	ıal Repo	ort. The coordinates are as	follows: N 78	14 37.4 X	
W82 30 21.5.				'				
SECTION 3	Commen	nts (s.) Non-Compli	ance wit	h Act o	r Licence. (s.)	tion Required	(s.)	
SECTION 3								
Proponent is reminded that it is the responsibility of the Licensee to ensure that all submissions to the Board are acknowledged by								
the licensing department and to ensure it is posted on the Nunavut Water Boards Public Registry.								
the incensing departme	TIL ALIU LU E	moure it is posted on the Nangyt	at vvateľ	מט ומטע US	i ubiic itegisti y.			
Failure to file on Anguin	al Donort	ithin the 20 day deadline mass	cult in f	rthoro	nforcement action has aller	und under the !	Munova:+	
	-	ithin the 30 day deadline may re	suit in TU	i mer el	morcement action has allov	veu under t h e f	vuilavut	
Waters and Nunavut Si	urtace Righ	ts iribunai act.						



Photo Log			
Date	Authorization	Camera	Inspector
July 6, 2014	3BC-LEP1010	Sony Cyber shot	A. Keim



Figure 1Beach shoreline landing strip.



Figure 2 Beach/ shoreline strip.



Figure 3 4 Full fuel barrels at end of beach strip



Affaires autochtones et Développement du Nord Canada



Figure 4 Two additional Barrels of heating fuel found in same location

Licensee or Representative	Inspector's Name
	A. Keim
Signature	Signature
	-Sent by Email – original on file
Date	Date
	Sept 2, 2014

Office Use Only:	Follow-up report to be issued by Inspector	☐ Yes No

