

NWB Annual Report

Year being reported: 2008



License No: 2BE-FRK0812

Issued Date: May 11, 2008

Expiry Date: September 30, 2012

Project Name: Fork Property

Licensee: Barry Hanslit

Mailing Address: 8621 Forest Ridge Dr.
Whistler, BC V0N 1B8

Name of Company filing Annual Report (if different from Name of Licensee please clarify relationship between the two entities, if applicable):

-as above-

General Background Information on the Project (*optional):

No drilling this year, only <1 week of prospecting from a temporary dome-tent camp.

Licence Requirements: the licensee must provide the following information in accordance with

Part B



Item 2

**A summary report of water use and waste disposal activities, including, but not limited to: methods of obtaining water; sewage and greywater management; drill waste management; solid and hazardous waste management.**

Water Source(s):

Lake west of camp

Water Quantity:

1

Quantity Allowable Domestic (cu.m)

<0.02

Actual Quantity Used Domestic (cu.m)

5

Quantity Allowable Drilling (cu.m)

0

Total Quantity Used Drilling (cu.m)

Waste Management and/or Disposal☒ Solid Waste Disposal☒ Sewage☐ Drill Waste☒ Greywater☐ Hazardous☐ Other:

Additional Details:

Greywater and toilet wastes were deposited in sumps that were backfilled on completion of the project. Solid wastes were backhauled to the Nanaimo dump (food wrappers, etc.).

A list of unauthorized discharges and a summary of follow-up actions taken.

Spill No.: (as reported to the Spill Hot-line)

Date of Spill:

Date of Notification to an Inspector:

Additional Details: (impacts to water, mitigation measures, short/long term monitoring, etc)

-None

Revisions to the Spill Contingency Plan

N/A - not applicable ▼

Additional Details:

-None

Revisions to the Abandonment and Restoration Plan

N/A - not applicable ▼

Additional Details:

-None

Progressive Reclamation Work Undertaken

Additional Details (i.e., work completed and future works proposed)

All sumps were treated with lime and backfilled to previous contours. All camp materials were removed from site.

Results of the Monitoring Program including:

The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where sources of water are utilized;

Details described below ▼

Additional Details:

-113.2'14" W, 67.1'10"N (Lake west of camp)

The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where wastes associated with the licence are deposited;

Details described below ▼

Additional Details:

Latrine Pit: -113.1'54"W, 67.1'10"N
Greywater sump: -113.2'1"W, 67.11"N

Results of any additional sampling and/or analysis that was requested by an Inspector

No additional sampling requested by an Inspector or the Board ▼

Additional Details: (date of request, analysis of results, data attached, etc)

Any other details on water use or waste disposal requested by the Board by November 1 of the year being reported.

No additional sampling requested by an Inspector or the Board ▼

Additional Details: (Attached or provided below)

Any responses or follow-up actions on inspection/compliance reports

No inspection and/or compliance report issued by INAC ▼

Additional Details: (Dates of Report, Follow-up by the Licensee)

Any additional comments or information for the Board to consider**Date Submitted:**

March 23, 2009

Submitted/Prepared by:

Janet Miller/Barry Hanslit

Contact Information:**Tel:** 604-905-2920**Fax:** 604-905-2964**email:** hanslitb@telus.net