



[Licensing] RE: 2BE-NTI0507 Inspection of July 12, 2014

Michael Macmorran <mmacmorran@northarrowminerals.com>

Thu, Aug 6, 2015 at 2:24 PM

To: "Licensing Department (licensing@nwb-oen.ca)" <licensing@nwb-oen.ca>, "phyllis.beaulieu@nwb-oen.ca" <phyllis.beaulieu@nwb-oen.ca>

Hi Phyllis,

Sorry, I'm a bit late following up on this. Can you tell me if there has been any resolution as to whether or not Strongbow has to go and remove the old Cominco drill collars Eva noted in her inspection report? Please let me know.

Many thanks!

Mike

From: Eva Paul [mailto:Eva.Paul@aandc-aadnc.gc.ca]

Sent: Friday, November 28, 2014 7:10 AM

To: Mike MacMorran; Ken Armstrong

Cc: Erik Allain; Licensing Department

Subject: 2BE-NTI0507 Inspection of July 12, 2014

Please find attached the inspection report for the above-noted inspection. Some minor reclamation work will be required before cancellation of this licence. Should you have any questions, please do not hesitate to contact me.

Best regards,

Eva Paul

Water Resources Officer | Agent des ressources en eau

Aboriginal Affairs and Northern Development Canada | Affaires autochtones et Développement du Nord Canada

Nunavut Regional Office | Bureau régional du Nunavut

Building 969, PO Box 2200 | Édifice 969, CP 2200

Iqaluit, NU X0A 0H0

Phone | Tél. : 867-975-4548

Cell | Mobile: 867-222-6490

Fax | Téléc. : 867-979-6445

Eva.Paul@aandc-aadnc.gc.ca



[Licensing] RE: 2BE-NT10507 Inspection of July 12, 2014

Cynthia Ene <cynthia.ene@nwb-oen.ca>
To: Eva.Paul@aandc-aadnc.gc.ca
Cc: Licensing Department <licensing@nwb-oen.ca>

Mon, Aug 24, 2015 at 11:29 AM

Good Morning Eva,

It was great chatting with you. As I had mentioned, below is the email from Mike. Thank you for adding some clarity on this.



Cynthia Ene, MBA, P.Eng.- ٧٢٢٤ ٤٤٥٧

Technical Advisor- Conseillère Technique

Aḥq^a ḏr n s^a Δ b r N- Piluaqnaqtuliginanun Ikayuuṭi

NUNAVUT WATER BOARD - OFFICE DES EAUX DU NUNAVUT
ᓄᓇᓂᓪ ᐃᓕᓂᓪ ᑲᓂᓕᓪᓴ - NUNAVUT IMALIRIYIN KATIMAYINGI

www.nwb-oen.ca

P.O. Box 119
Gjoca Haven, NJ, 08031-0119

C.P. 119
Gjoa Haven (Nunavut), X0B 1J0

በበጭጭ 119
፲፱፻፶፯, ጳጳስ 110

Tingagqvia 119
Uqhuqtuq, NU, X0B 1J0

Tel / Téléphone / ᐱᐱᐱᐱᐱ / Hivayauta: (867) 360-6338 | Fax / Télécopieur / ᐱᐱᐱᐱᐱᐱ / Fax-kut: (867) 360-6369
Toll Free / Sans / ᐱᐱᐱᐱᐱᐱᐱᐱ / Akiittuq: 1-855-521-3745

WARNING: This communication, including any attachments contains confidential information intended only for the addressee(s) noted above. Any unauthorized distribution, copying, or disclosure is strictly prohibited. If you have received this by mistake, please notify the sender immediately and delete this message without printing or copying it. Thank you.

AVIS DE CONFIDENTIALITÉ - Ce message, et tout(s) pièce(s) jointe(s) est confidentiel et est à l'usage exclusif du(es) destinataire(s) ci-dessus. Toute autre personne est par la présente avisée qu'il lui est strictement interdit de le diffuser, le distribuer ou le reproduire. Si le destinataire ne peut être joint ou vous est inconnu, veuillez informer l'expéditeur par courrier électronique immédiatement et détruire ce message et toute copie de celui-ci. Merci pour votre collaboration.



 Merci de penser à l'environnement avant d'imprimer ce courriel / Thank you for thinking of the environment before printing this email

[Quoted text hidden]



[Licensing] RE: 2BE-NTI0507 Inspection of July 12, 2014

Eva Paul <Eva.Paul@aandc-aadnc.gc.ca>
To: "Ene, Cynthia" <cynthia.ene@nwb-oen.ca>
Cc: "Department, Licensing" <licensing@nwb-oen.ca>

Mon, Aug 24, 2015 at 12:22 PM

Hi Cynthia and nice to make your acquaintance!

I did a quick review of the file, here's my understanding: The collars Mike refers to are of drilling carried out by Cominco prior to Strongbow's tenure. I don't know whether the Cominco drilling was licenced by the NWB, or when it occurred. From what I can gather, the NTI licence was a new licence, not an assignment, and no previous projects are mentioned in the Decision associated with NWB2NTI0305. Therefore, I do not see any legal obligation to Strongbow to remove Cominco's drill collars.

Based on the information provided to me, Strongbow conducted no drilling of their own.

As we discussed on the phone (and as per the attached report), Strongbow's obligation rests in restoring the location of the 2005 fly camp to a pre-disturbed state. However, if Strongbow felt compelled to leave the area better off than they found it and chose to cut the drill collars, then Nunavut would be a little better off, but they are not obliged.

Hope this helps!

Eva

Eva Paul

Water Resources Officer | Agent des ressources en eau
Aboriginal Affairs and Northern Development Canada | Affaires autochtones et Développement du Nord Canada
Nunavut Regional Office | Bureau régional du Nunavut
Building 969, PO Box 2200 | Édifice 969, CP 2200
Iqaluit, NU X0A 0H0

Phone | Tél. : 867-975-4548
Cell | Mobile: 867-222-6490
Fax | Téléc. : 867-979-6445
Eva.Paul@aandc-aadnc.gc.ca

>>> Cynthia Ene <cynthia.ene@nwb-oen.ca> 8/24/2015 1:29 PM >>>

[Quoted text hidden]



IQALUIT-#873095-v1-2BE-NTI0507_INSPECTION_OF_JULY_12_2014_PDF.PDF
1182K