



WATER LICENCE INSPECTION FORM

☒ Original  
☐ Follow-Up Report

Licensee		Licensee Representative	
Diamondex Resources Ltd.		-	
Licence No. / Expiry		Representative's Title	
2BE-TIM0813		-	
Land / Other Authorizations		Land / Other Authorizations	
Date of Inspection		Inspector	
20/07/2014		Eva Paul	
Activities Inspected			
<input type="checkbox"/> Camp	<input type="checkbox"/> Drilling	<input type="checkbox"/> Mining	<input type="checkbox"/> Construction
<input type="checkbox"/> Roads/Hauling	<input checked="" type="checkbox"/> Other: Till Sampling	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Fuel Storage
<input type="checkbox"/> Other:			

Conditions:		A - Acceptable	C - Concern	U - Unacceptable	NA – Not Applicable	NI – Not Inspected					
Water Use		Condition	Comment	Site Conditions		Condition	Comment	Haz/Mat Management		Condition	Comment
Intake/Screen	NA			Water Management Structures		NA		Storage		NA	
Flow Measure. Device	NA			Culverts / Bridges		NA		Spills		NA	
Source:	NA			Drainage		NA		Spill Plan		NA	
Water Use:	NA			Erosion / Sediment		NA					
Recirculation ( y /n)	NA			Mitigation Measures		NA		Administrative			
				Reclamation Activities		NA		Records		A	
				Materials Storage		NA		Reports		U	
Waste Disposal				Signage		NA		Plans		U	
Waste Water	A							Notifications		A	
Solid Waste	A			Monitoring				Other			
Hazardous Waste	A			Sample Collection / Analysis		NA					
*The number in the comments field will correspond with specific comments provided below.											
Samples taken by Inspector:				Location(s):							
<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No											

SECTION 1	<input checked="" type="checkbox"/> Comments (s.1)	<input checked="" type="checkbox"/> Non-Compliance with Act or Licence (s.2)	<input checked="" type="checkbox"/> Action Required (s.3)
<p>On July 20, 2014 I inspected the project area associated with this water licence. To my understanding, no work was done during the tenure of this licence; the last work was a till sampling program in 2006 under 2BE-TIM0608.</p> <p>As no camp was established under this licence and no drilling occurred, the till sampling was the activity inspected, by following the transects where till samples were taken. The area was left in an acceptable state.</p> <p>A review of the NWB public registry indicates that on August 23, 2013 the NWB requested that Diamondex provide three documents, that do not appear to have yet been submitted:</p> <ul style="list-style-type: none"><li>• 2012 Annual Report, required under Part B, Item 2, of the Licence’ terms and conditions;</li><li>• Addendum to the Spill Contingency Plan dated 2008, required under Part H, Item 2 of the Licence’ terms and conditions; and</li><li>• Abandonment and Restoration Plan, required under Part I, Item 1, of the Licence’ terms and conditions.</li></ul>			
SECTION 2	<input type="checkbox"/> Comments	<input checked="" type="checkbox"/> Non-Compliance with Act or Licence	<input type="checkbox"/> Action Required
<p>Part B Item 2: Failure to submit a 2012 Annual Report.</p> <p>Part H Item 2: Failure to submit an addendum to the Spill Contingency Plan.</p> <p>Part I Item 1: Failure to submit an Abandonment and Restoration Plan.</p>			
SECTION 3	<input type="checkbox"/> Comments	<input type="checkbox"/> Non-Compliance with Act or Licence	<input checked="" type="checkbox"/> Action Required
<p>Submission of the above-mentioned outstanding requirements by March 31. 2015.</p> <p>No further inspection of this project is required. When the NWB is satisfied that the Licensee has fulfilled its administrative requirements, this licence may be cancelled.</p>			

Licensee or Representative	Inspector's Name
	Eva Paul
Signature	Signature
	Sent electronically
Date	Date



27/10/2014

APPENDICES:

☐

Inspection Photos

☐

Sample Results

☐

Other:

\_\_\_\_\_

Office Use Only:

Follow-up report to be issued by Inspector

☐

Yes

☐

No

CC:

Phyllis Beaulieu, Manager of Licensing, NWB  
Erik Allain, Manager of Field Operations, AANDC  
Baba Pedersen, Resource Management Officer, Kitikmeot Region, AANDC