



## CORRECTION FROM THE AANDC INSPECTION JUNE 9<sup>TH</sup> 2015

Culvert 22:

These first 6 pictures show the water washing out across the road, the erosion it has caused, the amount of water that had been trapped due to the culverts being frozen, the steamer thawing out the pipe and the water flow when they both were operational.





#### Culvert 26:

These four pictures show the water washing out the road, the pooling of water and the effects after the pipes were thawed. The pictures were taken 14 hours apart.







We will have to look into the erosion in B-11. As mentioned in my last report, I believe these are natural drainage trenches. They were filled and compacted last year but have eroded again this year. The large sink hole will get filled when the surface dries out and we can get equipment in there. Until then, we will continue to monitor and document any changes that will arise.

There will be a report completed as asked from the GN for the freshet season, each week and sent to the Environment department.

Report done by : Philip Roy