



95 Wellington Street
Suite 1010
Toronto, Ontario
M5J 2N7
416-628-0216

Sent by Email

August 12, 2019

Candice Pederson – candice.pederson@canada.ca
Resource Management Officer
Crown-Indigenous Relations and Northern Affairs Canada
PO Box 2200
Iqaluit, NU
X0A 0H0

**Re: TMAC Response to CIRNAC Inspection Report Doris-Madrid Project
2AM-DOH1335 May 7-8, 2019**

Dear Mrs. Pederson,

TMAC Resources Inc. (TMAC) is providing this letter in response to action items identified in the 2AM-DOH1335 Water Licence Inspection Report provided by Crown-Indigenous Relations and Northern Affairs Canada (CIRNAC) on May 7-8, 2019. Action items and TMAC's response are detailed below:

- A. The inspector noted multiple snow piles within the Single Tank Farm at Roberts Bay.

Action Required: Inspector wants TMAC Resources to stop pushing snow into the berm at the Bulk Fuel Storage at the Single Tanks Farm.

TMAC Response: TMAC would like to clarify that snow is not pushed into any of the secondary containment berms on site. Snow within the secondary containment berms are routinely consolidated into piles to be removed from the secondary containment berms in order to maintain a 110% volumetric storage capacity of the fuel tank in the event of a tank failure.

Should you have any further questions please feel free to contact me at enviro@tmacresources.com.

Sincerely,



Kyle Conway
Environmental Supervisor
TMAC Resources Inc.

Cc:
Nunavut Water Board
Oliver Curran, Vice President - Environmental Affairs, TMAC
Dan Gagnon, Mine General Manager, TMAC