

Jerry,

Following up on our discussion earlier today, I can confirm my observations made this last fall (August/September 2010), when the fill at the landfarm pad was placed. The fill is consisting of mixed ROQ containing large oversize boulders covered with some better grade rock. I may be able to send you some photos showing the quality of the fill when I get back to my office in Vancouver.

Regards,

Iozsef Miskolczi

Consultant



SRK Consulting (Canada) Inc.

22nd Floor, 1066 West Hastings Street, Vancouver, BC, V6E 3X2, Canada

Tel: +1-604-681-4196; **Fax:** +1-604-687-5532

Mobile: +1-604-250-1653; **Direct:** +1-778-785-8460

Email: imiskolczi@srk.com;

www.srk.com

This transmission is intended for the sole use of the addressee, and may contain information that by its privileged and confidential nature is exempt from disclosure under applicable law. You are hereby notified that any dissemination, distribution or duplication of this transmission by someone other than the intended recipient or its designated agent is strictly prohibited. If you have received this transmission in error, please notify the sender immediately by replying to this transmission, or by collect call to the above phone number.

Please consider the environment before printing this e-mail.