Head Office - pstrand@Shearminerals.com

The Follow-Up Report includes:

- Summary of the spill incident
- Clean up actions
- Disposal
- Investigation and mitigation measures developed
- Photos

LEGEND

NOTES

CLIENT **SHEAR** AMONDS LTD. CONTINGENCY MANAGEMENT PLAN **JERICHO DIAMOND MINE, NUNAVUT**


Spill Response Reporting Flowsheet



PROJECT NO. DWN CKD APVD REV E14101118 CLS JΡ 0 OFFICE DATE EBA-EDM February 2011

Figure 5

Q:/Edmonton/Drafting/DIVISIONS2007/E141/E14101118/Contingency Management plan/Corel/E14101118_Figure 5.cd




ISSUED FOR USE A TETRATECH COMPANY


STATUS

SHEAR DIAMONDS LTD.

Ethylene Glycol Spill Response Flowsheet

PROJECT NO. DWN CKD APVD REV E14101118 CLS JP OFFICE EBA-EDM





STATUS

FOR INTERNAL USE ONLY

DWN CKD APVD REV

Figure 9

CLS WL

February 2011

DATE

PROJECT NO.

E14101118

EBA-EDM

OFFICE

A TETRATECH COMPANY

Q:/Edmonton/Drafting/DIVISIONS2007/E141/E14101118/Contingency Manager

STATUS ISSUED FOR USE

SHEAR DIAMONDS LTD.

JERICHO DIAMOND MINE, NUNAVUT

Hydrochloric Acid Spill Response Flowsheet



PROJECT NO. E14101118	DWN CLS		APVD	REV
OFFICE EBA-EDM	DATE February 2011			

Figure 10

