

To: Nunavut Water Board	Date: June 30, 2011
From: Shear Diamonds Ltd.	cc:
Ref: Jericho Diamond Mine: 2AM-JER0410	

2AM-JER Renewal Application Technical Meeting June 20-21, 2011

List of Commitments: Schedule of Monitoring Activities

July 2011

- Discharge from PKCA (June –October)
- Annual Geotechnical Inspection (July 11 to July 16)
- Annual Seepage Survey (dependent on presence of seepage): July 17 to July 21
- Assess fish habitat compensation measures - both constructed and outstanding: July 18 - July 22
- Pit Dewatering commencement (start date is dependent on approval)
- Training on hydrocarbon remediation skid and incineration management (July 6 – 11 tentative depending on shipment of unit to site from YK)

August 2011

- AEMP (July 28-August 9th)
- Annual Seepage Survey (if not present in July)
- Hydrocarbon Contaminated Soil Delineation for Landfarm Sizing