



NT-NU SPILL REPORT

OIL, GASOLINE, CHEMICALS AND OTHER HAZARDOUS MATERIALS

NT-NU 24-HOUR SPILL REPORT LINE

TEL: (867) 920-8130

FAX: (867) 873-6924

EMAIL: spills@gov.nt.ca

REPORT LINE USE ONLY

A	REPORT DATE: MONTH – DAY – YEAR 04/26/12	REPORT TIME 3:45 p.m	<input checked="" type="checkbox"/> ORIGINAL SPILL REPORT, OR <input type="checkbox"/> UPDATE # _____ TO THE ORIGINAL SPILL REPORT		REPORT NUMBER _____
B	OCCURRENCE DATE: MONTH – DAY – YEAR 04/24/12	OCCURRENCE TIME 4:00 p.m			
C	LAND USE PERMIT NUMBER (IF APPLICABLE) KTL 311 C015	WATER LICENCE NUMBER (IF APPLICABLE) 2AM-JER1119			
D	GEOGRAPHIC PLACE NAME OR DISTANCE AND DIRECTION FROM NAMED LOCATION Jericho Mine Site		REGION <input type="checkbox"/> NWT <input checked="" type="checkbox"/> NUNAVUT <input type="checkbox"/> ADJACENT JURISDICTION OR OCEAN		
E	LATITUDE DEGREES 66 MINUTES 01 SECONDS 00		LONGITUDE DEGREES 111 MINUTES 27 SECONDS 00		
F	RESPONSIBLE PARTY OR VESSEL NAME Shear Diamonds	RESPONSIBLE PARTY ADDRESS OR OFFICE LOCATION Suite 220, 6 Adelaide St. Toronto ON. M5C 1H6			
G	ANY CONTRACTOR INVOLVED No	CONTRACTOR ADDRESS OR OFFICE LOCATION N/A			
H	PRODUCT SPILLED Diesel (hydrocarbon)	QUANTITY IN LITRES, KILOGRAMS OR CUBIC METRES ~400L	U.N. NUMBER 1202		
	SECOND PRODUCT SPILLED (IF APPLICABLE) None	QUANTITY IN LITRES, KILOGRAMS OR CUBIC METRES N/A	U.N. NUMBER N/A		
I	SPILL SOURCE Generator Fuel Tank	SPILL CAUSE Fuel solenoid left on manual	AREA OF CONTAMINATION IN SQUARE METRES		
J	FACTORS AFFECTING SPILL OR RECOVERY Solid ice with little vehicle access	DESCRIBE ANY ASSISTANCE REQUIRED None	HAZARDS TO PERSONS, PROPERTY OR ENVIRONMENT N/A		
K	ADDITIONAL INFORMATION, COMMENTS, ACTIONS PROPOSED OR TAKEN TO CONTAIN, RECOVER OR DISPOSE OF SPILLED PRODUCT AND CONTAMINATED MATERIALS -While filling the day tank for generator 3, the fuel valve was left on manual overnight. -Fuel eventually overfilled the generator fuel tank and spilled into the building -leak eventually made its way outside from the Western Corner. -Valve was discovered and closed at 4:30 a.m on April 25th -All the fuel outside pooled into two pockets which were bailed to get the majority of the spill. -Small sump was created to pool the diesel that went under the generator building -Absorbent pads were used to soak up the remainder of the standing diesel. -All staff has been advised to never leave that pump on manual unattended again.				
L	REPORTED TO SPILL LINE BY Wes Atchison	POSITION Environment Tech	EMPLOYER Shear Diamonds	LOCATION CALLING FROM Jericho Mine Site	TELEPHONE 778-372-2723
M	ANY ALTERNATE CONTACT Chris Morton	POSITION VP Operations	EMPLOYER Shear Diamonds	ALTERNATE CONTACT Jericho Mine Site	ALTERNATE TELEPHONE 778-372-2726
REPORT LINE USE ONLY					
N	RECEIVED AT SPILL LINE BY	POSITION STATION OPERATOR	EMPLOYER	LOCATION CALLED YELLOWKNIFE, NT	REPORT LINE NUMBER (867) 920-8130
LEAD AGENCY <input type="checkbox"/> EC <input type="checkbox"/> CCG <input type="checkbox"/> GNWT <input type="checkbox"/> GN <input type="checkbox"/> ILA <input type="checkbox"/> INAC <input type="checkbox"/> NEB <input type="checkbox"/> TC			SIGNIFICANCE <input type="checkbox"/> MINOR <input type="checkbox"/> MAJOR <input type="checkbox"/> UNKNOWN		FILE STATUS <input type="checkbox"/> OPEN <input type="checkbox"/> CLOSED
AGENCY		CONTACT NAME	CONTACT TIME	REMARKS	
LEAD AGENCY					
FIRST SUPPORT AGENCY					
SECOND SUPPORT AGENCY					
THIRD SUPPORT AGENCY					