



Canada

NT-NU SPILL REPORT

OIL, GASOLINE, CHEMICALS AND OTHER HAZARDOUS MATERIALS

NT-NU 24-HOUR SPILL REPORT LINE

TEL: (867) 920-8130

FAX: (867) 873-6924

EMAIL: spills@gov.nt.ca

REPORT LINE USE ONLY

A	REPORT DATE: MONTH – DAY – YEAR May 2, 2012	REPORT TIME 7:05am	<input checked="" type="checkbox"/> ORIGINAL SPILL REPORT, OR <input type="checkbox"/> UPDATE # _____ TO THE ORIGINAL SPILL REPORT		REPORT NUMBER _____
B	OCCURRENCE DATE: MONTH – DAY – YEAR May 1, 2012	OCCURRENCE TIME 5:10pm			
C	LAND USE PERMIT NUMBER (IF APPLICABLE) KTL 311 C015	WATER LICENCE NUMBER (IF APPLICABLE) 2AM-JER1119			
D	GEOGRAPHIC PLACE NAME OR DISTANCE AND DIRECTION FROM NAMED LOCATION Jericho Mine Site		REGION <input type="checkbox"/> NWT <input checked="" type="checkbox"/> NUNAVUT <input type="checkbox"/> ADJACENT JURISDICTION OR OCEAN		
E	LATITUDE DEGREES 66 MINUTES 01 SECONDS 00		LONGITUDE DEGREES 111 MINUTES 27 SECONDS 00		
F	RESPONSIBLE PARTY OR VESSEL NAME Shear Diamonds	RESPONSIBLE PARTY ADDRESS OR OFFICE LOCATION Suite 220, 6 Adelaide St. E. Toronto, ON M5C 1H6			
G	ANY CONTRACTOR INVOLVED no	CONTRACTOR ADDRESS OR OFFICE LOCATION n/a			
H	PRODUCT SPILLED Hydraulic Fluid	QUANTITY IN LITRES, KILOGRAMS OR CUBIC METRES 1	U.N. NUMBER 3082		
	SECOND PRODUCT SPILLED (IF APPLICABLE) none	QUANTITY IN LITRES, KILOGRAMS OR CUBIC METRES n/a	U.N. NUMBER n/a		
I	SPILL SOURCE bobcat	SPILL CAUSE equipment malfunction	AREA OF CONTAMINATION IN SQUARE METRES 0.5		
J	FACTORS AFFECTING SPILL OR RECOVERY none	DESCRIBE ANY ASSISTANCE REQUIRED n/a	HAZARDS TO PERSONS, PROPERTY OR ENVIRONMENT n/a		
K	ADDITIONAL INFORMATION, COMMENTS, ACTIONS PROPOSED OR TAKEN TO CONTAIN, RECOVER OR DISPOSE OF SPILLED PRODUCT AND CONTAMINATED MATERIALS -this spill is being reported as required under the conditions in Part H, Section 8(b) of Shear Diamonds Water Board (NWB) Licence 2AM-JER1119 pursuant to the Nunavut waters and Nunavut Surface Rights Tribunal Act and as required by the Government of Nunavut's Environmental Protection Act paragraph 5.1(a) -this incident occurred around 5:15pm, approximately 500m northwest of Ash Lake -while operating a bobcat near the south wall of the processing plant the operator noticed a small trail of fluid being left behind the bobcat -the operator immediately brought the bobcat indoors and called the mechanic to make repairs -the contaminated gravel was shovelled up into a pail and brought to the west cell of the hazardous waste transfer area				
L	REPORTED TO SPILL LINE BY Wes Atchison	POSITION Environmental Tech	EMPLOYER Shear Diamonds	LOCATION CALLING FROM Jericho Mine Site	TELEPHONE 778-372-2723
M	ANY ALTERNATE CONTACT Chris Morton	POSITION VP Operations	EMPLOYER Shear Diamonds	ALTERNATE CONTACT Jericho Mine Site	ALTERNATE TELEPHONE 778-372-2726
REPORT LINE USE ONLY					
N	RECEIVED AT SPILL LINE BY	POSITION STATION OPERATOR	EMPLOYER	LOCATION CALLED YELLOWKNIFE, NT	REPORT LINE NUMBER (867) 920-8130
LEAD AGENCY <input type="checkbox"/> EC <input type="checkbox"/> CCG <input type="checkbox"/> GNWT <input type="checkbox"/> GN <input type="checkbox"/> ILA <input type="checkbox"/> INAC <input type="checkbox"/> NEB <input type="checkbox"/> TC			SIGNIFICANCE <input type="checkbox"/> MINOR <input type="checkbox"/> MAJOR <input type="checkbox"/> UNKNOWN		FILE STATUS <input type="checkbox"/> OPEN <input type="checkbox"/> CLOSED
AGENCY		CONTACT NAME	CONTACT TIME	REMARKS	
LEAD AGENCY					
FIRST SUPPORT AGENCY					
SECOND SUPPORT AGENCY					
THIRD SUPPORT AGENCY					