



Canada

NT-NU SPILL REPORT

OIL, GASOLINE, CHEMICALS AND OTHER HAZARDOUS MATERIALS

NT-NU 24-HOUR SPILL REPORT LINE

TEL: (867) 920-8130

FAX: (867) 873-6924

EMAIL: spills@gov.nt.ca

REPORT LINE USE ONLY

A	REPORT DATE: MONTH – DAY – YEAR 05/12/2012	REPORT TIME 17:57	<input type="checkbox"/> ORIGINAL SPILL REPORT, OR		REPORT NUMBER -
B	OCCURRENCE DATE: MONTH – DAY – YEAR 05/12/2012	OCCURRENCE TIME 01:00	<input type="checkbox"/> UPDATE # TO THE ORIGINAL SPILL REPORT		
C	LAND USE PERMIT NUMBER (IF APPLICABLE)		WATER LICENCE NUMBER (IF APPLICABLE) 2AM-JER1119		
D	GEOGRAPHIC PLACE NAME OR DISTANCE AND DIRECTION FROM THE NAMED LOCATION Jericho Mine Site			REGION <input type="checkbox"/> NWT <input checked="" type="checkbox"/> NUNAVUT <input type="checkbox"/> ADJACENT JURISDICTION OR	
E	LATITUDE DEGREES 66 MINUTES 01 SECONDS 00		LONGITUDE DEGREES 111 MINUTES 27 SECONDS 00		
F	RESPONSIBLE PARTY OR VESSEL NAME Fuel Truck	RESPONSIBLE PARTY ADDRESS OR OFFICE LOCATION Jericho Diamond Mine			
G	ANY CONTRACTOR INVOLVED N/A	CONTRACTOR ADDRESS OR OFFICE LOCATION N/A			
H	PRODUCT SPILLED Diesel	QUANTITY IN LITRES, KILOGRAMS OR CUBIC METRES 5 - 10 litres		U.N. NUMBER N/A	
	SECOND PRODUCT SPILLED (IF APPLICABLE) N/A	QUANTITY IN LITRES, KILOGRAMS OR CUBIC METRES N/A		U.N. NUMBER N/A	
I	SPILL SOURCE Overflow on the Tank of the Fuel Truck	SPILL CAUSE Bumpy road caused spill from		AREA OF CONTAMINATION IN SQUARE METRES 0.5m X 0.5m	
J	FACTORS AFFECTING SPILL OR RECOVERY Hard ground, still frozen	DESCRIBE ANY ASSISTANCE REQUIRED None		HAZARDS TO PERSONS, PROPERTY OR ENVIRONMENT N/A	
K	ADDITIONAL INFORMATION, COMMENTS, ACTIONS PROPOSED OR TAKEN TO CONTAIN, RECOVER OR DISPOSE OF SPILLED PRODUCT AND CONTAMINATED MATERIALS This spill is being reported in accordance with the conditions outlined in Part H, Section 8(b) of Shear Diamonds Water Board (NWB) Licence 2AM-JER1119 pursuant to the Nunavut Waters and Nunavut Surface Rights Tribunal Act and as required by the Government of Nunavut's Environmental Protection Act paragraph 5.1(a). The material that was scraped up by the loader was mistakenly taken to the Phase II Fuel Farm. This is not permitted. The snow on the road to the Hazardous Waste Transfer Area was cleared today. The contaminated material will be placed in drums and taken to the HWTA for storage until it is backhauled from site for appropriate storage.				
L	REPORTED TO SPILL LINE BY Allison Armstrong	POSITION Environment	EMPLOYER Shear Diamodns	LOCATION CALLING FROM Jericho	TELEPHONE 778-372-2752
M	ANY ALTERNATE CONTACT Steve Willcott	POSITION General Manager	EMPLOYER Shear Diamonds	ALTERNATE CONTACT LOCATION Jericho	ALTERNATE TELEPHONE 778-372-2753

REPORT LINE USE ONLY

N	RECEIVED AT SPILL LINE BY	POSITION Station operator	EMPLOYER	LOCATION CALLED Yellowknife, NT	REPORT LINE NUMBER (867) 920-8130
LEAD AGENCY <input type="checkbox"/> EC <input type="checkbox"/> CCG <input type="checkbox"/> GNWT <input type="checkbox"/> GN <input type="checkbox"/> ILA <input type="checkbox"/> INAC <input type="checkbox"/> NEB <input type="checkbox"/> TC			SIGNIFICANCE <input type="checkbox"/> MINOR <input type="checkbox"/> MAJOR <input type="checkbox"/> UNKNOWN		FILE STATUS <input type="checkbox"/> OPEN <input type="checkbox"/> CLOSED
AGENCY		CONTACT NAME	CONTACT TIME	REMARKS	
LEAD AGENCY					
FIRST SUPPORT AGENCY					
SECOND SUPPORT AGENCY					
THIRD SUPPORT AGENCY					